

PRESTIGE APPRAISER SERVICES

VEHICLE INSPECTION REPORT

To: Mr Teo Hoon Seng Timonthy
c/o Blk 12 Sin Ming Industrial Estate
#01-71
Singapore 575656

Date : 17th April 2017
Our Ref : PS/004/04/17
Policy No :
Sum Insured :
Excess : T/P Claim

Assigned By : Mr Teo Hoon Seng Timonthy
Assignment Date : 10th April 2017
Accident Date : 05th April 2017
Inspection Date : 10th April 2017
Workshop Name : Kum Chew Motor Workshop
Survey Conducted At : Blk 12 Sin Ming Industrial Estate
#01-71
Singapore 575656

PARTICULARS OF VEHICLE

Registration No	: SGV 1793 P	Mileage	: 65153km
Make/Model	: Toyota Vios	Engine No	: HIDDEN
Type Of Body	: Motorcar	Chassis No	: MR053HY9305008849
Year Of Manu./Regn.	: 2007	Passenger Cap.	: 4 Passengers
Colour	: Met. Blue	Others	: -

CONDITION OF TYRES

R/H SIDE

Front Tyre : 6mm 185/60R15 Michelin
Rear Tyre : 6mm 185/60R15 Michelin

L/H SIDE

6mm 185/60R15 Michelin
6mm 185/60R15 Michelin

The above represent the estimated remaining life of the tyre treads.

PRE-ACCIDENT CONDITION (Static tests only)

Handbrake	: Serviceable	Body Work	: Good
Footbrake	: Serviceable	Paint Work	: Good
Steering	: Serviceable	Others	: -

POINT OF IMPACT

The vehicle sustained an impact on the front portion.

GENERAL DESCRIPTION OF DAMAGES

The front support panel, bumper assy, fenders, bonnet, radiator, aircon condenser were dented/distorted.

For details of damages please refer to schedule attached.

REMARKS :

This survey was conducted strictly without prejudice.

PRESTIGE APPRAISER SERVICES

Vehicle No : **SGV 1793 P**

Our Ref :

PS/004/04/17

Qty	Descriptions	Conditions	Repairer's Est.	Our Revised.
	<u>LIST ITEMS</u>			
1	front bumper /CRU	dented	\$ 431.90	\$ 431.90 ✓
1	front bumper reinforcement /BT	dented	382.70	382.70 ✓
2	front bumper bracket XSUC	dented	112.60	112.60 X
2	front bumper side retainer /BR	dented	124.00	124.00 ✓
8	front bumper clip /Nec	necessary	40.00	40.00 ✓
1	front bumper grille /CRU	dented	79.60	79.60 ✓
1	front bumper inner top garnish /CRU	dented	99.60	99.60 ✓
1	R/H front bumper lower dust cover /CRU	torn	93.60	93.60 ✓
1	L/H front bumper lower dust cover /CRU	torn	155.00	155.00 93.60
2	fog lamp XSUC	holder cracked	596.20	596.20 X
2/1	fog lamp garnish /CRU	dented/cracked	98.80	98.80 49.4
1	front grille /CRU	dented/cracked	241.20	241.20 ✓
1	front grille emblem /Nec	necessary	50.80	50.80 ✓
4	front grille clip XSUC	necessary	24.00	24.00 X
1	R/H headlamp /CRU	holder cracked	602.80	602.80 ✓
1	L/H headlamp /CRU	holder cracked	602.80	602.80 ✓
2	headlamp bracket XSUC	dented	44.40	44.40 X
2	headlamp clip XSUC	necessary	9.60	9.60 X
1	front support panel /DD	dented	929.90	929.90 699.90
1	front support panel side garnish XSUC	dented	88.00	88.00 X
1	bonnet XR	dented/distorted	549.80	549.80 X
2	bonnet hinge XR	dented - repair	104.40	-
1	bonnet lock /Jam	dented	90.70	90.70 ✓
1	R/H front fender XR	dented - repair	559.50	-
1	R/H front fender dust cover XSUC	dented/distorted	168.10	168.10 X
1	L/H front fender XR	dented - repair	559.50	-
1	L/H front fender dust cover XSUC	dented/cut	168.20	168.20 X
1	radiator assy /CRU	dented/warped	1,835.90	1,835.90 1,750
1	radiator fan motor /DD	damaged	466.20	466.20 210.20
1	radiator fan blade /CRU	cut	201.60	201.60 ✓
1	radiator fan cowling /CRU	broken	246.90	246.90 ✓
1	aircon condenser /CRU	dented/warped	1,133.80	1,133.80 ✓
1	horn /CRU	dented	111.60	111.60 ✓
1	washer tank /CRU	dented/cracked	121.10	121.10 ✓
1	front lower panel /DD	dented	79.60	79.60 ✓
			11,204.40	9,981.00 7,532.40
		Less 25%	-	2,495.25 -25%
			\$ 11,204.40	\$ 7,485.75 5,653.05
	<u>S/NETT ITEM</u>			
1	front number plate	dented	60.00	50.00 ✓
		Balance c/f	\$ 11,264.40	\$ 7,535.75 50

PRESTIGE APPRAISER SERVICES

Vehicle No : SGV 1793 P

Our Ref : PS/004/04/17

Qty	Descriptions	Conditions	Repairer's Est.	Our Revised.
		Balance b/d	\$ 11,264.40	\$ 7,535.75

Labour Charges & Misc

To dismantle & replace damaged parts, panel beat where necessary.

1,480.00 1,200.00 *800*

To putty, apply primer & spray-paint on the affected portion.

1,300.00 1,100.00 *900*

To apply rust-proofing on repaired, replaced panel.

140.00 100.00 *30*

To remove/renew aircon condenser & refill gas.

150.00 120.00 *100*

To remove/renew radiator assy.

60.00 40.00 ✓

Towing charges.

80.00 60.00 ✓

To check wiring functions.

50.00 30.00 ✓
\$ 14,524.40 \$ 10,185.75 *1960*

Repair day - 5 days

5,653.05
50
1,960
7,663.05
- 20%
6,130.44

Note: The repairer has agreed to undertake the repairs at our adjusted amount of **\$8,100.00 lump sum** corresponding to supply of parts, labour and spray-painting charges.

Under normal circumstances, the estimated repair period would be **TEN (10)** days.

Pursuant to your instruction we have **not** authorised repairs on your behalf.

4/5
\$6,100
5 days

PRESTIGE APPRAISER SERVICES

[Signature]
LOUIS SCNG CAE AMIMI (UK)
Licensed Appraiser
Dip. MTM. Automotive Engineer