

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG20011156/ATD3E2

Date: 02/02/2021

REFERENCE

Insured/Claimant:	PREMIUM LEASING PTE LTD	Policy No:	0999993757	
Date of Loss:	24/09/2020	Nature of Claim:	OD	Claim No: 3645523628SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLJ7961K	Engine No:	CYR021841
Make & Model:	AUDI Q7, 2.0 TFSI QU (A)	Chassis No:	WAUZZZ4MXHD015797
Reg. Date:	27/12/2016 (Man. Year: 2016)	Odometer:	27863 km
Colour:	Black		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$150,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	255/55R19	Rear Tyre Size:	255/55R19
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,521.00	3,329.20	8,191.80	71.10
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,032.00	2,552.00	1,480.00	36.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,553.00	5,881.20	9,671.80	62.19
- Excess (S\$)	1,600.00	1,600.00	0.00	0.00
(S\$)	13,953.00	4,281.20	9,671.80	69.32
+ GST 7.00/7.00% (S\$)	976.71	299.68	677.03	69.32
Nett Amount (S\$)	14,929.71	4,580.88	10,348.83	69.32

INSPECTION

Date of Assignment:	15/10/2020		
Date Inspected:	14/10/2020	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	3.0 days		

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR UPPER BUMPER	Repair	1,215.00 FS	*- FS
2	1		*REAR LOWER BUMPER	Deformed	1,815.00 FS	*1,452.00 FS
3	1		*REAR BUMPER FIXING PARTS	Not Necessary	205.00 FS	*- FS
4	1		*REAR BUMPER SPOILER	Cut	1,247.00 FS	*997.60 FS
5	1		*REAR BUMPER SPOILER TRIM	Not Necessary	105.00 FS	*- FS
6	1		*BOOT LID CONTROL UNIT	Not Necessary	379.00 FS	*- FS
7	1		*REAR BUMPER CARRIER	Not Necessary	1,341.00 FS	*- FS
8	2		*REAR BUMPER CARRIER SEAL LH/RH	Not Necessary	28.00 FS	*- FS
9	1		*REAR BUMPER HOLDING STRAP	Not Necessary	180.00 FS	*- FS
10	1		*REAR BUMPER GUIDE SECTION-CENTRE	Not Necessary	140.00 FS	*- FS
11	2		*REAR PARKING AID SENSOR-INNER/OUTER	Not Necessary	484.00 FS	*- FS
12	4		*REAR PARKING AID SEAL RING	Not Necessary	14.00 FS	*- FS
13	1		*TAIL LIGHT-RH	Cracked	355.00 FS	*283.60 FS
14	1		*EXHAUST TAIL PIPE TRIM-RH	Not Necessary	325.00 FS	*- FS
15	1		*REAR SILENCER	Not Necessary	2,634.00 FS	*- FS
16	2		*REAR WHEEL COVER-LH/RH	Necessary	746.00 FS	*596.00 FS
17	1		*REAR SILENCER DUAL CLIP	Not Necessary	58.00 FS	*- FS
18	1		*SUNDRIES	Not Necessary	250.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)11,521.003,329.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR.CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE	New	360.00	360.00
2	TO DISMANTLE AND RENEW REAR BUMPER.RE-ORGANISE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	1,000.00	500.00
3	TO RESPRAY REAR UPPER BUMPER,REAR LOWER BUMPER,AND BOTH REAR WHEEL ARCH TRIMS	New	2,000.00	1,500.00
4	TO RENEW EXHAUST SILENCER AND ALIGN TO POSITION	New	480.00	0.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			4,032.00	2,552.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >