

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20011161/KGA3Q2
Date: 18/05/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800129289
Claimant Vehicle No :	SLV5642G	Insured Vehicle No :	SLC456K
Date of Loss:	13/10/2020	Nature of Claim:	TP
		Claim No:	4038634591SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLV5642G	Engine No:	L15Z15204885
Make & Model:	HONDA CITY, 1.5 SV CVT (A)	Chassis No:	MRHGM6660JT000277
Reg. Date:	02/01/2018 (Man. Year: 2017)	Odometer:	39150 km
Colour:	Metallic Grey		
Engine Capacity:	1497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	185/55 R16	Rear Tyre Size:	185/55 R16
Front Left Side:	Dunlop 7 mm	Rear Left Side:	Dunlop 7 mm
Front Right Side:	Dunlop 7 mm	Rear Right Side:	Dunlop 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,203.52	427.04	776.48	64.52
Miscellaneous Items	0.00	0.00	0.00	
Labour	960.00	550.00	410.00	42.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,163.52	977.04	1,186.48	54.84
+ GST 7.00/7.00% (S\$)	151.45	68.39	83.06	54.84

Nett Amount (S\$)	2,314.97	1,045.43	1,269.54	54.84
+ Car Rental (3.0 x S\$90.00/day + 7.00% GST) (S\$)		288.90		
+ Doc/Search Fee (S\$)		8.00		
Nett Liability (S\$)		1,342.33		

INSPECTION

Date of Assignment: 14/10/2020

Date Inspected: 14/10/2020

Estimated Period of Repair: 3.0 days

Inspected At:

Cheng Hoe Motor Pte Ltd (Yishun)
 Blk 1019 #01-374/382, Yishun Industrial Park A
 Singapore 768761

Adjuster: KENNETH KONG**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Buckled / Cracked	459.80 FL	*459.80 FL
2	1		*FRONT BUMPER REINFORCEMENT	Repair	265.60 FL	*- FL
3	2		*FRONT BUMPER SIDE RETAINERS	Distorted	27.20 FL	*27.20 FL
4	6		*FRONT BUMPER CLIPS	Necessary	23.40 FL	*23.40 FL
5	1		*FRONT GRILLE BASE	Serviceable	86.90 FL	*- FL
6	6		*FRONT GRILLE CLIPS	Necessary	23.40 FL	*23.40 FL
7	1		*LH HEADLAMP	Serviceable	618.10 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$)	1,504.40	533.80
- List Item Discount on L Items 20.00/20.00% (\$)	300.88	106.76
Total Parts (\$)	1,203.52	427.04

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REMOVE & REFIX FRT BUMPER ASSY ,GRILLE ,HEADLAMPS ,KNOCK & REPAIR FRT SUPPORT PANEL & REALIGN THE SAME	New	480.00	250.00
2	PUTTY & RESPRAY ON FRT BUMPER REINFORCEMENT ,SUPPORT PANEL	New	480.00	300.00
Gross Labour Cost (\$\$)			960.00	550.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >