

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/AIG20011172/KBA3Q2

**Date:** 22/02/2021

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100264857

**Claimant**  
**Vehicle No :** SFT1121B **Insured Vehicle No :** SFA8282Z

Date of Loss: 10/10/2020 Nature of Claim: TP Claim No: 2782267320SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SFT1121B**

Make & Model: LAND ROVER DISCOVERY SPORT, 2.0 D 7-SEATER (180PS) (A) Engine No: 170323W1000204DT

Reg. Date: 25/07/2017 (Man. Year: 2017) Chassis No: SALCA2AN5HH700425

Colour: Metallic Pearl White Odometer: 64293 km

Engine Capacity: 1999 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 235/55R19 Rear Tyre Size: 235/55R19

Front Left Side: Pirelli 8 mm Rear Left Side: Pirelli 8 mm

Front Right Side: Pirelli 8 mm Rear Right Side: Pirelli 8 mm

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                           | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|---|-------------------|-------------------|-------------------|---------------|
| Parts   | 13,675.20         | 9,082.48          | 4,592.72          | 33.58         |
| Miscellaneous Items                             | 0.00              | 0.00              | 0.00              |               |
| Labour  | 3,610.00          | 1,510.00          | 2,100.00          | 58.17         |
| Paintwork Labour                                | 0.00              | 0.00              | 0.00              |               |
| Towing  | 0.00              | 0.00              | 0.00              |               |
| <b>Gross Total (S\$)</b>                        | <b>17,285.20</b>  | <b>10,592.48</b>  | <b>6,692.72</b>   | <b>38.72</b>  |
| <b>+ GST 7.00/7.00% (S\$)</b>                   | <b>1,209.96</b>   | <b>741.47</b>     | <b>468.49</b>     | <b>38.72</b>  |
| <b>Nett Amount (S\$)</b>                        | <b>18,495.16</b>  | <b>11,333.95</b>  | <b>7,161.21</b>   | <b>38.72</b>  |
| <b>+ Car Rental (6.0 x S\$150.00/day) (S\$)</b> |                   | <b>900.00</b>     |                   |               |
| <b>Nett Liability (S\$)</b>                     |                   | <b>12,233.95</b>  |                   |               |

### INSPECTION

Date of Assignment: 14/10/2020

Date Inspected: 16/10/2020 Inspected At: Motor Edgevantage Pte Ltd (HQ)  
160 Sin Ming Drive, Sin Ming AutoCity  
#03-01/02  
Singapore 575722

Estimated Period of Repair: 5.0 days

**Adjuster:** KENNETH KONG

**Manager:** CHUA ZHEN LI

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

| No. | Qty | Part No. | Particulars  | Condition        | Repairer's | Amount       |
|-----|-----|----------|--|------------------|------------|--------------|
| 1   | 1   |          | *LR REAR BUMPER ASSEMBLY DS                        | Buckled / Dented | 1,774.40 F | *1,774.40 FL |
| 2   | 1   |          | *LR REAR BUMPER LOWER COVER DS                     | Missing          | 574.10 F   | *574.10 FL   |
| 3   | 1   |          | *LR REAR REINFORCEMENT BAR DS                      | Bent             | 625.60 F   | *625.60 FL   |
| 4   | 1   |          | *LR REAR BUMPER BRACKET MOUNTING RH DS             | Repair           | 124.60 F   | *- FL        |
| 5   | 1   |          | *LR REAR BUMPER BRACKET MOUNTING LH DS             | Repair           | 124.60 F   | *- FL        |
| 6   | 1   |          | *LR REAR BUMPER TOW HOOK COVER OPENING             | Missing          | 29.60 F    | *29.60 FL    |
| 7   | 1   |          | *LR TAILGATE ASSEMBLY DS                           | Bent             | 3,548.90 F | *3,447.60 FL |
| 8   | 1   |          | *LR TAILGATE MOULDING DS                           | Serviceable      | 1,355.20 F | *- FL        |
| 9   | 1   |          | *LR TAILGATE WINDSCREEN DS                         | Not Necessary    | 1,123.30 F | *- FL        |
| 10  | 1   |          | *LR WINDSCREEN GLASS ADHESIVE SEALANT              | Not Necessary    | 150.00 F   | *- FL        |
| 11  | 1   |          | *LR TAILGATE EMBLEM (DISCO)                        | Necessary        | 171.90 F   | *62.50 FL    |
| 12  | 1   |          | *LR TAILGATE EMBLEM (VERY)                         | Necessary        | 154.20 F   | *55.60 FL    |
| 13  | 1   |          | *LR TAILGATE EMBLEM (SPORT)                        | Necessary        | 180.40 F   | *85.60 FL    |
| 14  | 1   |          | *LR TAILGATE BADGE OVAL REAR RRS RRS3 (LAND ROVER) | Necessary        | 91.50 F    | *91.50 FL    |
| 15  | 1   |          | *LR TAILGATE BUMPER BRACKET RH                     | Repair           | 188.10 F   | *- FL        |
| 16  | 1   |          | *LR TAILGATE BUMPER BRACKET LH                     | Repair           | 188.10 F   | *- FL        |
| 17  | 2   |          | *LR PARKING AID RETAINER ASSEMBLY WITH SENSOR      | Scratched        | 778.00 F   | *504.60 FL   |
| 18  | 1   |          | *LR REAR EXHAUST MUFFLER LH                        | Dented           | 2,492.70 F | *2,309.41 FL |

F=Franchise part. L=ListItemDisc.

**Sub Total (\$\$)** **13,675.20** **9,560.51**  
**- List Item Discount on L Items 0.00/5.00% (\$\$)** **0.00** **478.03**

**Total Parts (\$\$)** **13,675.20** **9,082.48**

|   |
|---|
| Report was unsubmitted during this print-out. |
|---|

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                              | Particulars   | Lab.Type | Repairer's      | Amount          |
|---------------------------------|---|----------|-----------------|-----------------|
| <b><u>Labour Items</u></b>      |   |          |                 |                 |
| 1                               | TO REPLACE REAR BUMPER ,REAR BUMPER LOWER TOW EYE COVER ,REAR BUMPER REINFORCEMENT ,SIDE BRACKET REAR PARKING SENSOR ,REAR TAILGATE | New      | 1,200.00        | 600.00          |
| 2                               | TO PUTTY AND RESPRAY REAR BUMPER,REAR TAILGATE  | New      | 1,000.00        | 600.00          |
| 3                               | TO TRANSFER TAILGATE COMPONENTS PARTS   | New      | 200.00          | 80.00           |
| 4                               | TO REMOVE AND REPLACE REAR WINDSCREEN   | New      | 400.00          | 120.00          |
| 5                               | TO INSTALL REAR WINDSCREEN UV FILM  | New      | 180.00          | 0.00            |
| 6                               | TO REPLACE REAR EXHAUST MUFFLER LH SIDE   | New      | 350.00          | 80.00           |
| 7                               | TO CHECK WIRING INCLUDING ELECTRICAL MODULE   | New      | 200.00          | 30.00           |
| 8                               | WHEEL ALIGNMENT WITH ADJUSTMENT   | New      | 80.00           | 0.00            |
| <b>Gross Labour Cost (\$\$)</b> |   |          | <b>3,610.00</b> | <b>1,510.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >