

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG20011178/UVF3E2

Date: 11/11/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No: 1800051235
Claimant Vehicle No : JSE9098	Insured Vehicle No : SLZ707R
Date of Loss: 13/10/2020	Nature of Claim: TP Claim No: 0720026847SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	JSE9098		
Make & Model:	TOYOTA MARK X, 2.5 (A)	Engine No:	4GR0468541
Reg. Date:	10/11/2011 (Man. Year: 2008)	Chassis No:	GRX1203061249
Colour:	White	Odometer:	196806 km
Engine Capacity:	2499 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	265/30Z R19	Rear Tyre Size:	265/30Z R19
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,161.43	6,593.72	10,567.71	61.58
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,520.00	2,160.00	1,360.00	38.64
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	20,681.43	8,753.72	11,927.71	57.67
Approved Total (Overridden) (S\$)		7,000.00		
Nett Amount (S\$)	20,681.43	7,000.00	13,681.43	66.15

INSPECTION

Date of Assignment:	15/10/2020	
Date Inspected:	15/10/2020	Inspected At: VAC (Kaki Bukit) NO.1 KAKI BUKIT AVE 6 #02-11 SINGAPORE 417883
Estimated Period of Repair:	5.0 days	

Adjuster: MARCUS CHUA

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID	Badly Dented	1,275.00 FL	*1,275.00 FL
2	1		*BOOT LID LOGO	Necessary	68.50 FL	*68.50 FL
3	1		*BOOT LID MARK X EMBLEM	Necessary	68.60 FL	*68.60 FL
4	1		*BOOT LID X EMBLEM	Repeated	58.50 FL	*- FL
5	1		*BOOT LID TRD LIMITED EDITION EMBLEM	Necessary	68.60 FL	*68.60 FL
6	1		*BOOT LID LICENCE PLATE GARNISH	Cracked	281.95 FL	*281.95 FL
7	2		*REAR LICENCE PLATE LAMP	Not Necessary	116.40 FL	*- FL
8	1		*BOOT LID CHROME MOULDING UPPER	Not Necessary	97.20 FL	*- FL
9	1		*BOOT LID CHROME MOULDING LOWER	Not Necessary	72.90 FL	*- FL
10	1		*BOOT LID INNER LOCK	Twisted / Shorted	481.93 FL	*481.93 FL
11	1		*BOOT LID INNER TRIM	Not Necessary	341.66 FL	*- FL
12	10		*BOOT LID INNER TRIP CLIP	Not Necessary	55.00 FL	*- FL
13	1		*BOOT LID LOCK STRIKER	Not Necessary	76.85 FL	*- FL
14	1		*BOOT LID WEATHERSTRIP	Twisted	281.62 FL	*281.62 FL
15	2		*BOOT LID HINGE	Not Necessary	442.60 FL	*- FL
16	2		*BOOT LID HINGE COVER	Not Necessary	234.40 FL	*- FL
17	1		*REAR BUMPER	Distorted	1,623.31 FL	*1,250.00 FL
18	1		*REAR BUMPER TOW HOOK COVER	O/S Twisted	84.42 FL	*42.21 FL
19	2		*REAR BUMPER REFLECTOR	Not fitted	179.30 FL	*- FL
20	2		*REAR BUMPER BOLT COVER	Not Necessary	84.40 FL	*- FL
21	1		*REAR BUMPER BRACKET	O/S Dented	221.30 FL	*110.65 FL
22	2		*REAR BUMPER SIDE RETAINER	Not Necessary	179.30 FL	*- FL
23	1		*SET REAR BUMPER CLIP	Necessary	27.00 FL	*27.00 FL
24	1		*REAR END PANEL	Badly Dented	890.60 FL	*890.60 FL
25	1		*REAR END PANEL GARNISH	Twisted	411.63 FL	*411.63 FL
26	1		*REAR EXHAUST SILENCER ASSEMBLY	Repair	1,585.00 FL	*- FL
27	4		*REAR EXHAUST MOULDING	Not Necessary	84.40 FL	*- FL
28	2		*REAR FLOOR BOARD	Not Necessary	921.50 FL	*- FL
29	1		*REAR FLOOR TOOLS TRAY	Not Necessary	411.50 FL	*- FL
30	2		*REAR FLOOR PANEL	Repair	2,301.20 FL	*- FL
31	2		*TAILLAMP PANEL	Repair	263.00 FL	*- FL
32	2		*TAILLAMP LOWER BRACKET	Not Necessary	179.00 FL	*- FL
33	1		*BOOT LID SPOILER	Warped / Cracked	750.00 FS	*600.00 FS
34	1		*REAR BUMPER LOWER LID	Warped / Cracked	1,400.00 FS	*900.00 FS
35	1		*SET REAR BUMPER LOWER LID REFLECTORS	Cracked	450.00 FS	*250.00 FS
36	1		*REAR EXHAUST AKRAPORIC LID O/S	Cut	600.00 FS	*100.00 FS
37	1		*TAILLAMP LED	O/S Cracked	3,000.00 FS	*600.00 FS
38	1		*REAR LICENCE PLATE	Not Necessary	60.00 FS	*- FS
39	1		*REVERSE SENSOR	Shorted	350.00 FS	*200.00 FS
40	1		*REVERSE CAMERA	Not Necessary	450.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	20,528.57	7,908.29
- List Item Discount on L Items 25.00/25.00% (\$)	3,367.14	1,314.57
Total Parts (\$)	17,161.43	6,593.72

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECKING ELECTRICAL WIRING AND CHECK FUNCTIONS	New	60.00	30.00
2	TO REMOVE, REFIX INNER TRIMS, GARNISHES, LININGS ETC TO FACILITATE REPAIRS	New	120.00	80.00
3	TO REMOVE AND REPLACE REAR SENSORS AND REAR CAMERA AND CHECK FOR PROPER FUNCTION	New	80.00	50.00
4	TO REMOVE AND REPLACE REAR EXHAUST PIPE SYSTEM TO FACILITATE REPAIRS	New	160.00	60.00
5	TO RESPRAY UNDERCOATING / RUST PROOFING	New	100.00	60.00
6	TO RESPRAY PAINTING & ETC	New	1,400.00	800.00
7	PANEL BEATING, CUT, WELD, REMOVE AND REPLACING ABOVE PARTS	New	1,600.00	1,080.00
Gross Labour Cost (\$\$)			3,520.00	2,160.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >