

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CC3/AIG20011187/ATF3E2

**Date:** 10/02/2021

### REFERENCE

Insured/Claimant:	DARA ROK ING	Policy No:	2070006889		
Date of Loss:	11/10/2020	Nature of Claim:	OD	Claim No:	5714216623SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMR8970Z		
Make & Model:	AUDI A5, 2.0 SB TFSI S TRONIC (DESIGN) (A)	Engine No:	CVK087014
Reg. Date:	30/01/2020 (Man. Year: 2019)	Chassis No:	WAUZZZF59KA073043
Colour:	Grey	Odometer:	8538 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$160,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

### CONDITION OF TYRES

Front Tyre Size:	245/40 R18	Rear Tyre Size:	245/40 R18
Front Left Side:	Hankook 6 mm	Rear Left Side:	Hankook 6 mm
Front Right Side:	Hankook 6 mm	Rear Right Side:	Hankook 6 mm

*The above values represent the remaining tyre tread depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,376.00	1,900.00	14,476.00	88.40
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,272.00	1,522.00	2,750.00	64.37
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>20,648.00</b>	<b>3,422.00</b>	<b>17,226.00</b>	<b>83.43</b>
<b>- Excess (S\$)</b>	<b>800.00</b>	<b>800.00</b>	<b>0.00</b>	<b>0.00</b>
<b>(S\$)</b>	<b>19,848.00</b>	<b>2,622.00</b>	<b>17,226.00</b>	<b>86.79</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>1,389.36</b>	<b>183.54</b>	<b>1,205.82</b>	<b>86.79</b>
<b>Nett Amount (S\$)</b>	<b>21,237.36</b>	<b>2,805.54</b>	<b>18,431.82</b>	<b>86.79</b>

### INSPECTION

Date of Assignment:	15/10/2020		
Date Inspected:	15/10/2020	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	3.0 days		

**Adjuster:** ADRIAN LING

**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	2,251.00 FS	*- FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	402.00 FS	*- FS
3	1		*FRONT BUMPER GRILLE - CENTRE	Not Necessary	194.00 FS	*- FS
4	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Not Necessary	225.00 FS	*- FS
5	1		*FRONT BUMPER SPOILER	Not Necessary	529.00 FS	*- FS
6	1		*RADIATOR GRILLE	Cracked	2,300.00 FS	*1,840.00 FS
7	2		*ULTRASOUND SENSOR SUPPORT - LH	Not Necessary	102.00 FS	*- FS
8	1		*RADIATOR GRILLE COVER - UPPER	Not Necessary	187.00 FS	*- FS
9	1		*FRONT BUMPER AIR GUIDE GRILLE - LH	Not Necessary	468.00 FS	*- FS
10	1		*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	123.00 FS	*- FS
11	1		*FRONT BUMPER CARRIER	Not Necessary	795.00 FS	*- FS
12	1		*FRONT BUMPER TOP COVER	Not Necessary	126.00 FS	*- FS
13	1		*LOCK CARRIER BRACKET	Not Necessary	136.00 FS	*- FS
14	2		*LOCK CARRIER BRACKET SUPPORT - LH / RH	Not Necessary	56.00 FS	*- FS
15	1		*CAUTION SIGN STICKER	Not Necessary	14.00 FS	*- FS
16	1		*AIRCON STICKER	Not Necessary	8.00 FS	*- FS
17	1		*FRONT PARKING AID SENSOR - INNER	Not Necessary	242.00 FS	*- FS
18	4		*FRONT PARKING AID SEAL RING	Not Necessary	14.00 FS	*- FS
19	1		*BONNET IMPACT PROTECTION - CENTRE	Not Necessary	27.00 FS	*- FS
20	1		*BONNET IMPACT PROTECTION - LH	Not Necessary	28.00 FS	*- FS
21	1		*LED HEADLIGHT - LH	Not Necessary	7,812.00 FS	*- FS
22	1		*FRONT NO PLATE	Cut	60.00 FS	*60.00 FS
23	1		*SUNDRIES	Not Necessary	250.00 FS	*- FS
24	1		*BONNET IMPACT PROTECTION - RH	Not Necessary	27.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 16,376.00 1,900.00

Report was unsubmitted during this print-out.

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	New	280.00	280.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHT CONTROL UNIT AND POWER MODULE.	New	400.00	0.00
3	TO DISMANTLE AND RENEW FRONT BUMPER AND LHS HEADLIGHT. TO REPAIR BONNET, RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	New	1,750.00	500.00
4	TO RESPRAY FRONT BUMPER AND BONNET.	New	1,650.00	550.00
5	TO CARRY OUT DIAGNOSTIC CHECK.	New	192.00	192.00
<b>Gross Labour Cost (\$\$)</b>			<b>4,272.00</b>	<b>1,522.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >