

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG20011188/AVF3E2

Date: 04/03/2021

REFERENCE

Insured/Claimant:	LOH HIN SIONG	Policy No:	1800024615		
Date of Loss:	13/10/2020	Nature of Claim:	OD	Claim No:	1692209055SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLW9498A		
Make & Model:	AUDI A5, 2.0 SB TFSI S TRONIC (DESIGN) (A)	Engine No:	CVK050932
Reg. Date:	09/03/2018 (Man. Year: 2017)	Chassis No:	WAUZZZF58JA050268
Colour:	Black	Odometer:	78429 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$135,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	255/35 R19	Rear Tyre Size:	255/35 R19
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	22,347.00	12,666.56	9,680.44	43.32
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,172.00	3,572.00	3,600.00	50.20
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	29,519.00	16,238.56	13,280.44	44.99
- Excess (S\$)	1,600.00	1,600.00	0.00	0.00
(S\$)	27,919.00	14,638.56	13,280.44	47.57
+ GST 7.00/7.00% (S\$)	1,954.33	1,024.70	929.63	47.57
Nett Amount (S\$)	29,873.33	15,663.26	14,210.07	47.57

INSPECTION

Date of Assignment:	15/10/2020		
Date Inspected:	15/10/2020	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	5.0 days		

Adjuster: ADRIAN LING

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,251.00 FS	*1,800.80 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	402.00 FS	*- FS
3	2		*FRONT BUMPER SECURING STRIP	Not Necessary	70.00 FS	*- FS
4	1		*FRONT BUMPER GRILLE - CENTRE	Not Necessary	194.00 FS	*- FS
5	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Not Necessary	225.00 FS	*- FS
6	1		*FRONT BUMPER SPOILER	Not Necessary	529.00 FS	*- FS
7	1		*RADIATOR GRILLE	Cracked	2,300.00 FS	*1,840.00 FS
8	2		*ULTRASOUND SENSOR SUPPORT - LH / RH	Not Necessary	102.00 FS	*- FS
9	1		*RADIATOR GRILLE COVER - UPPER	Not Necessary	187.00 FS	*- FS
10	2		*FRONT BUMPER AIR GUIDE GRILLE - LH / RH	Not Necessary	936.00 FS	*- FS
11	1		*FRONT BUMPER CARRIER	Not Necessary	795.00 FS	*- FS
12	1		*FRONT BUMPER FOAM FILLER PIECE	Cracked	123.00 FS	*98.40 FS
13	1		*FRONT BUMPER TOP COVER	Cracked	126.00 FS	*100.40 FS
14	2		*FRONT BUMPER GUIDE SECTION - LH / RH	Not Necessary	72.00 FS	*- FS
15	1		*CAUTION SIGN STICKER	Necessary	14.00 FS	*10.80 FS
16	1		*AIRCON STICKER	Necessary	8.00 FS	*5.68 FS
17	1		*LOCK CARRIER BRACKET	Cracked	136.00 FS	*108.40 FS
18	2		*LOCK CARRIER BRACKET SUPPORT - LH / RH	Not Necessary	56.00 FS	*- FS
19	1		*HORN - LH HIGH TONE	Not Necessary	124.00 FS	*- FS
20	1		*SPRING SHACKLE - LH	Not Necessary	29.00 FS	*- FS
21	1		*FRONT PARKING AID SENSOR - INNER	Not Necessary	242.00 FS	*- FS
22	4		*FRONT PARKING AID SEAL RING	Not Necessary	14.00 FS	*- FS
23	1		*BONNET	Dented	2,817.00 FS	*2,253.60 FS
24	1		*BONNET ATTACHMENT PARTS	Not Necessary	121.00 FS	*- FS
25	2		*BONNET LID HINGE - LH / RH	Not Necessary	830.00 FS	*- FS
26	1		*BONNET IMPACT PROTECTION - CENTRE	Necessary	27.00 FS	*21.52 FS
27	1		*BONNET IMPACT PROTECTION - LH	Necessary	28.00 FS	*21.84 FS
28	1		*BONNET IMPACT PROTECTION - RH	Necessary	27.00 FS	*21.52 FS
29	1		*BONNET SOUND ABSORBER	Not Necessary	339.00 FS	*- FS
30	1		*BONNET BOWDEN CABLE - CENTRE	Not Necessary	57.00 FS	*- FS
31	1		*BONNET BOWDEN CABLE - LOWER	Not Necessary	57.00 FS	*- FS
32	2		*BONNET STRIKER - LH / RH	Not Necessary	100.00 FS	*- FS
33	2		*BONNET LID LOCK	Not Necessary	423.00 FS	*- FS
34	1		*LED HEADLIGHT - LH	Cracked	7,812.00 FS	*6,249.60 FS
35	1		*LIFT CYLINDER - LH	Not Necessary	196.00 FS	*- FS
36	1		*LIFT CYLINDER CORRUGATED PIPE	Not Necessary	85.00 FS	*- FS
37	2		*RADIATOR AIR GUIDE - LH / RH INNER	Not Necessary	62.00 FS	*- FS
38	2		*RADIATOR AIR GUIDE - LH / RH OUTER	Not Necessary	32.00 FS	*- FS
39	1		*RADIATOR AIR GUIDE - UPPER	Cracked	16.00 FS	*12.72 FS
40	1		*FRONT NO PLATE	Dented	60.00 FS	*60.00 FS
41	1		*SUNDRIES	Necessary	250.00 FS	*3.52 FS
42	1		*FRONT WHEEL SPOILER	Cracked	73.00 FS	*57.76 FS
			(SUPPLEMENTARY)			

F=Franchise part. S=SpcNett.

Total Parts (S\$) 22,347.00 12,666.56

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHT CONTROL UNIT AND POWER MODULE	New	400.00	250.00
3	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND LHA HEADLIGHT. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,400.00	1,000.00
4	TO RESPRAY FRONT BUMPER AND BONNET	New	2,500.00	1,100.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
6	TO REPAIR AND RESPRAY LHS FRONT UPPER A-PILLAR. (SUPPLEMENTARY)	New	1,200.00	550.00
Gross Labour Cost (\$\$)			7,172.00	3,572.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >