

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 1456L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	BROKEN	459.40	459.40
10	REAR BUMPER COVER CLIPS	NECESSARY	22.00	22.00
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	294.80	-
2	REAR BUMPER RE-INFORCEMENT BRACKET LH / RH	NOT NECESSARY	276.20	-
2	REAR BUMPER SIDE BRACKET LH / RH	NOT NECESSARY	111.60	-
1	REAR BUMPER TOWING COVER	NOT NECESSARY	98.80	-
1	REAR BUMPER CENTRE MOULDING ASSY	CRUSHED	451.25	451.25
1	REAR BUMPER LOWER CENTRE MOULDING ASSY	NOT NECESSARY	155.00	-
1	REAR FOG LAMP	NOT NECESSARY	201.50	-
	LESS 20% DISCOUNT		-414.11	-186.53
			1,656.44	746.12
<u>SPECIAL NETT ITEMS</u>				
1	REAR NO. PLATE WITH TRIM COVER (SN)	BROKEN	55.00	55.00
1	REVERSE SENSOR (SN)	SHORTED	180.00	180.00
			235.00	235.00
<u>LABOUR</u>				
	PANEL BEATING.		400.00	320.00
	SPRAY PAINTING.		300.00	200.00
	REMOVE / REPLACE REVERSE SENSOR.		120.00	30.00
	TUFF KOTE.	NOT NECESSARY	90.00	-
	CHECK LIGHTING.		60.00	30.00
			970.00	580.00
GRAND TOTAL			2,861.44	1,561.12
RECOMMENDED COST OF REPAIRS (CONFIRMED)				1,561.12

Report Ref No. NS/INC20011190/Eqf3e2



CHEN TSUE YEE

Automotive Assessor



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.