## COMFORTDELGRO ENGINEERING PTE LTD

	REPAIR ESTIMA	TE	
	15/10/2020	3P INSURANCE:	NTUC
MODEL:	HYUNDAI IONIQ	SURVEYOR:	LKK
VEH NO.:	SHA1456L	MVA:	LOKE WY

	SHA1456L		MVA:	LOKE WY
ART NO.	DESCRIPTION	QTY	LIST PRICE	REMARKS 367-5
	Rear Bumper / ///	1		1211
	Rear Bumper Cover Clips / N(	10		
	Rear Bumper Reinforcement / X MM	1	9.5	\$294.80 \$276.20
	Poor Rumas De informament Bracket LHRH X MM	2		\$111.60
	Rear Bumper Side Bracket LH RH	2		\$98.80
	Rear Bumper Towing Cover X NM	1		\$451.25 361
	Rear Bumper Centre Moulding Assy / CRY	1		\$155.00
	Rear Bumper Lower Centre Moulding Assy X ///	1		\$201.50
	Rear Fog Lamp 1 X NN	1		
	•		g at	
				\$2,070.55
	SPARE PARTS SUB TOTAL		# · · · · · · · · · · · · · · · · · · ·	\$414.11
	LESS 20%			
	DISCOUNTED SPARE PARTS TOTAL			\$1,656.44
	00	1		\$55.00 Nett
	Rear No. Plate with Trim Cover		lan ar	\$180.00 Net
	Rear No. Plate with Trim Cover	1		
				\$235.00
	DISCOUNTED SPARE PARTS & NETT TOTAL			\$233.00
		8. 5		
		F		200
n = 2 =				\$400.00 370
	Panel Beating			\$300.00 200
	Spray Painting		9	\$120.00 39
	Remove / Replace Reverse Sensor			\$90.00 🗶
	Tuff Kote			\$60.00 39
	Check Lighting	-		
	LABOUR TOTA	4		\$970.00
	ESTIMATE TOTA			\$2,861.44
4	ESTIMATE TOTA	٦		

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Steve (LKK) m M 15/10/2, 11.00 = 2 dyr P/P M Be L M

## LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a Without Frejudice" basis
- No illegal modification(s) is all, we 1
- Supplementary itemisis must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer Signature:

Date:

Page 1 of 8 Hvundai Sonata (Front)