

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CTI20011191/ATD3Q2

**Date:** 09/12/2020

### REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNA00019622000
<b>Claimant Vehicle No :</b>	SJG3191G	<b>Insured Vehicle No :</b>	YQ2410B
Date of Loss:	13/10/2020	Nature of Claim:	TP
		Claim No:	SNM20D203846/C02/TOHHS

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJG3191G	Engine No:	L15Z16200238
Make & Model:	HONDA CITY, 1.5 (A)	Chassis No:	MRHGM6660KT000119
Reg. Date:	11/04/2018 (Man. Year: 2018)	Odometer:	19021 km
Colour:	Maroon		
Engine Capacity:	1497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	185/55R16	Rear Tyre Size:	185/55R16
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	6,684.28	4,270.60	2,413.68	36.11
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,840.00	2,180.00	660.00	23.24
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>9,524.28</b>	<b>6,450.60</b>	<b>3,073.68</b>	<b>32.27</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>5,100.00</b>		
<b>(\$\$)</b>	9,524.28	5,100.00	4,424.28	46.45
<b>+ GST 7.00/7.00% (\$\$)</b>	666.70	357.00	309.70	46.45
<b>Nett Amount (\$\$)</b>	<b>10,190.98</b>	<b>5,457.00</b>	<b>4,733.98</b>	<b>46.45</b>

### INSPECTION

Date of Assignment: 15/10/2020

Date Inspected: 15/10/2020 Inspected At:

N-51 Automotive Pte Ltd (kaki Bukit Autohub) (HQ)  
KAKI BUKIT AUTOHUB 2 KAKI  
BVUKIT AVE 2 #01-18  
Singapore 417921

Estimated Period of Repair: 7.0 days

**Adjuster:** ADRIAN LING**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 09 Dec 2020)
<b>Parts:</b>	143	HONDA CITY 1.5 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SJG3191G)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*R BUMPER LOWER CENTER GARNISH	Cracked	59.20 FL	*59.20 FL
2	1		*REAR BOOTLID	Distorted	655.40 FL	*565.00 FL
3	1		*REAR BOOTLID CITY EMBLEM	Necessary	22.00 FL	*22.00 FL
4	1		*REAR BOOTLID I-VTEC EMBLEM	Necessary	22.00 FL	*22.00 FL
5	1		*REAR BOOTLID LOGO EMBLEM	Necessary	20.00 FL	*20.00 FL
6	2		*REAR BOOTLID HINGES L/R	Bent	136.80 FL	*136.80 FL
7	2		*REAR BOOTLID INNER RUBBER GUIDE STOPPER (LONG) L/R	Not Necessary	25.00 FL	*- FL
8	2		*REAR BOOTLID INNER RUBBER GUIDE STOPPER L/R	Not Necessary	21.00 FL	*- FL
9	1		*REAR BOOTLID INNER TRIM	Not Necessary	85.00 FL	*- FL
10	1		*REAR BOOTLID LOCK STRIKER	Not Necessary	22.50 FL	*- FL
11	1		*REAR BOOTLID MECHANISM LOCK	Damaged	90.30 FL	*90.30 FL
12	2		*REAR BOOTLID NUMBER PLATE LAMP L/R	Not Necessary	77.00 FL	*- FL
13	1		*REAR BOOTLID OUTER CHROME HANDLE	Cracked	148.50 FL	*148.50 FL
14	2		*REAR BOOTLID REFLECTOR INNER BLACK GASKET L/R	Necessary	37.00 FL	*37.00 FL
15	2		*REAR BOOTLID REFLECTOR L/R	Cracked	410.00 FL	*410.00 FL
16	1		*REAR BOOTLID WEATHER STRIP	Cut	91.60 FL	*91.60 FL
17	1		*REAR BUMPER	Deformed	472.70 FL	*472.70 FL
18	2		*REAR BUMPER REFLECTOR GARNISH L/R	Cracked	85.80 FL	*85.80 FL
19	1		*REAR BUMPER REFLECTOR L/R	N/s Cracked/O/s Not Necessary	60.00 FL	*30.00 FL
20	2		*REAR BUMPER SIDE RETAINER L/R	Necessary	50.60 FL	*50.60 FL
21	1		*REAR END PANEL	Dented	452.60 FL	*365.00 FL
22	1		*REAR END PANEL ANTENNA SENSOR	Cracked	85.00 FL	*85.00 FL
23	1		*REAR END PANEL INNER TOP GARNISH	Deformed	86.40 FL	*86.40 FL
24	2		*REAR FENDER INNER TRIM BOARD L/R	Not Necessary	457.80 FL	*- FL
25	1		*REAR FLOOR PANEL TOP BOARD COVER	Torn	254.30 FL	*254.30 FL
26	1		*REAR LH TAILLAMP INNER PANEL	Dented	89.70 FL	*89.70 FL
27	2		*REAR TAILLAMP INNER BLACK GASKET L/R	Necessary	37.00 FL	*37.00 FL
28	2		*REAR TAILLAMP L/R	N/s Cracked/O/s Cut	681.40 FL	*510.60 FL
29	1		*REAR BOOTLID CAMERA	Damaged	800.00 FS	*400.00 FS
30	1		*SET REAR BOOTLID INNER TRIM CLIPS	Not Necessary	50.00 FS	*- FS
31	1		*REAR BOOTLID NUMBER PLATE	Bent	25.00 FS	*25.00 FS
32	1		*REAR BOOTLID NUMBER PLATE HOLDER	Not Necessary	50.00 FS	*- FS
33	1		*SET REAR BOOTLID OUTER CHROME HANDLE CLIPS	Necessary	40.00 FS	*10.00 FS
34	1		*REAR BOOTLID TOP SPOILER	Cracked	980.00 FS	*500.00 FS
35	1		*SET REAR BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
36	1		*SET REAR BUMPER REVERSE SENSOR	Damaged	380.00 FS	*300.00 FS
37	1		*SET REAR END PANEL INNER TOP GARNISH CLIPS	Necessary	40.00 FS	*20.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
38	2		*SET REAR FENDER INNER TRIM BOARD CLIPS L/R	Not Necessary	100.00 FS	*- FS
39	1		*REAR FLOOR PANEL INSULATOR MAT	Not Necessary	300.00 FS	*- FS
40	2		*SET REAR TAILLAMP CLIPS L/R	Necessary	50.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>7,631.60</b>	<b>5,004.50</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$)</b>	947.32	733.90
<b>Total Parts (\$)</b>	<b>6,684.28</b>	<b>4,270.60</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO REMOVE,REINSTALL ELECTRICAL WIRING HARNESS,CHECK LIGHTING,AND REWIRE FOR PARKING SENSOR	New	100.00	80.00
2	TO REMOVE,REINSTALL ROOF TOP TRIM UPHOLSTERY,CUSHION SEAT,TRIM GARNISH,TRIM LINER CARPET (TO FR)	New	140.00	60.00
3	TO RE-SPRAY PAINTING ON THE REAR BOOTLID,REAR END PANEL,REAR FENDER (L/R),SPARE TYRE PANEL AND REAR BUMPER	New	1,300.00	1,000.00
4	TO PROVIDE LABOUR,WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS,REPAIR,RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE,BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	1,100.00	900.00
5	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	New	120.00	60.00
6	TO TRANSFER REAR BOOTLID MECHANISM LOCK OUTER HANDLE REFLECTOR	New	80.00	80.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,840.00</b>	<b>2,180.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >