



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CC4/FCI20011197/Kda3q2	
			Date: 10/11/2020	
			Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 7488E	Veh. Inspected	SMR 3828K	
Policy No.	D-20094922MFSH	Coverage (\$)	0.00	
Claim No.	D20004185MFSH	Excess (\$)	0.00	
Assign From	RACHEL WU	Assign Date	15/10/2020	
2. Vehicle Particulars & Condition				
Make & Model	RENAULT SCENIC (A)	c.c	1461	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	VF1RFA00063520524	Colour	METALLIC BLACK	
Odometer	65251 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/55 R20	CONTINENTAL	8 mm	
L/H Front Tyre	195/55 R20	CONTINENTAL	8 mm	
R/H Rear Tyre	195/55 R20	CONTINENTAL	8 mm	
L/H Rear Tyre	195/55 R20	CONTINENTAL	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	12/10/2020	Inspection Date	16/10/2020	
Survey held at	MUNICH AUTOMOBILES PTD LTD 30 TEBAN GARDENS CRESCENT SINGAPORE 608927			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			2 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMR 3828K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	BUCKLED	1,461.72	1,250.50
1	BUMPER BRACKET ,LEFT	SERVICEABLE	140.88	-
1	BUMPER REINFORCEMENT ,PLASTIC	TO REPAIR SEE LABOUR	247.92	-
2	PARK SENSOR @\$524.79	SERVICEABLE	1,049.58	-
1	FOGLAMP COVER ,CHROME	SCRATCHED	238.20	238.20
	LESS 10% DISCOUNT		-313.83	-148.87
			2,824.47	1,339.83
	<u>LABOUR</u>			
	REPLACING DAMAGED PARTS AS PER ABOVE INCLUDING PANEL BEATING LABOUR .		800.00	200.00
	CHECK SENSOR AND WIRING FUNCTION .		120.00	20.00
	SPRAY PAINTING FOR FRONT BUMPER .		400.00	250.00
			1,320.00	470.00
	GRAND TOTAL		4,144.47	1,809.83
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,450.00

Report Ref No. CC4/FCI20011197/Kda3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMR 3828K

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

