

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20011199/QQF3Q2

Date: 09/11/2020

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMHCSNA00003482000

Claimant Vehicle No : SMN1412K **Insured Vehicle No :** SMA7645J

Date of Loss: 10/10/2020 Nature of Claim: TP Claim No: SNM20D203828/C02/CHEESC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMN1412K	Engine No:	2ZR0D11242
Make & Model:	TOYOTA PRIUS PLUS, 1.8 (A)	Chassis No:	JTDZS3EU30J038704
Reg. Date:	25/07/2019 (Man. Year: 2018)	Odometer:	89554 km
Colour:	Black		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,024.68	2,046.00	5,978.68	74.50
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,480.00	1,240.00	2,240.00	64.37
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	11,504.68	3,286.00	8,218.68	71.44
Approved Total (Overridden) (\$\$)		2,650.00		
(\$\$)	11,504.68	2,650.00	8,854.68	76.97
+ GST 7.00/7.00% (\$\$)	805.33	185.50	619.83	76.97
Nett Amount (\$\$)	12,310.01	2,835.50	9,474.51	76.97

INSPECTION

Date of Assignment: 15/10/2020

Date Inspected: 16/10/2020 Inspected At: 60 Jalan Lam Huat, Carros Centre #05-68
Repairer: MY CAR CONSULTANT PTE LTD

Estimated Period of Repair: 4.0 days

Adjuster: OI SUN PIN

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 09 Nov 2020)
Parts:	M1-MPV	TOYOTA PRIUS PLUS 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMN1412K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Crumpled	730.54 FL	*698.00 FL
2	1		*REAR BUMPER SIDE RETAINER LH	Broken	113.60 FL	*113.60 FL
3	1		*REAR BUMPER SIDE RETAINER RH	Serviceable	113.60 FL	*- FL
4	1		*REAR BUMPER REINFORCEMENT	Bent	350.50 FL	*350.50 FL
5	1		*REAR BUMPER BRACKET LH	Broken	115.30 FL	*115.30 FL
6	1		*REAR BUMPER BRACKET RH	Serviceable	115.30 FL	*- FL
7	1		*REAR BUMPER LIP	Crumpled	728.90 FL	*728.90 FL
8	1		*REAR BUMPER REFLECTOR LH	Cracked	80.60 FL	*80.60 FL
9	1		*REAR BUMPER REFLECTOR RH	Serviceable	80.60 FL	*- FL
10	1		*REAR TAILGATE	Serviceable	1,180.60 FL	*- FL
11	1		*REAR TAILGATE LOCK	Serviceable	361.10 FL	*- FL
12	1		*REAR TAILGATE LOCK CATCH	Serviceable	89.50 FL	*- FL
13	1		*REAR TAILGATE LOCK SENSOR	Serviceable	360.90 FL	*- FL
14	1		*REAR TAILGATE LOCK OUTER HADLE	Serviceable	127.60 FL	*- FL
15	1		*REAR TAILGATE INNER TRIM BOARD	Serviceable	428.20 FL	*- FL
16	1		*REAR TAILGATE INNER TRIM INSULATOR	Serviceable	348.60 FL	*- FL
17	1		*REAR TAILGATE LOGO	Serviceable	95.50 FL	*- FL
18	1		*REAR TAILGATE EMBLEM PRIUS	Serviceable	89.40 FL	*- FL
19	1		*REAR TAILGATE EMBLEM HYBRID	Serviceable	82.30 FL	*- FL
20	1		*REAR TAILGATE WIRE HARNESS	Serviceable	998.40 FL	*- FL
21	1		*REAR TAILLAMP CLIPS RH	Serviceable	9.80 FL	*- FL
22	1		*REAR TAILLAMP LH	Cracked	690.50 FL	*512.00 FL
23	1		*REAR TAILLAMP INNER PANEL LH	Serviceable	280.40 FL	*- FL
24	1		*REAR TAILLAMP LOWER BRACKET LH	Broken	89.10 FL	*89.10 FL
25	1		*REAR TAILLAMP CLIPS	Serviceable	9.80 FL	*- FL
26	1		*REAR FENDER LH	Repair	850.30 FL	*- FL
27	1		*REAR END PANEL	Repair	660.20 FL	*- FL
28	1		*REAR END PANEL TOP GARNISH	Serviceable	225.10 FL	*- FL
29	1		*SET REAR BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
30	1		*SET REAR TAILGATE INNER TRIM BOARD CLIPS	Serviceable	80.00 FS	*- FS
31	1		*SET REAR TAILGATE OUTER GARNISH CLIPS	Serviceable	80.00 FS	*- FS
32	1		*REAR REVERSE SENSOR	Serviceable	250.00 FS	*- FS
33	1		*SET REAR FENDER INNTR TRIM BOARD CLIPS LH	Serviceable	80.00 FS	*- FS
34	1		*SET REAR FENDER INNTR TRIM BOARD CLIPS RH	Serviceable	80.00 FS	*- FS
35	1		*SET REAR END PANEL TOP GARNISH CLIPS	Serviceable	80.00 FS	*- FS
36	1		*SET REAR END PANEL SEALANT	Serviceable	60.00 FS	*- FS
37	1		*SET REAR FLOOR PANEL SEALANT	Serviceable	60.00 FS	*- FS
38	1		*REAR WINDSCREEN GLASS SEALANT	Serviceable	60.00 FS	*- FS
39	1		*REAR NUMBER PLATE WITH CASING	Serviceable	60.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 10,376.24 2,718.00
- List Item Discount on L Items 25.00/25.00% (\$\$) 2,351.56 672.00

Total Parts (\$\$) 8,024.68 2,046.00

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK REAR ELECTRICAL WIRING	New	80.00	30.00
2	TO REMOVE AND RENEW REVERSE SENSOR	New	150.00	30.00
3	TO REMOVE AND RENEW REAR REVERSE CAMERA	New	150.00	0.00
4	TO REMOVE AND TRANSFER WINDSCREEN GLASS	New	150.00	0.00
5	REMOVE AND RENEW REAR GARNISH /UPHOLSTERY	New	200.00	0.00
6	TO RESPRAY UNDERCOATING	New	150.00	40.00
7	APPLY ANTI RUST ON AFFECTED AREAS	New	200.00	40.00
8	SPRAY PAINTING ON AFFECTED AREAS	New	1,200.00	600.00
9	PANEL BEATING ON AFFECTED AREAS	New	1,200.00	500.00
Gross Labour Cost (\$)			3,480.00	1,240.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >