

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/III20011206/UGA3Q2

Date: 06/01/2021

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D19MCV0003933_01
Claimant Vehicle No :	SMP6142X	Insured Vehicle No :	GW5640R
Date of Loss:	14/10/2020	Nature of Claim:	TP
		Claim No:	MCV2020D0002086

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMP6142X	Engine No:	L15B6020211
Make & Model:	HONDA SHUTTLE, 1.5 G CVT (A)	Chassis No:	GK82100162
Reg. Date:	02/10/2019 (Man. Year: 2019)	Odometer:	19745 km
Colour:	White		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,611.80	5,355.68	10,256.12	65.69
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,720.00	2,180.00	1,540.00	41.40
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	19,331.80	7,535.68	11,796.12	61.02
Approved Total (Overridden) (S\$)		6,000.00		
Nett Amount (S\$)	19,331.80	6,000.00	13,331.80	68.96
+ Car Rental (5.0 x S\$100.00/day) (S\$)		500.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		6,502.00		
Global Sum Settlement (S\$)		6,500.00		

INSPECTION

Date of Assignment:	15/10/2020	
Date Inspected:	15/10/2020 Inspected At:	Choo Motor Spray Painter (HQ) 1 Kaki Bukit Avenue 6, #01-39 AutoBay @ Kaki Bukit Singapore 417883
Estimated Period of Repair:	5.0 days	

Adjuster: MARCUS CHUA**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 30 Nov 2020)	
Parts:	N/A	HONDA SHUTTLE 1.5 G CVT (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMP6142X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN MOULDING	Necessary	186.40 F	*166.30 FL
2	1		*TAILGATE	Badly Dented	1,866.20 F	*1,250.20 FL
3	1		*TAILGATE H LOGO	Necessary	48.50 F	*48.50 FL
4	1		*TAILGATE SHUTTLE EMBLEM	Necessary	68.30 F	*68.30 FL
5	1		*TAILGATE OUTER HANDLE	Cracked	465.00 F	*415.20 FL
6	1		*TAILGATE REFLECTORS	N/S Cracked	1,300.40 F	*535.50 FL
7	1		*TAILGATE INNER LOCK	Twisted	299.50 F	*199.20 FL
8	1		*TAILGATE INNER TRIM BOARD	Deformed / Cracked	465.30 F	*465.30 FL
9	1		*SET TAILGATE INNER TRIM BOARD CLIPS	Necessary	50.00 F	*50.00 FL
10	1		*TAILGATE WEATHERSTRIP	Twisted	288.70 F	*166.80 FL
11	1		*REAR BUMPER	Distorted	1,420.30 F	*1,150.60 FL
12	2		*REAR BUMPER SPONGES	Not Necessary	390.00 F	*- FL
13	2		*REAR BUMPER SIDE RETAINERS	Not Necessary	130.00 F	*- FL
14	1		*REAR BUMPER REFLECTORS	N/S Cracked	136.00 F	*68.00 FL
15	1		*SET REAR BUMPER CLIPS	Necessary	50.00 F	*40.00 FL
16	1		*REAR BUMPER TOP CHROME MOULDING	Cracked	233.50 F	*233.50 FL
17	1		*REAR END PANEL	Badly Dented	899.20 F	*849.40 FL
18	1		*REAR END PANEL TOP GARNISH	Not Necessary	366.50 F	*- FL
19	1		*TAILLAMPS	N/S Cracked	1,700.00 F	*625.30 FL
20	1		*REAR FLOOR PANEL	Repair	1,140.20 F	*- FL
21	1		*REAR FLOOR PANEL TOP BOARD	Not Necessary	688.50 F	*- FL
22	1		*REAR FENDER INNER TRIM BOARD	Not Necessary	681.10 F	*- FL
23	1		*REAR FENDER	Repair	1,099.20 F	*- FL
24	1		*REAR ANTENNA SENSOR	Not Necessary	290.50 F	*- FL
25	1		*REAR BUZZLE SENSOR	Not Necessary	288.50 F	*- FL
26	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
27	1		*REAR END PANEL SEALANT	Necessary	50.00 FS	*50.00 FS
28	1		*REAR WINDSCREEN SEALANT	Necessary	50.00 FS	*40.00 FS
29	1		*SET REAR FLOOR PANEL INSULATOR	Not Necessary	300.00 FS	*- FS
30	1		*SET REAR REVERSE CAMERA	Not Necessary	380.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	15,611.80	6,622.10
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	1,266.42
Total Parts (\$\$)	15,611.80	5,355.68

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING	New	50.00	30.00
2	TO DISMANTLE & REPLACED REVERSE SENSOR	New	80.00	50.00
3	TO DISMANTLE & REFIX CUSHION UPHOLSTERY	New	120.00	80.00
4	TO DISMANTLE & REFIX REAR EXHAUST	New	100.00	0.00
5	TO DISMANTLE & REFIX REAR WINDSCREEN	New	150.00	120.00
6	TO TRANSFER TAILGATE MECHANISM	New	100.00	60.00
7	TO SPRAY RUST PROOFING	New	120.00	60.00
8	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	1,500.00	700.00
9	TO PUTTY & SPRAY PAINTING	New	1,500.00	1,080.00
Gross Labour Cost (\$)			3,720.00	2,180.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >