

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20011210/ETD3E2

Date: 26/11/2020

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNA00029362001	
Claimant Vehicle No :	JSE6680	Insured Vehicle No :	SMK297Z	
Date of Loss:	10/10/2020	Nature of Claim:	TP	Claim No: SNM20D203813/C02/THAMYL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	JSE6680		
Make & Model:	TOYOTA CAMRY, 2.0 (A)	Engine No:	6ARP297390
Reg. Date:	22/06/2017 (Man. Year: 2017)	Chassis No:	PN153DK5100003415
Colour:	Black	Odometer:	156104 km
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55 R16	Rear Tyre Size:	215/55 R16
Front Left Side:	Michelin 5 mm	Rear Left Side:	Michelin 5 mm
Front Right Side:	Michelin 5 mm	Rear Right Side:	Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	32,781.75	3,313.00	29,468.75	89.89
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,170.00	1,320.00	9,850.00	88.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	43,951.75	4,633.00	39,318.75	89.46
Approved Total (Overridden) (S\$)		3,700.00		
(S\$)	43,951.75	3,700.00	40,251.75	91.58
+ GST 7.00/7.00% (S\$)	3,076.62	259.00	2,817.62	91.58
Nett Amount (S\$)	47,028.37	3,959.00	43,069.37	91.58

INSPECTION

Date of Assignment:	19/10/2020		
Date Inspected:	16/10/2020 Inspected At:	RICO 60 AUTO SERVICES PTE LTD (HQ) 8, KAKI BUKIT AVENUE 4, #02-24, PREMIER @ KAKI BUKIT Singapore 415875	
Estimated Period of Repair:	4.0 days		

Adjuster: CHEN TSUE YEE**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 25 Nov 2020)
Parts:	143	TOYOTA CAMRY 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for JSE6680)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN MOULDING	Not Necessary	691.00 FL	*- FL
2	1		*BOOTLID	Dented	1,679.00 FL	*890.00 FL
3	1		*BOOTLID CENTER GARNISH	Not Necessary	419.00 FL	*- FL
4	1		*BOOTLID LOGO (TOYOTA)	Necessary	58.00 FL	*58.00 FL
5	1		*BOOTLID EMBLEM (CAMRY)	Necessary	79.00 FL	*60.00 FL
6	1		*BOOTLID EMBLEM (2.0)	Necessary	81.00 FL	*55.00 FL
7	1		*BOOTLID EMBLEM (G)	Necessary	76.00 FL	*50.00 FL
8	1		*BOOTLID EMBLEM (RH)	Necessary	76.00 FL	*60.00 FL
9	1		*BOOTLID EMBLEM (D-45)	Necessary	88.00 FL	*55.00 FL
10	2		*BOOTLID LAMP (L+R)	Not Necessary	2,486.00 FL	*- FL
11	2		*BOOTLID LAMP CHROME (L+R)	Not Necessary	948.00 FL	*- FL
12	1		*BOOTLID HANDLE CHROME	Not Necessary	679.00 FL	*- FL
13	1		*BOOTLID HANDLE SWITCH	Not Necessary	589.00 FL	*- FL
14	2		*BOOTLID CARPLATE LAMP (L+R)	Not Necessary	246.00 FL	*- FL
15	1		*BOOTLID LOCK	Bent	879.00 FL	*220.00 FL
16	1		*BOOTLID LOCK COVER	Not Necessary	379.00 FL	*- FL
17	1		*BOOTLID LOCK CATCH	Not Necessary	103.00 FL	*- FL
18	1		*BOOTLID INNER TRIM	Not Necessary	673.00 FL	*- FL
19	2		*BOOTLID HINGE (L+R)	Not Necessary	578.00 FL	*- FL
20	2		*BOOTLID STOPPER (L+R)	Not Necessary	148.00 FL	*- FL
21	1		*BOOTLID WEATHERSTRIP	Torn	399.00 FL	*180.00 FL
22	2		*TAIL LAMP (L+R)	Not Necessary	2,674.00 FL	*- FL
23	2		*TAIL LAMP CHROME (L+R)	Not Necessary	1,054.00 FL	*- FL
24	2		*TAIL LAMP PANEL (L+R)	Not Necessary	864.00 FL	*- FL
25	1		*REAR BUMPER	Dented	1,379.00 FL	*580.00 FL
26	2		*REAR BUMPER RETAINER (L+R)	Broken	428.00 FL	*256.00 FL
27	2		*REAR BUMPER CENTER BRACKET (L+R) (NPA)	Not Necessary	0.00 FL	*- FL
28	1		*REAR BUMPER REINFORCEMENT BAR	Dented	1,009.00 FL	*420.00 FL
29	2		*REAR BUMPER REINFORCEMENT BRACKET (L+R)	Not Necessary	478.00 FL	*- FL
30	1		*REAR BUMPER BEAM (NPA)	Not Necessary	0.00 FL	*- FL
31	1		*REAR BUMPER SPONGE (NPA)	Not Necessary	0.00 FL	*- FL
32	1		*SET REAR BUMPER REVERSE SENSOR (4PCS)	Broken (2Pcs Only)	1,408.00 FL	*300.00 FL
33	1		*REAR BUMPER UNDERCOVER	Not Necessary	689.00 FL	*- FL
34	2		*REAR FENDER (L+R)	Not Necessary	3,894.00 FL	*- FL
35	2		*REAR FENDER INNER TRIM (L+R)	Not Necessary	2,004.00 FL	*- FL
36	2		*REAR FENDER COWLING (L+R)	Not Necessary	684.00 FL	*- FL
37	1		*END PANEL	Repair	1,374.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
38	1		*END PANEL TOP GARNISH	Broken	389.00 FL	*220.00 FL
39	1		*SPAREWHEEL PANEL	Not Necessary	1,978.00 FL	*- FL
40	1		*SPAREWHEEL PANEL TOP BOARD	Not Necessary	485.00 FL	*- FL
41	2		*SPAREWHEEL PANEL TOP SIDE BOARD (L+R)	Not Necessary	86.00 FL	*- FL
42	1		*SPAREWHEEL PANEL TOP BOARD TOP MAT	Not Necessary	341.00 FL	*- FL
43	1		*EXHAUST PIPE	Not Necessary	976.00 FL	*- FL
44	1		*EXHAUST GASKET	Not Necessary	174.00 FL	*- FL
45	2		*EXHAUST BRACKET (L+R)	Not Necessary	86.00 FL	*- FL
46	1		*EXHAUST HEAT SHIELD	Not Necessary	381.00 FL	*- FL
47	1		*REAR WINDSCREEN SEALANT	Not Necessary	120.00 FS	*- FS
48	10		*BOOTLID INNER TRIM CLIPS	Not Necessary	100.00 FS	*- FS
49	1		*BOOTLID PROTECTOR STRIP	Not Necessary	400.00 FS	*- FS
50	1		*REAR CARPLATE	Not Necessary	250.00 FS	*- FS
51	1		*REAR CARPLATE FRAME	Not Necessary	120.00 FS	*- FS
52	1		*REVERSE CAMERA	Not Necessary	850.00 FS	*- FS
53	10		*REAR BUMPER CLIPS	Necessary	100.00 FS	*50.00 FS
54	1		*REAR BUMPER LOWER	Crumpled	3,000.00 FS	*700.00 FS
55	2		*REAR BUMPER LOWER REFLECTOR (L+R)	Not Necessary	500.00 FS	*- FS
56	2		*REAR FENDER SEALANT	Not Necessary	600.00 FS	*- FS
57	20		*REAR FENDER INNER TRIM CLIPS	Not Necessary	200.00 FS	*- FS
58	20		*REAR FENDER COWLING CLIPS	Not Necessary	200.00 FS	*- FS
59	1		*END PANEL SEALANT	Not Necessary	250.00 FS	*- FS
60	10		*END PANEL TOP GARNISH CLIPS	Necessary	100.00 FS	*10.00 FS
61	1		*SPAREWHEEL PANEL SEALANT	Not Necessary	350.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 41,329.00 **4,164.00**
- List Item Discount on L Items 25.00/25.00% (\$\$) 8,547.25 851.00

Total Parts (\$\$) 32,781.75 **3,313.00**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO RNR ACCIDENT DAMAGE PARTS, CUT / WELD, KNOCK & REALIGN	New	3,600.00	600.00
2	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA	New	3,300.00	600.00
3	TO RUST PROOF ACCIDENT AFFECTED AREA	New	400.00	30.00
4	TO RNR REAR WINDSCREEN	New	400.00	0.00
5	TO RNR REAR BOOT MECHANISM	New	400.00	0.00
6	TO RNR UPHOLSTERY, GARNISH AND ATTACHMENT PARTS	New	800.00	0.00
7	TO RNR REVERSE SENSOR & CHECK FUNCTION	New	150.00	30.00
8	TO RNR EXHAUST SYSTEM AND ATTACHMENT PARTS	New	450.00	0.00
9	TO CHECK WIRING LAYOUT AND BOOTLID LAMP FUNCTION	New	150.00	0.00
10	TO CHECK WIRING LAYOUT AND TAIL LAMP FUNCTION	New	150.00	30.00
11	TO DO DIAGNOSIS AND RESET, REPROGRAM OR CODING FAULT CODE	New	800.00	0.00
12	TO DO WATER LEAK TEST	New	120.00	30.00
13	TO RNR FUEL TANK TO ASSIST WORK LOAD	New	450.00	0.00
Gross Labour Cost (\$\$)			11,170.00	1,320.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >