



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM20011214/Uga3q2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811

Date : 17-11-2020



ATTN: CYNTHIA LOH

Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHD 9534B	Veh. Inspected	SJT 2402L
Policy No.	VFX/P2348706	Coverage (\$)	0.00
Claim No.	S0M02VAR	Excess (\$)	0.00
Assign From		Assign Date	15/10/2020

2. Vehicle Particulars & Condition

Make & Model	TOYOTA COROLLA AXIO (A)	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	NZE1416120125	Colour	BLACK
Odometer	149635	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/70 R14	DUNLOP	6 mm
L/H Front Tyre	195/70 R14	DUNLOP	6 mm
R/H Rear Tyre	195/70 R14	DUNLOP	6 mm
L/H Rear Tyre	195/70 R14	DUNLOP	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	09/10/2020	Inspection Date	16/10/2020
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	-----------------------