

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG20011215/AQF3E2

Date: 05/03/2021

REFERENCE

Insured/Claimant:	JASVINPAL SINGH NARULLA	Policy No:	2070104382	
Date of Loss:	13/10/2020	Nature of Claim:	OD	Claim No: 8280980567SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMT9026H	Engine No:	CZD896135
Make & Model:	AUDI Q3, 1.4 TFSI (A)	Chassis No:	WAUZZZF34L1108250
Reg. Date:	23/07/2020 (Man. Year: 2020)	Odometer:	3224 km
Colour:	Black		
Engine Capacity:	1395 cc		
Market Value/New Car Price:	S\$150,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/65 R17	Rear Tyre Size:	215/65 R17
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,233.00	2,847.04	1,385.96	32.74
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,522.00	2,322.00	1,200.00	34.07
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,755.00	5,169.04	2,585.96	33.35
- Excess (S\$)	800.00	800.00	0.00	0.00
(S\$)	6,955.00	4,369.04	2,585.96	37.18
+ GST 7.00/7.00% (S\$)	486.85	305.83	181.02	37.18
Nett Amount (S\$)	7,441.85	4,674.87	2,766.98	37.18

INSPECTION

Date of Assignment:	16/10/2020		
Date Inspected:	15/10/2020	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	4.0 days		

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR - LH	Dented	2,639.00 FS	*2,111.20 FS
2	1		*REAR OUTER DOOR SEAL - LH	Necessary	134.00 FS	*106.80 FS
3	1		*REAR DOOR ATTACHMENT PARTS	Not Necessary	307.00 FS	*- FS
4	1		*REAR DOOR CATCH	Not Necessary	119.00 FS	*- FS
5	1		*REAR DOOR COVER - LH	Cut	254.00 FS	*202.80 FS
6	1		*REAR WHEEL COVER - LH	Cut	265.00 FS	*212.00 FS
7	1		*FRONT DOOR COVER - LH	Cut	265.00 FS	*212.00 FS
8	1		*SUNDRIES	Necessary	250.00 FS	*2.24 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	4,233.00	2,847.04
--------------------	----------	----------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER LHS REAR DOORS MULTILOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	New	280.00	280.00
2	TO DISMANTLE AND REINSTALL LHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL LHS WING MIRROR ASSY.	New	400.00	250.00
3	TO DISMANTLE AND RENEW LHS REAR DOOR. TO REPAIR LHS FRONT DOOR. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	New	1,000.00	500.00
4	TO RESPRAY LHS REAR DOOR AND LHS FRONT DOOR.	New	1,650.00	1,100.00
5	TO CARRY OUT DIAGNOSTIC CHECK.	New	192.00	192.00
Gross Labour Cost (\$\$)			3,522.00	2,322.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >