Adjuster Report Page 1 of 3

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/EGI20011216/R1SD3Q2

Date: 20/11/2020

REFERENCE

Price:

Handling Insurer: ERGO Insurance Pte. Ltd. Policy No:

Claimant SBS6395Y **Insured Vehicle No:** YP4279G

Vehicle No:

Date of Loss: ΤP 06/10/2020 Nature of Claim: Claim No: CDMCG20001482

DESCRIPTION & IDENTIFICATION OF VEHICLE

SBS6395Y Reg No:

MERCEDES-BENZ CITARO O530, 6.4 D AT Make & Model: Engine No: 902926C0996382

TURBO ABS (A)

Reg. Date: 03/06/2013 (Man. Year: 2012) Chassis No: WEB62808323124810 Odometer: 448256 km

Colour: Green **Engine Capacity:** 6374 cc

Market Value/New Car

N/A

Market Value/New Car Price Sum Insured (S\$):

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 275/70R22.5 Rear Tyre Size: 275/70R22.5(D) Front Left Side: Michelin 8 mm Rear Left Side: Michelin 8/8 mm Front Right Side: Rear Right Side: Michelin 8/8 mm Michelin 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	923.12	923.12	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	650.00	325.00	325.00	50.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$) + GST 7.00/7.00% (S\$)	1,573.12	1,248.12	325.00	20.66
	110.12	87.37	22.75	20.66
Nett Amount (S\$)	1,683.24	1,335.49	347.75	20.66

INSPECTION

Date of Assignment: 15/10/2020

19/10/2020 Inspected At: Tower Transit Singapore Pte Ltd (HQ) Date Inspected:

21 Bulim Drive, Bulim Bus Depot

Singapore 648170

Estimated Period of Repair: 1.0 days

Adjuster: MOHD RASUL Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 2 of 3

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 20 Nov 2020)

Parts: N/A MERCEDES-BENZ CITARO 0530 6.4 D AT TURBO ABS (A) (Model not available in

database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SBS6395Y)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No. Qty Part No.	Particulars	Condition	Repairer's	Amount
1 1	*O/S/R TAIL LAMP ASSY	Cracked	923.12 FS	*923.12 FS
F=Franchise part. S=SpcNett.				
		Total Parts (S\$)	923.12	923.12

Report was unsubmitted during this print-out.

Adjuster Report Page 3 of 3

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			_
1	TO DISMANTLE & REPLACE DAMAGED PARTS	New	650.00	325.00
	Gross Labour Cost (S\$)		650.00	325.00
Report was unsubmitted during this print-out.				

< END OF ESTIMATES >