

Date : 13.10.2020

**RE-VEHICLE REPAIR QUOTATION**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- Insurance Company
- Vehicle Registration
- Name of Insured
- Policy Number
- Date of Accident
- Type of Claim
- Model
- Chassis No.

Insurance Company: \_\_\_\_\_  
Vehicle Registration: \_\_\_\_\_  
Name of Insured: \_\_\_\_\_  
Policy Number: \_\_\_\_\_  
Date of Accident: \_\_\_\_\_  
Type of Claim: \_\_\_\_\_  
Model: \_\_\_\_\_  
Chassis No.: \_\_\_\_\_

Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer: \_\_\_\_\_  
Signature: \_\_\_\_\_  
Date: \_\_\_\_\_

2 Day S. Gue Qiang  
P/P 82880282  
After repair photos 19/10/2020

China & Taiping Insurance  
SMU7545J

02.10.2020  
3rd Party Claim  
MB GLC300  
W1N2533842F801286

We are please to submit our estimate of repairs to the above mention vehicle.

|   |                                | Parts       | Labour |
|---|--------------------------------|-------------|--------|
| 1 | REAR BUMPER X MN               | \$ 1,251.01 |        |
| 2 | REAR BUMPER SKIRT X NN         | \$ 729.14   |        |
| 3 | REAR BUMPER CHROME X MN        | \$ 156.40   |        |
| 4 | REAR BUMPER LH CHROME - SCR    | \$ 179.22   | ✓      |
| 5 | REAR BUMPER EXHAUST TIP - BT   | \$ 80.51    | ✓      |
| 6 | REAR BUMPER FIN - Ent          | \$ 201.34   | ✓      |
| 7 | FRONT BUMPER SENSOR RING - nbc | \$ 16.00    | ✓      |

Sub Total Parts \$ 2,613.62 477.07  
Less 10% \$ 261.36  
Total Parts \$ 2,352.26 429.36

|                |                                                                                                                                                                      |    |          |        |
|----------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------|----|----------|--------|
| 1              | Sundries                                                                                                                                                             | \$ | 100.00   | 10     |
| 2              | Wiring connection and check.                                                                                                                                         | \$ | 100.00   | X NN   |
| 3              | Labour charges to dismantle & refix rear bumper<br>front fog lamp cover, side retainer, chrome lower<br>To repair and adjust affected portion to specific dimension. | \$ | 500.00   | 180    |
| 4              | rear rear<br>To spray paint front bumper, front lh fender<br>and all other accident affected portion                                                                 | \$ | 500.00   | 100    |
| 5              | rear<br>Remove and replace front bumper sensor                                                                                                                       | \$ | 150.00   | 40     |
| 6              | To conduct ECU programming, check and<br>clear fault codes, restore programme modules - photos/repair                                                                | \$ | 350.00   | 100    |
| Total (Labour) |                                                                                                                                                                      | \$ | 1,700.00 | 430    |
| Sub Total :    |                                                                                                                                                                      | \$ | 4,052.26 |        |
| GST 7%         |                                                                                                                                                                      | \$ | 283.66   |        |
| Grand Total :  |                                                                                                                                                                      | \$ | 4,335.92 | 859.36 |

The above estimates are base on visual inspection and it is possible that further materials and labour may be required upon dismantling. Should this occur, we will submit supplementary quotation for further approval.