

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20011220/GSD3Q2

Date: 29/12/2020

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSNW00119522002

**Claimant
Vehicle No :** SMU7545J

**Insured
Vehicle No :** S5367CD

Date of Loss: 02/10/2020

Nature of
Claim: TP

Claim
No: SNM20D203768C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMU7545J**

Make & Model: MERCEDES-BENZ GLC300, 2.0 4MATIC COUPE
(R19 LED) (A)

Engine No: 26492080051236

Reg. Date: 27/08/2020 (Man. Year: 2020)

Chassis No: W1N2533842F801286

Colour: Grey

Odometer: 3020 km

Engine Capacity: 1991 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 255/50R19

Rear Tyre Size:

255/50R19

Front Left Side: Pirelli 8 mm

Rear Left Side:

Pirelli 8 mm

Front Right Side: Pirelli 8 mm

Rear Right Side:

Pirelli 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,452.26	439.36	2,012.90	82.08
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,600.00	420.00	1,180.00	73.75
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,052.26	859.36	3,192.90	78.79
+ GST 7.00/7.00% (S\$)	283.66	60.16	223.50	78.79
Nett Amount (S\$)	4,335.92	919.52	3,416.40	78.79

INSPECTION

Date of Assignment: 16/10/2020

Date Inspected: 19/10/2020 Inspected At:

TTS Eurocars Pte Ltd (Sin Ming)
383 Sin Ming Drive, TTS Centre
Singapore 575717

Estimated Period of Repair: 2.0 days

Adjuster: XING GUO QIANG

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 29 Dec 2020)
Parts:	M1-SUV	MERCEDES-BENZ GLC300 2.0 4MATIC COUPE (R19 LED) (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMU7545J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Not Necessary	1,251.01 FL	*- FL
2	1		*REAR BUMPER SKIRT	Not Necessary	729.14 FL	*- FL
3	1		*REAR BUMPER CHROME	Not Necessary	156.40 FL	*- FL
4	1		*REAR BUMPER LH CHROME	Scratched	179.22 FL	*179.22 FL
5	1		*REAR BUMPER EXHAUST TIP	Bent	80.51 FL	*80.51 FL
6	1		*REAR BUMPER FIN	Cut	201.34 FL	*201.34 FL
7	1		*FRONT BUMPER SENSOR RING	Necessary	16.00 FL	*16.00 FL
8	1		*SUNDRIES	Necessary	100.00 FS	*10.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	2,713.62	487.07
- List Item Discount on L Items 10.00/10.00% (S\$)	261.36	47.71
Total Parts (S\$)	2,452.26	439.36

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	WIRING CONNECTION AND CHECK	New	100.00	0.00
2	LABOUR CHARGES TO DISMANTLE & REFIX REAR BUMPER,SIDE RETAINER,CHROME LOWER.TO REPAIR AND ADJUST AFFECTED PORTION TO SPECIFIC DIMENSION	New	500.00	180.00
3	TO SPRAY PAINT REAR BUMPER,REAR LH FENDER AND ALL OTHER ACCIDENT AFFECTED PORTION	New	500.00	100.00
4	REMOVE AND REPLACE REAR BUMPER SENSOR	New	150.00	40.00
5	TO CONDUCT ECU PROGRAMMING,CHECK AND CLEAR FAULT CODES,RESTORE PROGRAMME MODULES	New	350.00	100.00
Gross Labour Cost (\$\$)			1,600.00	420.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >