

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20011222/UVF3E2

Date: 01/12/2020

REFERENCE

| | | | |
|------------------------------|---|-----------------------------|-------------------------|
| Handling Insurer: | China Taiping Insurance (Singapore) Pte. Ltd. | Policy No: | DMCVSNW00067742000 |
| Claimant Vehicle No : | GBG4808A | Insured Vehicle No : | YN8976L |
| Date of Loss: | 08/10/2020 | Nature of Claim: | TP |
| | | Claim No: | SNM20D203859/C02/THAMYL |

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|-----------------------------|---|-------------|-------------------|
| Reg No: | GBG4808A | | |
| Make & Model: | NISSAN NV200, 1.5 L ABS AIRBAG 2WD 6DR EURO 5 (M) | Engine No: | K9KC400D057140 |
| Reg. Date: | 21/08/2017 (Man. Year: 2017) | Chassis No: | VSKYBAM20Z0145575 |
| Colour: | White | Odometer: | 96104 km |
| Engine Capacity: | 1461 cc | | |
| Market Value/New Car Price: | N/A | | |
| Sum Insured (S\$): | Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: |

CONDITION OF TYRES

| | | | |
|-------------------|-------------|------------------|-------------|
| Front Tyre Size: | 175/70 R14 | Rear Tyre Size: | 175/70 R14 |
| Front Left Side: | Falken 6 mm | Rear Left Side: | Falken 6 mm |
| Front Right Side: | Falken 6 mm | Rear Right Side: | Falken 6 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|-------------------------------|-----------------|-----------------|---------------|--------------|
| Parts | 2,176.57 | 1,810.00 | 366.57 | 16.84 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 1,025.59 | 781.99 | 243.60 | 23.75 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Gross Total (S\$) | 3,202.16 | 2,591.99 | 610.17 | 19.05 |
| + GST 7.00/7.00% (S\$) | 224.15 | 181.44 | 42.71 | 19.05 |
| Nett Amount (S\$) | 3,426.31 | 2,773.43 | 652.88 | 19.05 |

INSPECTION

| | | |
|-----------------------------|------------|---|
| Date of Assignment: | 20/10/2020 | |
| Date Inspected: | 21/10/2020 | Inspected At: 53 Ubi Ave 1 #02-24 |
| | | Repairer : Goldbell Engineering Pte Ltd |
| Estimated Period of Repair: | 3.0 days | |

Adjuster: MARCUS CHUA

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

| | | |
|----------------------|--|--|
| Part Source: | (Last Synchronised: 30 Nov 2020) | |
| Parts: | N/A | NISSAN NV200 1.5 L ABS AIRBAG 2WD 6DR EURO 5 (M) (Model not available in database) |
| Labour: | Repairer's | (Price-denominated Standard List) |
| Print Code: | (Unsubmitted, no print-code for GBG4808A) | |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page | |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *. | |

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|------------------------------|-----|----------|----------------------------|---------------|--------------------------|--------------------------|
| 1 | 1 | | *BONNET | Dented | 525.00 F | *525.00 F |
| 2 | 1 | | *FRONT AIRBAG SENSOR | Not Necessary | 199.38 F | *- F |
| 3 | 1 | | *FRONT BUMPER | Cut | 350.00 F | *350.00 F |
| 4 | 1 | | *GRILLE | Cracked | 300.00 F | *300.00 F |
| 5 | 1 | | *L/F BUMP CORNER MLDG | Cut | 208.00 F | *208.00 F |
| 6 | 1 | | *R/F BUMP CORNER MLDG | Cut | 208.00 F | *208.00 F |
| 7 | 1 | | *RAD GRILLE BADGE | Cracked | 69.00 F | *69.00 F |
| 8 | 1 | | *SUNDRY PARTS (+2.0%) | Not Necessary | 37.19 FS | *- FS |
| 9 | 1 | | *COM, STICKER COM, STICKER | Necessary | 280.00 FS | *150.00 FS |
| F=Franchise part. S=SpcNett. | | | | | | |
| | | | | | Total Parts (S\$) | 2,176.57 1,810.00 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|--------------------------------|-----------------------------------|----------|-----------------|---------------|
| <u>Labour Items</u> | | | | |
| 1 | 85.0 WU X 42.00 SGD/H | New | 357.00 | 113.40 |
| 2 | ALIGNMENT - MEASURING WORK | New | 16.80 | 16.80 |
| 3 | LABOUR COST 96.0 WU X 42.00 SGD/H | New | 403.20 | 403.20 |
| 4 | MATERIAL COST | New | 248.59 | 248.59 |
| Gross Labour Cost (S\$) | | | 1,025.59 | 781.99 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >