

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG20011234/KTD3E2

Date: 21/01/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800100199		
Claimant Vehicle No :	FBR751Y	Insured Vehicle No :	SMD4758X		
Date of Loss:	09/10/2020	Nature of Claim:	TP	Claim No:	1253296503SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBR751Y	Engine No:	G3K9E0029555
Make & Model:	YAMAHA MT-15, 155cc	Chassis No:	MH3RG5610KK004688
Reg. Date:	17/02/2020 (Man. Year: 2019)	Odometer:	8801 km
Colour:	Metallic Blue/Black		
Engine Capacity:	155 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	110/70 R17	Rear Tyre Size:	140/70 R17
Front Left Side:	Bridgestone 5 mm	Rear Left Side:	Bridgestone 4 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,552.05	3,188.20	5,363.85	62.72
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,830.00	330.00	1,500.00	81.97
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	10,382.05	3,518.20	6,863.85	66.11
Approved Total (Overridden) (\$\$)		2,800.00		
(\$\$)	10,382.05	2,800.00	7,582.05	73.03
+ GST 7.00/7.00% (\$\$)	726.74	196.00	530.74	73.03
Nett Amount (\$\$)	11,108.79	2,996.00	8,112.79	73.03

INSPECTION

Date of Assignment:	16/10/2020		
Date Inspected:	16/10/2020	Inspected At:	Yee Auto Service (HQ) 160 Sin Ming Drive #02-17 Sin Ming Autocity Singapore 575722
Estimated Period of Repair:	4.0 days		

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but

any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR NUMBER PLATE	Bent	50.00 FS	*12.00 FS
2	1		*BRAKE LEVER	Dented	68.00 F	*68.00 FL
3	1		*SET BRAKE PEDAL	Repair	68.00 F	*- FL
4	1		*EXHAUST MUFFLER	Repair	480.00 F	*- FL
5	1		*FORK OIL SEAL - LH	Not Necessary	38.00 F	*- FL
6	1		*FORK OIL SEAL - RH	Not Necessary	38.00 F	*- FL
7	1		*FRONT BRAKE CALIPER	Serviceable	210.00 F	*- FL
8	1		*FRONT DISC BRAKE	Serviceable	125.00 F	*- FL
9	1		*FRONT FAIRING BRACKET - LH	Repair	42.00 F	*- FL
10	1		*FRONT FAIRING BRACKET - RH	Repair	42.00 F	*- FL
11	1		*FRONT FAIRING - RH	Dented / Cut	288.00 F	*288.00 FL
12	1		*FRONT FORK - LH	Serviceable	386.00 F	*- FL
13	1		*FRONT FORK - RH	Serviceable	386.00 F	*- FL
14	1		*FRONT FORK TUBE - LH	Serviceable	222.00 F	*- FL
15	1		*FRONT FORK TUBE - RH	Serviceable	222.00 F	*- FL
16	1		*FRONT SIGNAL LAMP - RH	Broken	75.00 F	*75.00 FL
17	1		*FRONT WHEEL BEARING	Not Necessary	28.00 F	*- FL
18	1		*HANDLE RUBBER - RH	Serviceable	38.00 F	*- FL
19	1		*HEAD LAMP	Serviceable	280.00 F	*- FL
20	1		*HEADLAMP COWLING	Serviceable	290.00 F	*- FL
21	1		*IU UNIT	Serviceable	180.00 F	*- FL
22	1		*REAR BODY SIDE COVER - RH	Serviceable	290.00 F	*- FL
23	1		*REAR BODY SIDE COVER STICKER - RH	Not Necessary	120.00 F	*- FL
24	1		*ENGINE BLOCK COVER (LOWER)	Dented / Cut	342.00 F	*342.00 FL
25	1		*FRONT SIDE STAND FOOT ENLARGE - RH	Repair	115.20 F	*- FL
26	1		*FUEL TANK	Repair	841.70 F	*- FL
27	1		*FRONT HANDLE BAR BALANCER - RH	Dented	115.20 F	*115.20 FL
28	1		*SIDE COVER STICKER - RH	Necessary	90.00 F	*90.00 FL
29	1		*COVER FROME - RH	Dented	182.70 F	*182.70 FL
30	1		*BATTERY	Serviceable	60.00 F	*- FL
31	1		*FRONT HEADLAMP COVER	Cut	288.00 F	*288.00 FL
32	1		*FRONT NUMBER PLATE	Dented	50.00 FS	*10.00 FS
33	1		*STEERING CONE W/BEARING	Not Necessary	68.00 F	*- FL
34	1		*WING MIRROR - LH	Serviceable	144.00 F	*- FL
35	1		*WING MIRROR - RH	Dented	144.00 F	*144.00 FL
36	1		*HANDLE BAR BRACKET	Bent	180.00 F	*180.00 FL
37	1		*FRONT FORK HOLDER BRACKET	Distorted	380.00 F	*380.00 FL
38	1		*FRONT HANDLE BAR	Bent	320.85 F	*320.85 FL
39	1		*REAR CARRY BOX	Dented / Cut	495.85 F	*495.85 FL
40	1		*REAR CARRY BOX BRACKET	Repair	220.15 F	*- FL
41	1		*REAR NUMBER PLATE HANDLE	Distorted	260.15 F	*260.15 FL
42	1		*EXHAUST MUFFLER COVER	Dented	288.25 F	*288.25 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,552.05	3,540.00
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	351.80
Total Parts (\$\$)	8,552.05	3,188.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE & REPLACE DAMAGED PARTS. PANEL BEAT WHERE NECESSARY	New	800.00	180.00
2	TO PUTTY, APPLY PRIMER & SPRAY PAINT ON THE AFFECTED PORTION	New	700.00	0.00
3	TO ALIGN MAIN BODY FRAME	New	280.00	120.00
4	TO TOW VEHICLE TO WORKSHOP	New	50.00	30.00
Gross Labour Cost (\$\$)			1,830.00	330.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >