

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG20011240/AVF3E2

Date: 02/03/2021

REFERENCE

Insured/Claimant:	GOH KIAN HENG ALVIN	Policy No:	1800012970		
Date of Loss:	06/10/2020	Nature of Claim:	OD	Claim No:	2000193199SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLW3344A	Engine No:	CVK052016
Make & Model:	AUDI A5, 2.0 SPORTBACK (A)	Chassis No:	WAUZZZF53JA054678
Reg. Date:	07/02/2018 (Man. Year: 2017)	Odometer:	48110 km
Colour:	Black		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$130,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/40 R18	Rear Tyre Size:	245/40 R18
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,198.00	5,658.56	4,539.44	44.51
Miscellaneous Items	0.00	0.00	0.00	
Labour	13,312.00	5,332.00	7,980.00	59.95
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	23,510.00	10,990.56	12,519.44	53.25
- Excess (S\$)	1,800.00	1,800.00	0.00	0.00
(S\$)	21,710.00	9,190.56	12,519.44	57.67
+ GST 7.00/7.00% (S\$)	1,519.70	643.34	876.36	57.67
Nett Amount (S\$)	23,229.70	9,833.90	13,395.80	57.67

INSPECTION

Date of Assignment:	16/10/2020		
Date Inspected:	16/10/2020	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	7.0 days		

Adjuster: ADRIAN LING

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR FENDER - RH	Dented	2,472.00 FS	*1,852.80 FS
2	1		*SIDE WINDOW - RH	Not Necessary	709.00 FS	*- FS
3	1		*REAR DOOR - RH	Distorted	3,091.00 FS	*2,472.80 FS
4	1		*REAR DOOR OUTER SEAL - RH	Necessary	220.00 FS	*175.60 FS
5	1		*BONDING AGENT	Not Necessary	47.00 FS	*- FS
6	1		*CLEANING SOLUTION	Not Necessary	65.00 FS	*- FS
7	1		*REAR DOOR ATTACHMENT PARTS	Not Necessary	128.00 FS	*- FS
8	1		*REAR DOOR CATCH	Damaged	119.00 FS	*94.80 FS
9	1		*SIDE MEMBER TRIM - RH	Repair	816.00 FS	*- FS
10	1		*SILL MEMBER TRIM ATTACHMENT PARTS	Damaged	129.00 FS	*102.80 FS
11	1		*SIDE MEMBER TRIM ADHESIVE TAPES	Necessary	210.00 FS	*167.60 FS
12	1		*REAR ALUMINIUM RIM - RH	Not Necessary	1,012.00 FS	-
13	1		*1/4 GLASS	Not Necessary	100.00 FS	*- FS
14	1		*METAL FILLER POWDER	Necessary	280.00 FS	*280.00 FS
15	1		*STONE CHIP	Necessary	180.00 FS	*180.00 FS
16	1		*CAVITY WAX	Necessary	140.00 FS	*140.00 FS
17	1		*ACRYLIC SEALANT	Necessary	180.00 FS	*180.00 FS
18	1		*SUNDRIES	Necessary	300.00 FS	*12.16 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 10,198.00 5,658.56

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE	New	360.00	0.00
2	TO RENEW 1/4 GLASS TO FACILITATE FENDER RENEWAL	New	300.00	0.00
3	TO INSTALL SOLAR FILM FOR 1/4 GLASS	New	400.00	0.00
4	TO CARRY OUT WATER SEEPAGE TEST FOR 1/4 GLASS	New	200.00	0.00
5	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT	New	1,400.00	0.00
6	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC (* Check)	New	1,400.00	280.00
7	TO REMOVE AND TRANSFER RHS REAR DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES	New	280.00	280.00
8	TO DISMANTLE REAR BUMPER, RHS REAR DOOR AND RHS SILL PANEL TRIM. TO RENEW RHS REAR DOOR AND RHS SILL PANEL TRIM. CUT OUT AND WELD RHS REAR FENDER. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	4,500.00	2,000.00
9	TO RESPRAY REAR BUMPER, RHS REAR FENDER, DOOR ENTRANCES, RHS REAR DOOR, DOOR HANDLES, RHS SILL PANEL, RHS SILL PANEL TRIM, ROOF CHANNEL, DRAIN PANEL AND END PANELLING. TO CARRY OUT STONE CHIP TREATMENT AND JOINT SEALER WORKS	New	4,000.00	2,300.00
10	TO RENEW RHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	280.00
11	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			13,312.00	5,332.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >