

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CC3/AIG20011241/AQF3E2

Date: 14/01/2022

REFERENCE

Insured/Claimant:	QIN XIANG	Policy No:	1900256402		
Date of Loss:	02/10/2020	Nature of Claim:	OD	Claim No:	1037319025SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMR296P		
Make & Model:	AUDI A3, 999cc SEDAN TFSI (A)	Engine No:	CHZC35258
Reg. Date:	14/12/2019 (Man. Year: 2019)	Chassis No:	WAUZZZ8V0LA002554
Colour:	Black	Odometer:	12416 km
Engine Capacity:	999 cc		
Market Value/New Car Price:	S\$113,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	19,998.60	12,168.96	7,829.64	39.15
Miscellaneous Items	0.00	0.00	0.00	
Labour	25,932.00	12,157.00	13,775.00	53.12
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	45,930.60	24,325.96	21,604.64	47.04
- Excess (S\$)	4,000.00	4,000.00	0.00	0.00
(S\$)	41,930.60	20,325.96	21,604.64	51.52
+ GST 7.00/7.00% (S\$)	2,935.14	1,422.82	1,512.32	51.52
Nett Amount (S\$)	44,865.74	21,748.78	23,116.96	51.52

INSPECTION

Date of Assignment:	05/10/2020		
Date Inspected:	05/10/2020	Inspected At:	24 Benoi Sector Repairer: Premium Automobiles Pte Ltd
Estimated Period of Repair:	20.0 days		

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN	Not Necessary	805.00 FS	*- FS
2	1		*PRIMER	Necessary	19.00 FS	*14.96 FS
3	1		*REAR FENDER - RH	Buckled	2,305.00 FS	*1,844.00 FS
4	1		*SIDE WINDOW - RH	Necessary	563.00 FS	*450.40 FS
5	1		*REAR BUMPER	Distorted	1,944.00 FS	*1,555.20 FS
6	1		*REAR BUMPER FIXING PARTS	Not Necessary	191.00 FS	*- FS
7	1		*REAR BUMPER GUIDE SECTION - LH/RH	O/S Damaged	32.00 FS	*12.56 FS
8	2		*REAR BUMPER LOCKING MECHANISM	Necessary	59.00 FS	*46.72 FS
9	1		*REAR BUMPER SPOILER	Deformed	234.00 FS	*187.20 FS
10	1		*REAR LIGHT REFLECTOR - LH/RH	O/S Cracked	82.00 FS	*32.24 FS
11	1		*LED TAIL LIGHT - LH/RH	O/S Cut	1,734.00 FS	*1,387.20 FS
12	1		*TAIL LIGHT TRIM - LH/RH	O/S Cut	60.00 FS	*23.36 FS
13	1		*REAR BUMPER BRACKET - LH	Damaged	27.00 FS	*21.12 FS
14	1		*REAR BUMPER BRACKET - RH	Not Necessary	28.00 FS	*- FS
15	1		*REAR BUMPER GUIDE SECTION - LH/RH	O/S Cracked	132.00 FS	*52.16 FS
16	4		*REAR PARKING AID SENSOR - INNER/OUTER	Not Necessary	968.00 FS	*- FS
17	4		*REAR PARKING AID SEAL RING	Not Necessary	14.00 FS	*- FS
18	1		*REAR BUMPER WIRING SET	Not Necessary	510.00 FS	*- FS
19	1		*REAR CROSS PANEL	Dented	356.00 FS	*284.40 FS
20	1		*REAR CROSS PANEL REINFORCEMENT	Dented	725.00 FS	*579.60 FS
21	1		*REAR LID	Dented	2,564.00 FS	*2,051.20 FS
22	1		*REAR LID ATTACHMENT PARTS	Not Necessary	291.00 FS	*- FS
23	2		*REAR LID HINGE - LH/RH	Bent	506.00 FS	*202.40 FS
24	1		*REAR LID FLAP GASKET	Not Necessary	203.00 FS	*- FS
25	1		*REAR LID LOCK STRIKER	Not Necessary	49.00 FS	*- FS
26	1		*REAR LID LOCK	Not Necessary	184.00 FS	*- FS
27	1		*PACKING ADHENSIVE	Necessary	18.00 FS	*14.40 FS
28	1		*REAR LID LOCK ACTUATOR	Damaged	1,330.00 FS	*1,064.00 FS
29	1		*AUDI EMBLEM	Necessary	122.00 FS	*97.60 FS
30	1		*A3 INSCRIPTION	Necessary	95.00 FS	*75.36 FS
31	1		*REAR LID TRIM PANEL	Not Necessary	303.00 FS	*- FS
32	1		*REAR CROSS PANEL TRIM	Not Necessary	153.00 FS	*- FS
33	1		*REAR NO PLATE	Not Necessary	60.00 FS	*- FS
34	1		*REAR WINDSCREEN SEALANT	Not Necessary	200.00 FS	*- FS
35	1		*1/4 GLASS SEALANT	Necessary	200.00 FS	*100.00 FS
36	1		*METAL FILLER POWDER	Necessary	280.00 FS	*140.00 FS
37	1		*STONE CHIP	Not Necessary	180.00 FS	*- FS
38	1		*CAVITY WAX	Necessary	140.00 FS	*140.00 FS
39	1		*ACRYLIC SEALANT	Necessary	180.00 FS	*180.00 FS
40	1		*SUNDRIES	Necessary	500.00 FS	*171.04 FS
41	1		*REAR SILENCER	Bent	677.00 FS	*569.60 FS
42	1		*REAR SILENCER DUAL CLIP	Necessary	55.00 FS	*44.96 FS
43	1		*KEYLESS CONTROL UNIT	Damaged	69.00 FS	*55.12 FS
44	1		*REAR WHEEL HOUSING LINER ADAPTER - RH	Crumpled	37.00 FS	*29.52 FS
45	2		*CONNECTING PLATE - LH/RH	Distorted	286.00 FS	*228.00 FS
46	1		*REAR BUMPER REINFORCEMENT (Supplementary)	Bent	451.60 FS	*451.60 FS
47	1		*REAR SILENCER RETAINER EXHAUST SYSTEM	Bent	77.00 F	*63.04 F

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 19,998.60 12,168.96

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CARRY OUT FIRST MEASUREMENT TEST ON CAR O-LINER.	New	800.00	800.00
2	TO REPLACE VEHICLE ON CAR O-LINER.	New	1,800.00	1,800.00
3	TO REMOVE AND REINSTALL REAR PARKING AID, CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE.	New	280.00	280.00
4	TO REMOVE AND TRANSFER REAR LIDS CONVENIENCE LOCK SYSTEM AND WIRE HARNESS FOR TAIL LIGHTS.	New	280.00	280.00
5	TO RENEW REAR WINDSCREEN AND BOTH REAR 1/4 GLASS TO FACILITATE FENDER RENEWAL.	New	900.00	300.00
6	TO INSTALL SOLAR FILM FOR REAR WINDSCREEN AND BOTH REAR 1/4 GLASS.	New	400.00	200.00
7	TO CARRY OUT WATER SEEPAGE TEST FOR REAR WINDSCREEN.	New	200.00	0.00
8	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT.	New	1,400.00	0.00
9	TO DISLODGE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC.	New	1,400.00	0.00
10	TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID. CUT OUT AND WELD BOTH REAR FENDERS, LHS SILL PANEL AND REAR END PANELLING. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	New	10,000.00	4,250.00
11	TO RESPRAY REAR BUMPER, REAR LID, LHS REAR FENDER, RHS REAR FENDER, DOOR ENTRANCES, LHS SILL PANEL, RHS SILL PANEL, ROOF CHANNELS, DRAIN PANELS, LHS B PILLAR, END PANELLING, REAR LID HINGES AND SPARE WHEEL HOUSING. TO CARRY OUT STONE CHIP TREATMENT AND JOINT SEALER WORKS.	New	7,800.00	3,575.00
12	TO CARRY OUT DIAGNOSTIC CHECK.	New	192.00	192.00
13	TO REMOVE AND RENEW REAR EXHAUST SILENCER AND ALIGN TO POSITION.	New	480.00	480.00
Gross Labour Cost (\$\$)			25,932.00	12,157.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >