

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	16 Oct 2020		16 Oct 2020 15:04 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	GRAB RENTALS PTE LTD , Co. Reg. No.: 201617200G, GST No.: 201617200G		
Main Claimant:	MUHAMMAD TAJUDDIN BIN ISMAIL , ID: S8707913I		
Vehicle Reg. No.:	FBP8999H	Date of Loss:	15/10/2020 00:00 - :59 [14 Months and 15 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 629924	Policy/Cover Note No.:	29141713MKF (Comprehensive) Coverage: 01/02/2020 - 31/12/2020
Vehicle Reg. No. (Insured):	SLP9053L	Policy No. (Claimant):	
		Excess:	S\$3,000.00
Repairer:	Garage 13 Pte. Ltd. (HQ) 8 Kaki Bukit Avenue 4, #03-46 Premier, 415875 Kaki Bukit - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Katherine Wong - 6594 2544]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Imm.Advice due 17/10/2020]		
Adj Asg. Remarks:	on WP. Liab: NR. Disagree on SJE. Contact: JieYing / Priscilla @ 8797 0013		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.

Claim Documents

***FBP8999H (629924)**

[SLP9053L]

TP

MUHAMMAD TAJUDDIN BIN ISMAIL

Oct 15 2020 12:00AM

[GRAB RENTALS PTE LTD]

Garage 13 Pte. Ltd.

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View
[View in Browser](#)

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	19/10/20 09:45	Odometer Reading	 Load JPG	☒
2	19/10/20 09:46	General View	 Load JPG	☒
3	19/10/20 09:46	General View	 Load JPG	☒
4	19/10/20 09:46	General View	 Load JPG	☒
5	19/10/20 09:46	General View	 Load JPG	☒
6	19/10/20 09:46	General View	 Load JPG	☒
7	19/10/20 09:46	General View	 Load JPG	☒
8	19/10/20 09:46	General View	 Load JPG	☒
9	19/10/20 09:46	General View	 Load JPG	☒
10	19/10/20 09:46	General View	 Load JPG	☒
11	19/10/20 09:46	General View	 Load JPG	☒
12	19/10/20 09:46	General View	 Load JPG	☒
13	19/10/20 09:46	General View	 Load JPG	☒
14	19/10/20 09:46	General View	 Load JPG	☒
15	19/10/20 09:46	General View	 Load JPG	☒
16	19/10/20 09:46	General View	 Load JPG	☒
17	19/10/20 09:46	General View	 Load JPG	☒
18	19/10/20 09:46	General View	 Load JPG	☒
19	19/10/20 09:46	General View	 Load JPG	☒
20	19/10/20 09:46	General View	 Load JPG	☒
21	19/10/20 09:46	General View	 Load JPG	☒
22	19/10/20 09:46	General View	 Load JPG	☒
23	19/10/20 09:46	General View	 Load JPG	☒
24	19/10/20 09:46	General View	 Load JPG	☒
25	19/10/20 09:46	General View	 Load JPG	☒
26	19/10/20 09:46	General View	 Load JPG	☒
27	19/10/20 09:46	General View	 Load JPG	☒
28	19/10/20 09:46	General View	 Load JPG	☒
29	19/10/20 09:46	General View	 Load JPG	☒
30	19/10/20 09:46	General View	 Load JPG	☒
31	19/10/20 09:46	General View	 Load JPG	☒
32	19/10/20 09:46	General View	 Load JPG	☒
33	19/10/20 09:46	General View	 Load JPG	☒
34	19/10/20 09:46	General View	 Load JPG	☒
35	19/10/20 09:46	General View	 Load JPG	☒

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
36	19/10/20 09:46	General View	 Load JPG	☒
37	19/10/20 09:46	General View	 Load JPG	☒
38	19/10/20 09:46	General View	 Load JPG	☒
39	19/10/20 09:46	General View	 Load JPG	☒
40	19/10/20 09:46	General View	 Load JPG	☒
41	19/10/20 09:46	General View	 Load JPG	☒
42	19/10/20 09:46	General View	 Load JPG	☒
43	19/10/20 09:46	General View	 Load JPG	☒
44	19/10/20 09:46	General View	 Load JPG	☒
45	19/10/20 09:46	General View	 Load JPG	☒
46	19/10/20 09:46	General View	 Load JPG	☒
47	19/10/20 09:46	General View	 Load JPG	☒
48	19/10/20 09:46	General View	 Load JPG	☒
49	19/10/20 09:46	General View	 Load JPG	☒
50	19/10/20 09:46	General View	 Load JPG	☒
51	19/10/20 09:46	General View	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	16/10/20 14:45	PRI Email	 Load PDF	
2	16/10/20 14:45	Notice of Accident	 Load PDF	
3	16/10/20 14:48	Disagree on SJE	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

ResetSavePrint

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To:

☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/MSG20011243/GVF3S2**Date:** 28/10/2020REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 29141713MKF

Claimant Vehicle No : FBP8999H**Insured Vehicle No :** SLP9053L

Date of Loss: 15/10/2020

Nature of Claim: TP

Claim No: 629924

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **FBP8999H**

Make & Model: HONDA NSS 300A, 279cc

Engine No: NF07E2016769

Reg. Date: 31/07/2019 (Man. Year: 2019)

Chassis No: MLHNF0798J5000564

Colour: White

Odometer: 23799 km

Engine Capacity: 279 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 120/70-15

Rear Tyre Size: 140/70-14

Front Left Side: Pirelli 4 mm

Rear Left Side: Pirelli 4 mm

Front Right Side: 0 mm

Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 16/10/2020

Date Inspected: 16/10/2020 Inspected At:

149 Kaki Bukit Ave 1 Soon Lee Industrial Park

Singapore 416009

Repairer: Garage 13 Pte. Ltd.

Estimated Period of Repair: 2.0 days

Adjuster: XING GUO QIANG**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

10/28/2020

Adjuster Report

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000.00 - \$3,000.00

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 28 Oct 2020)	
Parts:	N/A	HONDA NSS 300A 279cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBP8999H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >