

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG20011248/KEA3Q2**Date:** 08/03/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999993928
Claimant Vehicle No :	SBP6575K	Insured Vehicle No :	GBE883T
Date of Loss:	18/08/2020	Nature of Claim:	TP
		Claim No:	0207743303SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SBP6575K	Engine No:	10398122137831
Make & Model:	MERCEDES-BENZ 300SEL, 3.0 (A)	Chassis No:	WDB1260252A608184
Reg. Date:	01/08/1991 (Man. Year: 1991)	Odometer:	383865 km
Colour:	Metallic Green		
Engine Capacity:	2962 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55 R16	Rear Tyre Size:	225/55 R16
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 8 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,978.98	5,080.36	3,898.62	43.42
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,790.00	630.00	1,160.00	64.80
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,768.98	5,710.36	5,058.62	46.97
Approved Total (Overridden) (S\$)		4,550.00		
Nett Amount (S\$)	10,768.98	4,550.00	6,218.98	57.75
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment:	16/10/2020	
Date Inspected:	19/10/2020	Inspected At: Autoworx House - Sin Ming (HQ) 176 SIN MING DRIVE #02-01 Singapore 575721
Estimated Period of Repair:	2.0 days	

Adjuster: KENNETH KONG**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR END PANEL	Repair	975.40 FN	*- FN
2	1		*REAR BUMPER	Buckled	2,150.40 FN	*2,150.40 FN
3	1		*BUMPER CHROME MOULDING CENTRE	Dented	1,150.00 FN	*1,150.00 FN
4	2		*REAR BUMPER SIDE CHROME TRIM	*Check	970.00 FN	*- FN
5	2		*REAR BUMPER SIDE RETAINER	Serviceable	213.40 FN	*- FN
6	2		*REAR BUMPER REINFORCEMENT ABSORBER	No such part	793.00 FN	*- FN
7	2		*REAR BUMPER BRACKET	*Check	390.00 FN	*- FN
8	1		*REAR BUMPER INNER PAD	No such part	345.00 FN	*- FN
9	1		*REAR END PANEL GARNISH	Serviceable	645.00 FN	*- FN
10	2		*TAIL LAMP ASSY	Scratched	1,900.00 FN	*1,900.00 FN
11	1		*SET REVERSE SENSOR 4 SENSOR TYPE	Dented	400.00 FS	*400.00 FS
					Sub Total (\$)	9,932.20 5,600.40
					- Nett Item Discount on N Items 10.00/10.00% (\$)	953.22 520.04
					Total Parts (\$)	8,978.98 5,080.36

F=Franchise part. S=SpcNett. N=NettItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REPLACE THE PARTS MENTIONED ABOVE ,PANEL BEAT AND REALIGN THE NECESSARY AFFECTED AREAS	New	800.00	250.00
2	TO CHECK WIRING SYSTEM	New	80.00	20.00
3	TO APPLY RUST PROOFING ON AFFECTED AREAS	New	150.00	0.00
4	TO APPLY WATERPROOF SEALANT ON AFFECTED AREAS	New	150.00	0.00
5	TO APPLY PUTTY & SPRAY PAINTING ON AFFECTED AREAS	New	450.00	300.00
6	TO INSTALL REVERSE SENSORS	New	80.00	60.00
7	TO REMOVE CAPRET ,TRIMMING TO ENABLE REPAIR	New	80.00	0.00
Gross Labour Cost (\$\$)			1,790.00	630.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >