

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20011260/QRA3Q2

Date: 12/04/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100432933
Claimant Vehicle No :	XE5519C	Insured Vehicle No :	SKW4810B
Date of Loss:	08/10/2020	Nature of Claim:	TP
		Claim No:	6046475790SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	XE5519C		
Make & Model:	ISUZU CYZ52R, 15.7 D (M)	Engine No:	6WG1439514
Reg. Date:	07/01/2020 (Man. Year: 2019)	Chassis No:	JALCYZ52RK7000039
Colour:	Blue	Odometer:	14844 km
Engine Capacity:	15681 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	375/80 R22.5	Rear Tyre Size:	375/80 R22.5
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,791.00	2,805.00	5,986.00	68.09
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,330.00	780.00	1,550.00	66.52
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	11,121.00	3,585.00	7,536.00	67.76
Approved Total (Overridden) (\$\$)		2,850.00		
Nett Amount (\$\$)	11,121.00	2,850.00	8,271.00	74.37
+ Loss of Use (3.0 x \$S\$170.00/day) (\$\$)		510.00		
	Nett Liability (\$\$)	3,360.00		

INSPECTION

Date of Assignment:	16/10/2020	Soon Seng Company (sg) Pte Ltd (HQ)
Date Inspected:	10/12/2020 Inspected At:	160 SIN MING DRIVE #04-05 SIN MING AUTOCITY
Estimated Period of Repair:	3.0 days	Singapore 575722

Adjuster: OI SUN PIN

Manager: Jaslin Kok Chin Yi

4/12/2021

Adjuster Report

any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Dented	3,650.00 F	*2,450.00 FL
2	1		*FRONT BUMPER BRACKET LH	Serviceable	265.00 F	*- FL
3	1		*LH HEADLAMP ASSY	Serviceable	1,650.00 F	*- FL
4	1		*LH HEADLAMP GARNISH	Deformed	420.00 F	*380.00 FL
5	1		*FRONT LH HEADLIGHT SUPPORT BRACKET	Serviceable	986.00 F	*- FL
6	1		*FRONT LH SIGNAL LAMP ASSY	Serviceable	580.00 F	*- FL
7	1		*FRONT LH REFLECTOR	Crumpled	180.00 F	*110.00 FL
8	1		*LH DOOR STEP PANEL	Repair	700.00 F	*- FL
9	1		*LH DOOR STEP PANEL STEEL GARNISH	Deformed / Scratched	360.00 F	*360.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$)	8,791.00	3,300.00
- List Item Discount on L Items 0.00/15.00% (\$)	0.00	495.00
Total Parts (\$)	8,791.00	2,805.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CHECK WIRING AND FOCUS HEADLAMPS	New	150.00	30.00
2	RUST PROOFING ON AFFECTED AREAS	New	180.00	50.00
3	LABOR CHARGES TO DISMANTLE ,REMOVE AND REPLACE DAMAGED PARTS AND AFFECTED AREAS	New	800.00	400.00
4	SPRAY PAINTING OF FRONT BUMPER ,FRONT HEADLIGHT BRACKET ,HEADLAMP GARNISH ,DOOR STEP PANEL	New	1,200.00	300.00
Gross Labour Cost (S\$)			2,330.00	780.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >