

Soon Seng Company (SG) Pte Ltd

160 Sin Ming Drive
#04-05
Sin Ming Autocity
S575722

Our client XE5519C
TP claim against AIG Insurance (Your Insured: SKW4810B)

Repairer's estimate

Parts

1	Front bumper	/PH	1	3650	3,650
2	Front bumper bracket LH	X SW	1	265	265
3	LH Headlamp assy	X SW	1	1650	1,650
4	LH headlamp garnish	/DEF	1	420	420
5	Front LH headlight support bracket	X SW	1	986	986
6	Front LH signal lamp assy	X SW	1	580	580
7	Front LH Reflector	/CR4	1	180	180
8	LH door step panel	X R	1	700	700
9	LH door step panel steel garnish	/DEF/SW	1	360	360
Parts Total:				\$	8,791.00

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Labor

1	Check wiring and focus headlamps		1	150	150
2	Rust proofing on affected areas		1	180	180
3	Labor charges to dismantle, remove and replace damaged parts and affected areas		1	800	800
4	Spray painting of front bumper, front headlight bracket, headlamp garnish, door step panel		1	1200	1,200
Labor Total:				\$	2,330.00

TOTAL: \$ 11,121.00

*Supplementary items would be included if noticed during the course of repair

Contact:
Mr Chal - 96250518
James - 92960289

Repair day - 3 days

L/S

After paint photo

Sun Pin (LH)

10/12/2020

TP within period

2,805
780
3,585
- 20%
2,868.00

L/S
\$2,850
3 days