

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS3/MSG19015797/GSD3E2-1  
**Date:** 06/11/2020

### REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	28798805SMF
Claimant Vehicle No : SKV7333Y	Insured Vehicle No :	SDE36Z
Date of Loss: 04/09/2019	Nature of Claim:	TP
	Claim No:	605183

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKV7333Y	Engine No:	3ZZ4633826
Make & Model:	TOYOTA COROLLA, 1.6 (A)	Chassis No:	MR053ZEC107142321
Reg. Date:	26/04/2007 (Man. Year: 2006)	Odometer:	300408 km
Colour:	Black		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	195/60 R15	Rear Tyre Size:	195/60 R15
Front Left Side:	Goodyear 5 mm	Rear Left Side:	Goodyear 5 mm
Front Right Side:	Goodyear 5 mm	Rear Right Side:	Goodyear 5 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,343.21	4,794.07	5,549.14	53.65
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,200.00	2,750.00	2,450.00	47.12
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>15,543.21</b>	<b>7,544.07</b>	<b>7,999.14</b>	<b>51.46</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>6,050.00</b>		
<b>Nett Amount (S\$)</b>	<b>15,543.21</b>	<b>6,050.00</b>	<b>9,493.21</b>	<b>61.08</b>

### INSPECTION

Date of Assignment:	05/09/2019	
Date Inspected:	06/09/2019	Inspected At:
		D's Graffiti Concepts (HQ) 25 Kaki bt Road 4 #06-26 Synergy @ KB Singapore 417800
Estimated Period of Repair:	8.0 days	

**Adjuster:** XING GUO QIANG

**Manager:** Hiew May Fung

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 05 Nov 2020)
<b>Parts:</b>	143	TOYOTA COROLLA 1.6 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SKV7333Y)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Bent	638.10 FL	*485.00 FL
2	2		*FRONT BUMPER SIDE RETAINER	Bent	45.00 FL	*35.00 FL
3	2		*FRONT BUMPER BRACKET	Serviceable	78.20 FL	*- FL
4	1		*FRONT BUMPER REINFORCEMENT	Necessary	418.50 FL	*343.00 FL
5	10		*FRONT BUMPER CLIPS	Necessary	50.00 FL	*50.00 FL
6	1		*HEADLAMP ASSEMBLY	N/s Cracked/O/s Serviceable	684.00 FL	*342.00 FL
7	1		*BONNET	Bent	590.20 FL	*590.20 FL
8	1		*BONNET LOCK	Distorted	85.00 FL	*85.00 FL
9	1		*FRONT GRILLE	Cracked	258.40 FL	*258.40 FL
10	1		*FRONT GRILLE BADGE	Damaged	55.00 FL	*55.00 FL
11	6		*FRONT GRILLE CLIPS	Necessary	56.00 FL	*30.00 FL
12	1		*FRONT SUPPORT PANEL	Repair	650.00 FL	*- FL
13	1		*AIR COND CONDENSOR	Serviceable	729.40 FL	*- FL
14	1		*RADIATOR ASSEMBLY	Serviceable	1,507.40 FL	*- FL
15	1		*REAR BUMPER	Bent	525.70 FL	*525.70 FL
16	2		*REAR BUMPER SIDE RETAINER	Bent	87.40 FL	*57.00 FL
17	2		*REAR BUMPER SIDE ATTACHMENT	Serviceable	87.80 FL	*- FL
18	2		*REAR BUMPER STAY	Bent	87.10 FL	*87.10 FL
19	10		*REAR BUMPER CLIPS	Necessary	90.00 FL	*30.00 FL
20	1		*BOOTLID	Bent	798.90 FL	*649.15 FL
21	1		*BOOTLID LOCK	Distorted	101.80 FL	*101.80 FL
22	2		*BOOTLID REFLECTOR	Damaged	653.60 FL	*570.00 FL
23	2		*BOOTLID REFLECTOR SEALANT	Serviceable	100.00 FL	*- FL
24	4		*BOOTLID REFLECTOR CLIPS	Serviceable	51.60 FL	*- FL
25	1		*BOOTLID WEATHERSTRIP	Deformed	105.80 FL	*105.80 FL
26	1		*BOOTLID EMBLEM 1.6E	Necessary	32.50 FL	*32.50 FL
27	1		*BOOTLID EMBLEM VVTI	Necessary	45.50 FL	*45.50 FL
28	1		*BOOTLID EMBLEM COROLLA	Necessary	38.50 FL	*38.50 FL
29	1		*BOOTLID EMBLEM ALTIS	Necessary	34.50 FL	*34.50 FL
30	1		*BOOTLID CHROME	Serviceable	328.70 FL	*- FL
31	4		*BOOTLID CHROME CLIPS	Serviceable	51.60 FL	*- FL
32	2		*TAILLAMP	Cracked	737.80 FL	*640.00 FL
33	2		*TAILLAMP SEALANT	Serviceable	150.00 FL	*- FL
34	4		*TAILLAMP CLIPS	Serviceable	51.60 FL	*- FL
35	2		*TAILLAMP LOWER PANEL	Serviceable	191.80 FL	*- FL
36	8		*TAILLAMP LOWER PANEL RIVETS	Serviceable	103.20 FL	*- FL
37	2		*TAILLAMP BASE PANEL	Serviceable	283.60 FL	*- FL
38	1		*REAR END PANEL	Bent	781.25 FL	*655.00 FL
39	1		*REAR END PANEL TOP TRIM	Bent	372.25 FL	*179.28 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	4		*REAR END PANEL TOP TRIM CLIPS	Necessary	51.60 FL	*20.00 FL
41	1		*REAR FLOOR PANEL	Repair	987.25 FL	*- FL
42	1		*REAR FLOOR PANEL INSULATOR CLOTCH	Serviceable	374.40 FL	*- FL
43	2		*NUMBER PLATE CASING	Bent	120.00 FS	*40.00 FS
44	2		*NUMBER PLATE	Damaged	80.00 FS	*20.00 FS
45	1		*SET REVERSE SENSOR	Shocked	280.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>13,630.95</b>	<b>6,305.43</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$)</b>	3,287.74	1,511.36
<b>Total Parts (\$)</b>	<b>10,343.21</b>	<b>4,794.07</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TOWING	New	120.00	0.00
2	TO CHECK AND RECONNECT SNAP WIRING	New	180.00	30.00
3	TO TUFF COAT AFFECTED AREAS	New	180.00	60.00
4	TO REMOVE AND REPLACE INTERIOR UPHOLSTERY	New	180.00	60.00
5	TO REMOVE AND REPLACE AIR COND CONDENSOR,PIPING VACUUM AND TOP UP GAS	New	180.00	60.00
6	TO REMOVE AND REPLACE RADIATOR,HOSE,FAN AND TOP UP COOLANT	New	180.00	60.00
7	TO RESPRAY AFFECTED AREAS	New	1,800.00	1,400.00
8	TO RENEW DAMAGED PARTS,STRAIGHTEN AND REPAIR FRONT & REAR CHASSIS MEMBER,FRONT & REAR FENDER INNER PANEL AND ALIGNED ALL PARTS	New	2,000.00	1,000.00
9	TO REMOVE AND REPLACE REVERSE SENSOR	New	180.00	40.00
10	TO REMOVE AND TRANSFER BOOT LID MECHANISM	New	200.00	40.00
<b>Gross Labour Cost (S\$)</b>			<b>5,200.00</b>	<b>2,750.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >