

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road, #16-00 Springleaf Tower  
Singapore 079909

**Our File No:** CS/CTI20011263/GQF3E2

**Date:** 22/03/2021

### REFERENCE

Insured/Claimant: ALLLSWELL LEASING & LIMOUSINE PTE LTD Policy No: DMHCSNA00005762000  
Date of Loss: 12/10/2020 Nature of Claim: OD Claim No: SNM20D203889/C01/TOHHS

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLH8096L  
Make & Model: TOYOTA PRIUS HYBRID, 1.8 CVT (A) Engine No: 2ZR6870463  
Reg. Date: 18/11/2016 (Man. Year: 2016) Chassis No: ZVW506048595  
Colour: Black Odometer: 336034 km  
Engine Capacity: 1797 cc  
Market Value/New Car Price: S\$62,000.00  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15  
Front Left Side: Windforce 5 mm Rear Left Side: Windforce 5 mm  
Front Right Side: Windforce 5 mm Rear Right Side: Windforce 5 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,430.00	7,785.30	6,644.70	46.05
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,800.00	1,320.00	1,480.00	52.86
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>17,230.00</b>	<b>9,105.30</b>	<b>8,124.70</b>	<b>47.15</b>
<b>- Excess (S\$)</b>	<b>2,000.00</b>	<b>2,000.00</b>	<b>0.00</b>	<b>0.00</b>
<b>(S\$)</b>	<b>15,230.00</b>	<b>7,105.30</b>	<b>8,124.70</b>	<b>53.35</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>1,066.10</b>	<b>497.37</b>	<b>568.73</b>	<b>53.35</b>
<b>Nett Amount (S\$)</b>	<b>16,296.10</b>	<b>7,602.67</b>	<b>8,693.43</b>	<b>53.35</b>

### INSPECTION

Date of Assignment: 16/10/2020  
Date Inspected: 21/10/2020 Inspected At: 160 Sin Ming Drive Autocity #04-05  
Estimated Period of Repair: 5.0 days Repairer : Allswell Motor Traders

**Adjuster:** XING GUO QIANG

**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 22 Mar 2021)
<b>Parts:</b>	144	TOYOTA PRIUS HYBRID 1.8 CVT (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLH8096L)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*EXHAUST AIR GARNISH	Broken	140.00 F	*120.00 FL
2	1		*FRONT BUMPER	Deformed	1,779.00 F	*495.50 FL
3	1		*FRONT TOP GRILLE	Deformed	549.00 F	*189.70 FL
4	1		*LOWER FRONT GRILLE	Deformed	342.00 F	*281.85 FL
5	1		*TOYOTA EMBLEM	Cut	85.00 F	*85.00 FL
6	1		*ENGINE TOP GARNISH	Deformed	290.00 F	*290.00 FL
7	1		*FRONT BONNET	Buckled	1,100.00 F	*853.60 FL
8	1		*FRONT REINFORCEMENT BAR (UPPER)	Bent	420.00 F	*420.00 FL
9	1		*RADIATOR	Bent	495.00 F	*495.00 FL
10	1		*COOLING COIL	Bent	399.00 F	*399.00 FL
11	2		*RADIATOR FANS	Not Necessary	120.00 F	*- FL
12	1		*RADIATOR CASING	Broken	320.00 F	*255.80 FL
13	1		*END PANEL	Bent	595.00 F	*381.45 FL
14	1		*ANTI-CRASH SENSOR	Damaged	1,400.00 F	*1,400.00 FL
15	1		*CLIPS/RETAINERS	Deformed	60.00 FS	*50.00 FS
16	1		*LICENSE PLATE & CASING	Bent	52.00 FS	*40.00 FS
17	1		*AIR FILLET	Cracked	360.00 F	*258.00 FL
18	1		*FRT BUMPER RUBBER	Cut	42.00 F	*42.00 FL
19	1		*FRT REINFORCEMENT LOWER	Bent	230.00 F	*230.00 FL
20	1		*AIR DUCT LOWER	Cracked	90.00 F	*90.00 FL
21	1		*AIR GUIDE	Deformed	85.00 F	*85.00 FL
22	1		*BRACE PANEL	Bent	69.00 F	*69.00 FL
23	1		*LOWER REINFORCEMENT BRACKET	Bent	150.00 F	*150.00 FL
24	1		*FRT BUMPER SPONGE	Cracked	85.00 F	*85.00 FL
25	1		*FRT BUMPER LOWER COVER	Torn	220.00 F	*120.00 FL
26	2		*HEADLAMP	Broken	2,500.00 F	*1,825.00 FL
27	1		*AIR RESONATOR	Cracked	45.00 F	*45.00 FL
28	1		*TOYOTA CIRCUIT EMBLEM T	Damaged	580.00 F	*580.00 FL
29	1		*OIL COOLER	Bent	260.00 F	*260.00 FL
30	1		*RH RETAINER	Bent	55.00 F	*55.00 FL
31	1		*RADIATOR TOP BRACKET	Bent	59.00 F	*59.00 FL
32	1		*LICENSE PLATE REAR PLATE	Bent	69.00 F	*69.00 FL
33	1		*BUMPER BACK BASE	Deformed	290.00 F	*160.00 FL
34	2		*RADIATOR MOTOR	Not Working	650.00 F	*291.50 FL
35	1		*RADIATOR LOWER BASE BKT	Bent	280.00 F	*120.00 FL
36	1		*RADIATOR LOWER PLATE	Not Necessary	165.00 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>14,430.00</b>	<b>10,350.40</b>
<b>- List Item Discount on L Items 0.00/25.00% (S\$)</b>	<b>0.00</b>	<b>2,565.10</b>
<b>Total Parts (S\$)</b>	<b>14,430.00</b>	<b>7,785.30</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	DISMANTLE / ASSEMBLY OF ALL AFFECTED PARTS INCLUDING PANEL KNOCKING & WELDING OF CHASSIS SUPPORT, END PANEL, FENDER x2	New	1,400.00	600.00
2	SPRAY PAINTING OF ALL AFFECTED PARTS INCLUDING ANTI-RUST PAINT, WASHED AFTER POLISH	New	1,000.00	600.00
3	RESET & WARNING OF ANTI-COLLISION ERROR & ETC	New	400.00	120.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,800.00</b>	<b>1,320.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >