

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG20011264/KGS3Q2
Date: 08/12/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100488050
Claimant Vehicle No :	SKC1554R	Insured Vehicle No :	SLH1931Y
Date of Loss:	14/10/2020	Nature of Claim:	TP
		Claim No:	2839024293SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKC1554R		
Make & Model:	VOLVO XC60, 2.0 T5 (A)	Engine No:	B4204T71025073
Reg. Date:	26/07/2011 (Man. Year: 2011)	Chassis No:	YV1DZ475BB2223931
Colour:	Metallic Brown	Odometer:	129158 km
Engine Capacity:	1999 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	235/60 R18	Rear Tyre Size:	235/60 R18
Front Left Side:	Bridgestone 8 mm	Rear Left Side:	Bridgestone 8 mm
Front Right Side:	Bridgestone 8 mm	Rear Right Side:	Bridgestone 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,189.50	2,594.45	10,595.05	80.33
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,300.00	1,015.00	2,285.00	69.24
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,489.50	3,609.45	12,880.05	78.11
Approved Total (Overridden) (S\$)		2,850.00		

(S\$)	16,489.50	2,850.00	13,639.50	82.72
+ GST 7.00/7.00% (S\$)	1,154.27	199.50	954.77	82.72
Nett Amount (S\$)	17,643.77	3,049.50	14,594.27	82.72
Global Sum Settlement (S\$)	0.00			

INSPECTION

Date of Assignment: 16/10/2020

Date Inspected: 16/10/2020

Estimated Period of Repair: 4.0 days

Inspected At:

Yee Auto Pte Ltd (HQ)
 160 SIN MING DRIVE #02-17 SIN MING AUTOCITY
 Singapore 575722

Adjuster: KENNETH KONG**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT EMBLEM XC60	Necessary	65.00 F	*65.00 FL
2	1		*BOOT EMBLEM T6	Necessary	92.50 F	*92.50 FL
3	1		*BOOT EMBLEM VOLVO	Necessary	185.00 F	*158.00 FL
4	1		*REAR BUMPER	Buckled	2,680.50 F	*1,528.30 FL
5	1		*REAR BUMPER REINFORCEMENT	Repair	904.50 F	*- FL
6	1		*REAR BUMPER INNER GARNISH	Serviceable	320.20 F	*- FL
7	1		*REAR BUMPER SIDE RETAINER -LH	Serviceable	95.20 F	*- FL
8	1		*REAR BUMPER SIDE RETAINER -RH	Serviceable	95.20 F	*- FL
9	1		*REAR BUMPER TOWING COVER	Serviceable	45.00 F	*- FL
10	1		*REAR END PANEL	Repair	1,310.50 F	*- FL
11	1		*REAR END PANEL GARNISH	Serviceable	440.00 F	*- FL
12	1		*REAR EXHAUST BOX	Repair	1,925.10 F	*- FL
13	1		*REAR EXHAUST MOUNTING	Serviceable	160.00 F	*- FL
14	1		*REAR BUMPER SPONGE	Serviceable	385.50 F	*- FL
15	1		*REAR BUMPER GARNISH (TOP)	Cracked	335.90 F	*322.00 FL
16	1		*REAR BUMPER LOWER SPOILER	Dented	565.20 F	*565.20 FL
17	1		*REAR BUMPER LOWER SPOILER REFLECTOR -LH	Serviceable	420.85 F	*- FL
18	1		*REAR BUMPER LOWER SPOILER REFLECTOR -RH	Serviceable	420.85 F	*- FL
19	1		*REAR BUZZER SENSOR	Serviceable	332.50 F	*- F
20	1		*REVERSE SENSOR CORNER -LH	Serviceable	465.00 F	*- F
21	1		*REVERSE SENSOR CORNER -RH	Serviceable	465.00 F	*- F
22	1		*REVERSE SENSOR CENTRE -LH	Serviceable	465.00 F	*- F
23	1		*REVERSE SENSOR CENTRE -RH	Serviceable	465.00 F	*- F
24	1		*REAR REVERSE SENSOR WIRE	Serviceable	550.00 F	*- F

F=Franchise part. L=ListItemDisc.

Sub Total (\$)	13,189.50	2,731.00
- List Item Discount on L Items 0.00/5.00% (\$)	0.00	136.55
Total Parts (\$)	13,189.50	2,594.45

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO DISMANTLE & REPLACE DAMAGED PARTS ,PANEL BEAT WHERE NECESSARY	New	1,500.00	500.00
2	TO PUTTY ,APPLY PRIMER & SPRAY PAINT ON THE AFFECTED PORTION	New	1,200.00	500.00
3	TO APPLY RUST-PROOFING ON REPAIRED ,REPLACED PANEL	New	120.00	0.00
4	TO COMPUTER RESET	New	380.00	0.00
5	TO CHECK WIRING FUNCTIONS	New	100.00	15.00
Gross Labour Cost (S\$)			3,300.00	1,015.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >