



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:VALE OH			Ref: CC4/ASM20011268/Abs3q2 Date: 01/04/2021 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SCR 8318B	Veh. Inspected	SMJ 5457B
	Policy No.	GA523251/1	Coverage (\$)	0.00
	Claim No.	S0M02VM3	Excess (\$)	0.00
	Assign From		Assign Date	19/10/2020
2. Vehicle Particulars & Condition				
	Make & Model	HONDA STREAM	c.c	1799
	Engine No.	HIDDEN	Year of Reg.	2008
	Chassis No.	RN61042252	Colour	WHITE
	Odometer	162757 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	215/50 R17	HABILEAD	6 mm
	L/H Front Tyre	215/50 R17	HABILEAD	6 mm
	R/H Rear Tyre	215/50 R17	HABILEAD	6 mm
	L/H Rear Tyre	215/50 R17	HABILEAD	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	15/10/2020	Inspection Date	19/10/2020
	Survey held at	VISION AUTOWORK PTE LTD 8 KAKI BUKIT AVE 4, #08-09 PREMIER @ KAKI BUKIT SINGAPORE 415875		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days	