

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20011269/R1QF3Q2

Date: 01/02/2021

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCNSA00107572001

**Claimant
Vehicle No :** SMM1296J

**Insured
Vehicle No :** SLF6189B

Date of Loss: 14/10/2020

Nature of
Claim: TP

Claim
No: SNM20D203877/C02/TOHHS

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMM1296J**

Make & Model: LAND ROVER DISCOVERY SPORT, 2.0 SE Si4
(L550) (A)

Engine No: 015037103446204PT

Reg. Date: 17/09/2015 (Man. Year: 2015)

Chassis No: SALCA2AG0FH542221

Colour: Orange

Odometer: 98641 km

Engine Capacity: 1999 cc

Market Value/New Car

Price: N/A

Sum Insured (\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/60 R18

Rear Tyre Size:

235/60 R18

Front Left Side: Pirelli 6 mm

Rear Left Side:

Pirelli 6 mm

Front Right Side: Pirelli 6 mm

Rear Right Side:

Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,736.44	6,128.09	5,608.35	47.79
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,920.00	1,120.00	1,800.00	61.64
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$)	14,656.44	7,248.09	7,408.35	50.55
Approved Total (Overridden) (\$)		5,800.00		
(\$)	14,656.44	5,800.00	8,856.44	60.43
+ GST 7.00/7.00% (\$)	1,025.95	406.00	619.95	60.43
Nett Amount (\$)	15,682.39	6,206.00	9,476.39	60.43

INSPECTION

Date of Assignment: 19/10/2020

Date Inspected: 28/10/2020 Inspected At:

Accord Auto Services Pte Ltd (Bukit
Merah)

BLK 1009 BUKIT MERAH LANE 3,

#01-80

Singapore 159723

Estimated Period of Repair: 3.0 days

Adjuster: MOHD RASUL**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 01 Feb 2021)
Parts:	M1-SUV	LAND ROVER DISCOVERY SPORT 2.0 SE Si4 (L550) (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMM1296J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Bent	4,200.00 FL	*3,265.00 FL
2	2		*REAR TAILGATE ABSORBER	Serviceable	800.00 FL	*- FL
3	1		*SET REAR TAILGATE GLASS MOULDING	Not Necessary	215.65 FL	*- FL
4	1		*REAR TAILGATE LOGO DISCOVERY	Necessary	180.00 FL	*63.00 FL
5	1		*REAR TAILGATE LOGO SPORT	Necessary	110.00 FL	*46.00 FL
6	1		*REAR TAILGATE LOGO LANDROVER	Necessary	120.00 FL	*86.00 FL
7	1		*REAR BUMPER	Deformed	3,564.00 FL	*2,606.00 FL
8	2		*REAR BUMPER SIDE RETAINER	Serviceable	310.00 FL	*- FL
9	1		*REAR BUMPER LOWER	Deformed	626.32 FL	*626.32 FL
10	1		*REAR REFLECTOR LH	Serviceable	280.87 FL	*- FL
11	1		*REAR REFLECTOR RH	Serviceable	280.87 FL	*- FL
12	1		*REAR BUMPER TOW COVER	Serviceable	100.00 FL	*- FL
13	1		*REAR REINFORCEMENT BAR	Serviceable	680.65 FL	*- FL
14	1		*REAR END PANEL	Serviceable	777.68 FL	*- FL
15	1		*SET REVERSE SENSOR	Serviceable	480.00 FS	*- FS
16	1		*SET REAR BUMPER CLIPS	Necessary	35.00 FS	*35.00 FS
17	1		*SET REAR BOOT INSULATOR CLIPS	Necessary	35.00 FS	*35.00 FS
18	1		*SET REAR FENDER INNER TRIM BOARD CLIPS	Not Necessary	50.00 FS	*- FS
19	1		*SET REAR BUMPER LOWER CLIPS	Necessary	35.00 FS	*35.00 FS
20	1		*REAR TAILGATE GLASS SEALANT	Not Necessary	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	12,961.04	6,797.32
- List Item Discount on L Items 10.00/10.00% (S\$)	1,224.60	669.23
Total Parts (S\$)	11,736.44	6,128.09

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	SPRAY PAINTING TO ALL AFFECTED AREAS	New	800.00	300.00
2	LABOUR REMOVE/REFIX ACCIDENT DAMAGES PARTS TO KNOCK,JACK,CUT WELD AND REALIGN ACCIDENT AFFECTED AREA	New	1,000.00	450.00
3	CHECK WIRING SYSTEM & LIGHT	New	100.00	0.00
4	ANTI RUST TREATMENT	New	120.00	40.00
5	TO CHECK WATER LEAKING	New	100.00	30.00
6	TO REMOVE/REFIX REVERSE SENSOR	New	150.00	60.00
7	TO REMOVE/REFIX REVERSE CAMERA	New	150.00	60.00
8	TO REMOVE/REFIX/REPLACE REAR BOOT INNER COMPARTMENT,MECHEMISM & ASSY TO NEW TAILGATE	New	200.00	60.00
9	TO REMOVE/REFIX REAR INNER COMPARTMENT TO FACILITATE REPAIR	New	150.00	0.00
10	TO REMOVE/REFIX TAILGATE GLASS TO NEW TAILGATE	New	150.00	120.00
Gross Labour Cost (\$\$)			2,920.00	1,120.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >