

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:**

CC4/AIG20011274/ERA3Q2

Date:

08/12/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

2000003102

Claimant Vehicle No : SHA4535Y**Insured Vehicle No :**

SMR5700G

Date of Loss: 17/10/2020

Nature of Claim:

TP

Claim No:

9530975625SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SHA4535Y**

Make & Model: HYUNDAI I40, 1.7 D CRDI F/L ABS AIRBAG 4DR (A)

Engine No:

D4FDGU614109

Reg. Date: 26/03/2015 (Man. Year: 2014)

Chassis No:

KMHLB41UMFU065930

Colour: Blue

Odometer:

749377 km

Engine Capacity: 1685 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16

Rear Tyre Size:

205/60 R16

Front Left Side: Michelin 5 mm

Rear Left Side:

Michelin 5 mm

Front Right Side: Michelin 5 mm

Rear Right Side:

Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,445.44	280.00	5,165.44	94.86
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,300.00	1,110.00	1,190.00	51.74
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	7,745.44	1,390.00	6,355.44	82.05
+ GST 7.00/7.00% (S\$)	542.18	97.30	444.88	82.05

Nett Amount (S\$)	8,287.62	1,487.30	6,800.32	82.05
+ Loss of Use (3.0 x S\$50.00/day) (S\$)		150.00		
+ Car Rental (3.0 x S\$110.67/day) (S\$)		332.01		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		1,971.31		

INSPECTION

Date of Assignment: 19/10/2020

Date Inspected: 19/10/2020

Estimated Period of Repair: 2.0 days

Inspected At:

ComfortDelGro Engineering Pte Ltd (Loyang)
59 Loyang Drive
Singapore 508969

Adjuster: CHEN TSUE YEE**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	1,106.00 FL	*- FL
2	10		*REAR BUMPER CLIPS	Not Necessary	22.00 FL	*- FL
3	1		*REAR BUMPER SIDE BRACKET -RH	Not Necessary	35.60 FL	*- FL
4	1		*REAR BUMPER REFLECTOR -RH	Not Necessary	32.00 FL	*- FL
5	1		*REAR DOOR RH	Repair	2,201.10 FL	*- FL
6	1		*REAR DOOR HANDLE RH	Not Necessary	36.30 FL	*- FL
7	1		*REAR FENDER RH	Not Necessary	2,171.40 FL	*- FL
8	1		*ROCKER PANEL GARNISH RH	Not Necessary	682.80 FL	*- FL
9	1		*REAR WHEEL HUB CAP	Not Necessary	107.10 FL	*- FL
10	1		*REAR DOOR ADVERTISEMENT STICKER RH	Necessary	100.00 FS	*100.00 FS
11	1		*REAR BUMPER ADVERTISEMENT STICKER	Necessary	100.00 FS	*100.00 FS
12	1		*REAR BUMPER RUBBER MAT	Not Necessary	50.00 FS	*- FS
13	1		*REAR DOOR COMFORTDELGRO APPS STICKER	Necessary	80.00 FS	*80.00 FS
					Sub Total (\$)	6,724.30 280.00
					- List Item Discount on L Items 20.00/20.00% (\$)	1,278.86 0.00
					Total Parts (\$)	5,445.44 280.00

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	1,000.00	280.00
2	SPRAY PAINTING CHARGE	New	1,000.00	800.00
3	WIRING CHARGE	New	60.00	30.00
4	REMOVE/REFIX REVERSE SENSOR	New	120.00	0.00
5	DOOR TRANSFER	New	120.00	0.00
Gross Labour Cost (S\$)			2,300.00	1,110.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >