

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/III20011275/BTF3E2

Date: 23/02/2021

REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No:

Claimant Vehicle No : SLU5120B

Insured Vehicle No : SHC8182U

Date of Loss: 30/08/2020

Nature of Claim: TP Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLU5120B

Make & Model: TOYOTA C-HR HYBRID, 1.8 E S 5DR (A)

Engine No: 2ZR8198481

Reg. Date: 04/12/2017 (Man. Year: 2017)

Chassis No: ZYX102076531

Colour: Black

Odometer: 70805 km

Engine Capacity: 1797 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R17

Rear Tyre Size: 215/60 R17

Front Left Side: Continental 6 mm

Rear Left Side: Continental 6 mm

Front Right Side: Continental 6 mm

Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	21,401.19	10,448.34	10,952.85	51.18
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,770.00	3,080.00	2,690.00	46.62
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	27,171.19	13,528.34	13,642.85	50.21
Approved Total (Overridden) (\$\$)		10,700.00		
(\$\$)	27,171.19	10,700.00	16,471.19	60.62
+ GST 7.00/7.00% (\$\$)	1,901.98	749.00	1,152.98	60.62
Nett Amount (\$\$)	29,073.17	11,449.00	17,624.17	60.62

INSPECTION

Date of Assignment: 19/10/2020

Date Inspected: 19/10/2020

Inspected At:

Team Autopro Pte Ltd (Sin Ming)

160 SIN MING DR

#01-14 SIN MING AUTO CITY

SINGAPORE 575722

Estimated Period of Repair: 10.0 days

Adjuster: Lim Teow Guan

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 23 Feb 2021)
Parts:	M1-SUV	TOYOTA C-HR HYBRID 1.8 E S 5DR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLU5120B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Broken	598.00 FL	*598.00 FL
2	1		*FRONT BUMPER LOWER	Broken	485.00 FL	*485.00 FL
3	1		*FRONT BUMPER CENTRE GRILLE	Broken	198.60 FL	*198.60 FL
4	1		*FRONT BUMPER FOG LAMP GARNISH	O/S Missing	554.20 FL	*112.00 FL
5	1		*FRONT GRILLE	No such part	578.85 FL	*- FL
6	1		*FRONT GRILLE LOGO }	Cracked	1,217.70 FL	*1,850.50 FL
7	1		*FRONT RADAR SENSOR }	Short Circuit	1,700.00 FL	*- FL
8	1		*FRONT GRILLE BASE	No such part	371.25 FL	*- FL
9	1		*FRONT GRILLE OUTER CHROME GARNISH	No such part	289.90 FL	*- FL
10	2		*FRONT GRILLE TOP BRACKET SIDE	Not Damaged	174.60 FL	*- FL
11	1		*FRONT GRILLE TOP BRACKET CENTRE	Not Damaged	95.00 FL	*- FL
12	1		*FRONT BUMPER INNER SPONGE	Broken	152.55 FL	*109.25 FL
13	1		*FRONT BUMPER REINFORCEMENT	Dented	371.75 FL	*371.75 FL
14	2		*FRONT BUMPER SIDE RETAINER	Necessary	362.20 FL	*133.00 FL
15	1		*HEADLAMP ASSY (2PCS)	Broken (1Pc Only)	5,442.50 FL	*3,634.00 FL
16	2		*HEADLAMP BRACKET	No such part	370.50 FL	*- FL
17	1		*HEADLAMP PANEL	Not Damaged	271.45 FL	*- FL
18	1		*BONNET	Bent	971.70 FL	*971.70 FL
19	1		*BONNET LOCK ASSY	Not Damaged	276.60 FL	*- FL
20	1		*BONNET INSULATOR	Not Damaged	280.00 FL	*- FL
21	2		*BONNET HINGE	Not Damaged	342.90 FL	*- FL
22	1		*FRONT SUPPORT PANEL	Not Damaged	1,217.75 FL	*- FL
23	1		*FRONT SUPPORT TOP PANEL GARNISH	Not Damaged	371.45 FL	*- FL
24	1		*FRONT FENDER RH	Dented	781.85 FL	*691.00 FL
25	1		*FRONT FENDER EMBLEM HYBRID	Necessary	61.10 FL	*61.10 FL
26	1		*FRONT FENDER INNER COWLING RH	Broken	377.75 FL	*377.75 FL
27	1		*FRONT FENDER ARCH GARNISH RH	Broken	271.70 FL	*210.00 FL
28	1		*FRONT DOOR RH	Repair	1,578.60 FL	*- FL
29	1		*FRONT DOOR BLACK TAPE RH	Not Necessary	58.00 FL	*- FL
30	1		*FRONT WIPER WASHER TANK	Broken	289.90 FL	*165.40 FL
31	1		*FRONT WIPER WASHER TANK MOTOR	Not Damaged	115.00 FL	*- FL
32	1		*FRONT SHOCK ABSORBER RH	Bent	571.25 FL	*380.20 FL
33	1		*FRONT LOWER ARM RH	Not Damaged	589.90 FL	*- FL
34	1		*FRONT KNUCKLE ARM RH	Dented	561.60 FL	*390.00 FL
35	1		*FRONT KNUCKLE ARM BEARING RH	Jammed	577.10 FL	*165.75 FL
36	1		*STEERING RACK	Bent	1,602.25 FL	*1,602.25 FL
37	1		*SUNDRIES	Not Necessary	80.00 FS	*- FS
38	1		*FRONT BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
39	1		*FRONT BUMPER LOWER CLIPS	Necessary	50.00 FS	*30.00 FS
40	1		*FRONT BUMPER CENTRE GRILLE CLIP	Necessary	50.00 FS	*30.00 FS
41	1		*FRONT BUMPER FOG LAMP GARNISH CLIPS	No such part	50.00 FS	*- FS

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
42	1		*FRONT GRILLE CLIPS	No such part	50.00 FS	*- FS
43	1		*HEADLAMP PANEL SEALANT	Not Necessary	100.00 FS	*- FS
44	1		*BONNET SEALANT	Not Necessary	100.00 FS	*- FS
45	1		*BONNET INSULATOR CLIPS	Necessary	50.00 FS	*30.00 FS
46	1		*BONNET RUBBER CLIPS	Necessary	50.00 FS	*30.00 FS
47	1		*FRONT SUPPORT PANEL SEALANT	Not Necessary	100.00 FS	*- FS
48	1		*FRONT SUPPORT PANEL TOP GARNISH CLIPS	Not Necessary	50.00 FS	*- FS
49	1		*FRONT FENDER SEALANT	Necessary	100.00 FS	*30.00 FS
50	1		*FRONT FENDER INNER COWLING CLIPS	Necessary	50.00 FS	*30.00 FS
51	1		*FRONT FENDER ARCH GARNISH CLIPS	Necessary	50.00 FS	*30.00 FS
52	1		*FRONT DOOR SEALANT	Not Necessary	100.00 FS	*- FS
53	1		*FRONT ALLOY RIM	Cut	980.00 FS	*450.00 FS
54	1		*FRONT TYRE	Not Damaged	380.00 FS	*- FS
55	1		*RADIATOR COOLANT	Not Necessary	80.00 FS	*- FS
56	1		*BRAKE FLUID	Not Necessary	80.00 FS	*- FS
57	1		*AIRCON FLUID	Not Necessary	80.00 FS	*- FS
58	1		*FRONT BUMPER LOWER INNER SPONGE	Broken	121.00 FL	*87.20 FL
59	1		*FRONT WHEEL HOUSE PANEL RH	Broken	576.80 FL	*350.00 FL
60	1		*FRONT WHEEL HOUSE PANEL SEALANT	Necessary	100.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	27,608.25	13,684.45
- List Item Discount on L Items 25.00/25.00% (\$)	6,207.06	3,236.11
Total Parts (\$)	21,401.19	10,448.34

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	R&R BONNET COMPONENT	New	150.00	80.00
2	R&R FRONT UNDERCARRIAGE	New	300.00	200.00
3	R&R RIM AND TYRE BALANCING	New	100.00	60.00
4	WHEEL ALIGNMENT	New	120.00	60.00
5	R&R RADIATOR	New	150.00	0.00
6	R&R CONDENSER	New	150.00	0.00
7	CHECK WIRING	New	100.00	50.00
8	ALIGNMENT RADAR SENSOR	New	300.00	0.00
9	DIAGNOTIC AND RESET FAULT CODE	New	300.00	150.00
10	UPHOLSTERY	New	300.00	0.00
11	PANEL BEATING	New	1,800.00	1,200.00
12	RUST PROOFING	New	200.00	80.00
13	SPRAY PAINTING	New	1,800.00	1,200.00
Gross Labour Cost (\$\$)			5,770.00	3,080.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >