

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20011278/T1PA3Q2

Date: 19/11/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100344643

Claimant
Vehicle No : GBB3055M **Insured Vehicle No :** SFF52Y

Date of Loss: 30/09/2020 Nature of Claim: TP Claim No: 1638201133SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBB3055M		
Make & Model:	TOYOTA DYNA 150 MANUAL 3SEATER, 3.0 D (M)	Engine No:	1KD1888319
Reg. Date:	27/11/2008 (Man. Year: 2008)	Chassis No:	JTFAT35Y40K200242
Colour:	Silver	Odometer:	355643 km
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	155 R12 (D)
Front Left Side:	Yokohama 5 mm	Rear Left Side:	Yokohama 5/5 mm
Front Right Side:	Yokohama 5 mm	Rear Right Side:	Yokohama 5/5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,575.17	3,613.97	7,961.20	68.78
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,150.00	1,240.00	910.00	42.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,725.17	4,853.97	8,871.20	64.63
Approved Total (Overridden) (S\$)		3,900.00		
Nett Amount (S\$)	13,725.17	3,900.00	9,825.17	71.59
+ Loss of Use (9.0 x S\$100.00/day) (S\$)		900.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		4,802.00		
Global Sum Settlement (S\$)		4,800.00		

INSPECTION

Date of Assignment: 19/10/2020

Date Inspected: 19/10/2020 Inspected At:

Sin Yew Hup Auto Pte Ltd (HQ)
Blk D4 Woodlands Road 393M, Yew
Tee Industrial Estate
Singapore 677981

Estimated Period of Repair: 7.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Bent	1,255.80 FL	*1,255.80 FL
2	1		*DYNA STICKER	Necessary	28.30 FL	*28.30 FL
3	2		*TAILGATE LOCK	Repair	197.60 FL	*- FL
4	1		*SIDE GATE RH	Repair	1,154.80 FL	*- FL
5	2		*TAIL LAMP	N/S Cracked / O/S Cut	440.00 FL	*440.00 FL
6	1		*TAIL LAMP BRACKET	N/S Bent / O/S Repair	178.40 FL	*89.20 FL
7	1		*REVERSE SENSOR	Not Working	280.00 FS	*200.00 FS
8	1		*REAR DECK (LOCAL REPAIR)	Dented	6,000.00 FS	*500.00 FS
9	1		*REAR CANOPY	Broken	2,800.00 FS	*1,500.00 FS
10	1		*REAR NUMBER PLATE	Bent	30.00 FS	*30.00 FS
11	1		*70KM H STICKER	Necessary	12.00 FS	*12.00 FS
12	1		*13 PAX STICKER	Necessary	12.00 FS	*12.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	12,388.90	4,067.30
- List Item Discount on L Items 25.00/25.00% (\$\$)	813.73	453.33
Total Parts (\$\$)	11,575.17	3,613.97

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO DISMANTLE ALL DAMAGED PARTS ,PANEL BEAT /STRAIGHTEN ,ALL DENTS,CHECK ,ADJUST ,REPLACE AND RE-ALIGN THE ABOVE PARTS	New	1,000.00	600.00
2	TO PUTTY AND SPRAY PAINT TAILGATE IN & OUT ,REAR DECK ,SIDE GATE RH AND ALL AFFECTED PORTIONS	New	1,000.00	600.00
3	TO ANTI-RUST REAR AFFECTED PORTIONS	New	150.00	40.00
Gross Labour Cost (\$)			2,150.00	1,240.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >