

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG20011281/T1VD3E2

Date: 06/11/2020

REFERENCE

Insured/Claimant:	CHEN JIANGLIN	Policy No:	1900072711	
Date of Loss:	17/10/2020	Nature of Claim:	OD	Claim No: 0040410315SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLE3489K			
Make & Model:	MITSUBISHI ATTRAGE, 1.2 CVT (A)		Engine No:	3A92UHL8559
Reg. Date:	25/03/2019 (Man. Year: 2018)		Chassis No:	MMBSTA13AKH000554
Colour:	Maroon		Odometer:	23568 km
Engine Capacity:	1193 cc			
Market Value/New Car Price:	S\$53,000.00			
Sum Insured (S\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/55R15	Rear Tyre Size:	185/55R15
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,595.60	3,357.06	3,238.54	49.10
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,285.00	2,570.00	3,715.00	59.11
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,880.60	5,927.06	6,953.54	53.98
- Excess (S\$)	300.00	300.00	0.00	0.00
(S\$)	12,580.60	5,627.06	6,953.54	55.27
+ GST 7.00/7.00% (S\$)	880.64	393.89	486.75	55.27
Nett Amount (S\$)	13,461.24	6,020.95	7,440.29	55.27

INSPECTION

Date of Assignment: 19/10/2020
Date Inspected: 19/10/2020 Inspected At:

Cycle & Carriage Automotive Pte Ltd
(Pandan Gardens)
209 Pandan Gardens
Singapore 609339

Estimated Period of Repair: 5.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PANEL ASSY,FR END	Not Necessary	1,055.00 FL	*- FL
2	1		*PANEL,HEADLAMP SUPPORT,UPR	Not Necessary	65.00 FL	*- FL
3	1		*CONDENSER ASSY,A/C REFRIGE	Not Necessary	758.00 FL	*- FL
4	1		*PANEL,AIR GUIDE	Not Necessary	112.00 FL	*- FL
5	1		*RADIATOR ASSY	Not Necessary	967.00 FL	*- FL
6	1		*PANEL,AIR GUIDE,RH	Not Necessary	11.00 FL	*- FL
7	1		*PANEL,AIR GUIDE,LH	Not Necessary	11.00 FL	*- FL
8	1		*GRILLE,RADIATOR	Not Necessary	554.00 FL	*- FL
9	1		*BRACKET,FR BUMPER,LH	Not Necessary	13.00 FL	*- FL
10	1		*BRACKET,FR BUMPER,RH	Deformed	13.00 FL	*13.00 FL
11	1		*LLC 4L	Not Necessary	26.00 FL	*- FL
12	1		*COVER,HEADLAMP SUPT PANEL	Not Necessary	62.00 FL	*- FL
13	1		*GRILLE,FR UNDER	Not Necessary	165.00 FL	*- FL
14	10		*CLIP,FR BUMPER	Necessary	40.00 FL	*40.00 FL
15	1		*FACE,FR BUMPER	Deformed	703.00 FL	*703.00 FL
16	1		*GARNISH,FR BUMPER,RH	Cut	127.00 FL	*127.00 FL
17	1		*HEADLAMP ASSY,RH	Cracked	660.00 FL	*660.00 FL
18	1		*LAMP ASSY FOG,FR RH	Not Necessary	303.00 FL	*- FL
19	1		*SHIELD,FR WHEEL HOUSE RH (NPA)	Deformed	98.00 FL	*98.00 FL
20	10		*CLIP,FR BUMPER	Necessary	40.00 FL	*40.00 FL
21	1		*EMBLEM ECO	Necessary	17.00 FS	*17.00 FS
22	1		*BODY KIT,ATTRAGE	Cracked	1,643.00 FS	*1,643.00 FS
23	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
24	1		*FENDER,FR RH	Bent	497.00 FL	*497.00 FL
25	1		*FRONT NUMBER PLATE WITH FRAME	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,040.00	3,858.00
- List Item Discount on L Items 23.00/23.00% (\$\$)	1,444.40	500.94
Total Parts (\$\$)	6,595.60	3,357.06

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	RENEW ACCIDENT DAMAGED PARTS ON FRONT SUPPORT PANEL,RH FRONT FENDER,FRONT BUMPER,FRONT BODY KITS,REPAIR RH FRONT DOOR,REPAIR FRONT BONNET	New	2,475.00	900.00
2	REMOVE AND INSTALL RADIATOR AND A/CON CONDENSER TO FACILITATE REPAIR WORK	New	100.00	0.00
3	TOP UP A/CON GAS AND CHECK A/CON SYSTEM	New	80.00	0.00
4	PAINT WORK SPRAY FRONT SUPPORT PANEL,FRONT BUMPER,RH FRONT FENDER,FRONT BODY KITS,RH FRONT DOOR,LH FRONT FENDER,FRONT BONNET AND AFFECTED PORTION	New	2,800.00	1,400.00
5	APPLY BODY SEALANT	New	80.00	0.00
6	CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM	New	30.00	30.00
7	PERFORM RUST PREVENTION	New	80.00	0.00
8	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
9	APPLY FRONT BODY KITS SEALANT	New	80.00	0.00
10	RE-APPLY BODY ZERTONA COATING ON AFFECTED PORTION	New	320.00	-
11	TO CONDUCT COMPUTERIZED FULL WHEEL ALIGNMENT.	New	120.00	120.00
Gross Labour Cost (\$)			6,285.00	2,570.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >