



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKZ 9198L

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR TAILLAMP LH	NOT NECESSARY	552.30	-
1	REAR BUMPER CENTER	CUT	762.70	762.70
1	REAR BUMPER SIDE LH	CUT	195.80	195.80
2	REAR BUMPER SIDE RETAINER LH/RH @\$16.40	N/S NECESSARY	32.80	16.40
1	REAR BUMPER REFLECTOR LH	NOT NECESSARY	151.40	-
1	REAR END PANEL	NOT NECESSARY	480.30	-
1	REAR FENDER ARCH GARNISH LH	NOT NECESSARY	192.80	-
1	REAR FENDER INNER AIR VENT LH	NOT NECESSARY	33.10	-
1	REAR FENDER INNER SHIELD LH	NOT NECESSARY	198.10	-
	LESS 20% DISCOUNT		-519.86	-194.98
			2,079.44	779.92
<u>SPECIAL NETT ITEMS</u>				
1	REAR TAILLAMP CLIPS SET LH (SN)	NOT NECESSARY	40.00	-
1	SET REAR BUMPER CENTER CLIPS (SN)	NECESSARY	60.00	30.00
1	REAR BUMPER LOWER LIP (SN)	CUT	580.00	400.00
1	SET REAR BUMPER REVERSE SENSOR (SN)	NOT NECESSARY	280.00	-
1	REAR BUMPER TOP CHROME PAD (SN)	NECESSARY	350.00	180.00
1	REAR END PANEL SEALANT (SN)	NOT NECESSARY	100.00	-
1	REAR FENDER ARCH GARNISH CLIPS SET LH (SN)	NOT NECESSARY	50.00	-
1	REAR FENDER INNER SHIELD CLIPS SET LH (SN)	NOT NECESSARY	60.00	-
			1,520.00	610.00
<u>LABOUR</u>				
	TO DISMANTLE & REPLACED WITH PANEL BEATING ALL THE ACCIDENT PORTION.		400.00	200.00
	TO SPRAY PAINTING ALL THE ACCIDENT PORTION & POLISHING AFFECTED AREA.		400.00	200.00
	TO PERFORM LIGHTING & WIRING CHECK.		80.00	30.00
	TO DISMANTLE & REPLACED REAR BUMPER REVERSE SENSOR WITH DISTANCE SETTING.		80.00	40.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO PERFORM CONDUCT WATER LEAKAGE TEST OF ACCIDENT PORTION.	NOT NECESSARY	80.00	-
			1,040.00	470.00
GRAND TOTAL			4,639.44	1,859.92
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,450.00

Report Ref No. CS/AGI20011286/Avf3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.