

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG20011287/T1SD3E2

Date: 16/11/2020

REFERENCE

Insured/Claimant:	TAN WEI YAN	Policy No:	1900019307
Date of Loss:	17/10/2020	Nature of Claim:	OD
		Claim No:	2056163795SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMH8475P		
Make & Model:	MITSUBISHI ATTRAGE, 1.2 CVT (A)	Engine No:	3A92UHN8556
Reg. Date:	12/02/2019 (Man. Year: 2018)	Chassis No:	MMBSTA13AKH001119
Colour:	Grey	Odometer:	11441 km
Engine Capacity:	1193 cc		
Market Value/New Car Price:	S\$47,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/55 R15	Rear Tyre Size:	185/55 R15
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,653.56	7,291.95	3,361.61	31.55
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,340.00	4,900.00	1,440.00	22.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,993.56	12,191.95	4,801.61	28.26
- Excess (S\$)	300.00	300.00	0.00	0.00
(S\$)	16,693.56	11,891.95	4,801.61	28.76
+ GST 7.00/7.00% (S\$)	1,168.55	832.44	336.11	28.76
Nett Amount (S\$)	17,862.11	12,724.39	5,137.72	28.76

INSPECTION

Date of Assignment: 19/10/2020
Date Inspected: 19/10/2020 Inspected At:

Cycle & Carriage Automotive Pte Ltd
(Pandan Gardens)
209 Pandan Gardens
Singapore 609339

Estimated Period of Repair: 8.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
2	1		*PANEL ASSY, FR END	Bent	1,055.00 FL	*1,055.00 FL
3	1		*PANEL, HEADLAMP SUPPORT, UPR	Bent	65.00 FL	*65.00 FL
4	1		*CONDENSER ASSY, A/C REFRIGE	Bent	758.00 FL	*758.00 FL
5	1		*PANEL, AIR GUIDE	Deformed	112.00 FL	*112.00 FL
6	1		*RADIATOR ASSY	Bent	967.00 FL	*967.00 FL
7	1		*TANK ASSY, RADIATOR COND	Not Necessary	42.00 FL	*- FL
8	1		*FAN, COOLING, LH	Cracked	77.00 FL	*77.00 FL
9	1		*SHROUD, COOLING FAN	Cracked	130.00 FL	*130.00 FL
10	1		*MOTOR, COOLING FAN	Not Necessary	479.00 FL	*- FL
11	1		*LLC 4L	Not Necessary	26.00 FL	*- FL
12	1		*PANEL, AIR GUIDE, RH	Not Necessary	11.00 FL	*- FL
13	1		*PANEL, AIR GUIDE, LH	Not Necessary	11.00 FL	*- FL
14	1		*HEADLAMP ASSY, LH	Cracked	660.00 FL	*660.00 FL
15	1		*HEADLAMP ASSY, RH	Cracked	660.00 FL	*660.00 FL
16	1		*LAMP ASSY, FOG, FR LH	Not Necessary	303.00 FL	*- FL
17	1		*LAMP ASSY, FOG, FR RH	Not Necessary	303.00 FL	*- FL
18	1		*HINGE, HOOD, LH	Bent	56.00 FL	*56.00 FL
19	1		*HINGE, HOOD, RH	Bent	56.00 FL	*56.00 FL
20	1		*HOOD	Bent	734.00 FL	*734.00 FL
21	1		*INSULATOR, HOOD	Deformed	177.00 FL	*177.00 FL
22	6		*CLIP, HOOD INSULATOR	Necessary	18.00 FL	*18.00 FL
23	1		*LATCH, HOOD	Bent	69.00 FL	*69.00 FL
24	1		*FENDER, FR LH	Bent	497.00 FL	*497.00 FL
25	1		*FENDER, FR RH	Bent	497.00 FL	*497.00 FL
26	2		*EMBLEM ECO	Necessary	34.00 FS	*34.00 FS
27	1		*PANEL ASSY, FR DOOR, RH	Bent	996.00 FL	*996.00 FL
28	1		*TAPE, FR DOOR SASH, RH	Necessary	29.00 FL	*29.00 FL
29	1		*GARNISH, FR PILLAR, LH	Not Necessary	30.00 FL	*- FL
30	1		*GARNISH, FR PILLAR, RH	Cracked	30.00 FL	*30.00 FL
31	1		*GRILLE, RADIATOR	Cracked	554.00 FL	*554.00 FL
32	1		*GRILLE, RADIATOR	Not Necessary	554.00 FL	*- FL
33	1		*BRACKET, FR BUMPER, LH	Not Necessary	13.00 FL	*- FL
34	1		*BRACKET, FR BUMPER, RH	Distorted	13.00 FL	*13.00 FL
35	1		*GRILLE, FR UNDER	Deformed	165.00 FL	*165.00 FL
36	1		*GARNISH, FR BUMPER, LH	Not Necessary	127.00 FL	*- FL
37	1		*GARNISH, FR BUMPER, RH	Not Necessary	127.00 FL	*- FL
38	1		*AIR DAM, SIDE, FR LH	Not Necessary	18.00 FL	*- FL
39	1		*AIR DAM, SIDE, FR RH	Not Necessary	18.00 FL	*- FL
40	1		*COVER, HEADLAMP SUPT PANEL	Deformed	62.00 FL	*62.00 FL
41	10		*CLIP, FR BUMPER	Necessary	40.00 FL	*40.00 FL
42	1		*COVER, FR BUMPER	Deformed	12.00 FL	*12.00 FL
43	1		*FACE, FR BUMPER	Deformed	703.00 FL	*703.00 FL
44	1		*BODY KIT ATTRAGE	Repair	1,643.00 FS	*- FS
45	1		*FRONT NUMBER PLATE WITH FRAME	Bent	50.00 FS	*50.00 FS
46	1		*DUCT, A/CLNR INTAKE	Not Necessary	131.00 FL	*- FL
47	1		*TANK, WINDSHIELD WASHER	Deformed	74.00 FL	*74.00 FL
48	1		*MARK, THREE-DIA	Necessary	69.00 FL	*69.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
				Sub Total (S\$)	13,305.00	9,439.00
				- List Item Discount on L Items 23.00/23.00% (S\$)	2,651.44	2,147.05
				Total Parts (S\$)	10,653.56	7,291.95

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REMOVE AND INSTALL RADIATOR AND A/CON CONDENSER TO FACILITATE REPAIR WORK	New	100.00	100.00
2	TOP UP AIR CON GAS AND CHECK A/CON SYSTEM	New	80.00	80.00
3	PAINT WORK SPRAY FRONT SUPPORT PANEL, FRONT BONNET, FRONT BUMPER, FRONT BODY KITS, RH FRONT FENDER, LH FRONT FENDER	New	2,800.00	2,450.00
4	RE-APPLY BODY KITS SEALANT	New	80.00	0.00
5	CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM	New	30.00	30.00
6	APPLY BODY SEALANT	New	120.00	80.00
7	REMOVE AND TRANSFER RH FRONT DOOR GLASS, TRIM AND OTHERS ATTACHMENT TO NEW DOOR PANEL	New	150.00	120.00
8	PERFORM RUST PREVENTION	New	80.00	40.00
9	APPLY LTA FOR APPLICATION BREAK SEAL AND RESEAL OPC FRONT NUMBER PLATE	New	80.00	80.00
10	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
11	RENEW ACCIDENT DAMAGED PARTS ON FRONT SUPPORT PANEL, FRONT BONNET, FRONT BUMPER, FRONT BODY KITS, RH FRONT FENDER, LH FRONT FENDER, RH FRONT DOOR, REPAIR LH FRONT DOOR, REPAIR FRONT BOTH CHASSIS	New	2,700.00	1,800.00
Gross Labour Cost (S\$)			6,340.00	4,900.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >