

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20011292/EGS3Q2

Date: 18/01/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100402835

Claimant
Vehicle No : SHD3044M **Insured Vehicle No :** SKR5093Z

Date of Loss: 18/10/2020 Nature of Claim: TP Claim No: 9341894136SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHD3044M**

Make & Model: HYUNDAI I40, 1.7 D CRDI F/L ABS AIRBAG 4DR (A) Engine No: D4FDDU395849

Reg. Date: 23/06/2016 (Man. Year: 2016) Chassis No: KMHLB41UMGU091494

Colour: Blue Odometer: 437836 km

Engine Capacity: 1685 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R14 Rear Tyre Size: 205/60 R14

Front Left Side: Michelin 4 mm Rear Left Side: Michelin 4 mm

Front Right Side: Michelin 4 mm Rear Right Side: Michelin 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,392.90	5,139.86	4,253.04	45.28
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,730.00	2,160.00	570.00	20.88
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,122.90	7,299.86	4,823.04	39.78
Approved Total (Overridden) (S\$)		5,850.00		
(S\$)	12,122.90	5,850.00	6,272.90	51.74
+ GST 7.00/7.00% (S\$)	848.60	409.50	439.10	51.74
Nett Amount (S\$)	12,971.50	6,259.50	6,712.00	51.74
+ Loss of Use (4.0 x S\$50.00/day) (S\$)		200.00		
+ Car Rental (4.0 x S\$110.67/day) (S\$)		442.68		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		6,904.18		
Global Sum Settlement (S\$)		6,900.00		

INSPECTION

Date of Assignment: 19/10/2020

Date Inspected: 19/10/2020 Inspected At: ComfortDelGro Engineering Pte Ltd (Loyang)

59 Loyang Drive
Singapore 508969

Estimated Period of Repair: 4.0 days

Adjuster: CHEN TSUE YEE

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Dented	2,174.90 FL	*2,174.90 FL
2	2		*BOOTLID HINGE (LH/RH)	Not Necessary	284.60 FL	*- FL
3	1		*BOOTLID LOCK UPPER	Bent	114.90 FL	*114.90 FL
4	1		*BOOTLID LOCK LOWER	Not Necessary	31.70 FL	*- FL
5	1		*BOOTLID HYUNDAI PLATE	Necessary	21.10 FL	*21.10 FL
6	1		*BOOTLID H EMBLEM	Necessary	28.70 FL	*28.70 FL
7	1		*BOOTLID CRDI PLATE	Necessary	27.90 FL	*27.90 FL
8	1		*BOOTLID I40 EMBLEM	Necessary	27.90 FL	*27.90 FL
9	2		*BOOTLID LAMP (LH/RH)	Not Necessary	1,131.20 FL	*- FL
10	1		*BOOTLID MOULDING	Not Necessary	85.00 FL	*- FL
11	1		*BOOTLID LOWER OUTER GARNISH	Not Necessary	227.90 FL	*- FL
12	1		*REAR BUMPER	Dented	1,106.00 FL	*1,106.00 FL
13	1		*REAR BUMPER REINFORCEMENT	Broken	428.40 FL	*428.40 FL
14	2		*REAR BUMPER STAY (LH/RH)	Not Necessary	160.60 FL	*- FL
15	10		*REAR BUMPER CLIP	Necessary	22.00 FL	*22.00 FL
16	2		*REAR BUMPER SIDE BRACKET (LH/RH)	Broken	71.20 FL	*71.20 FL
17	1		*REAR BUMPER SPONGE	Broken	119.50 FL	*119.50 FL
18	1		*REAR BUMPER UNDER COVER	Cut	228.00 FL	*228.00 FL
19	1		*REAR BUMPER REFLECTOR (LH/RH)	N/S Broken / O/S Not Necessary	64.00 FL	*32.00 FL
20	1		*TAIL LAMP (LH/RH)	N/S Broken / O/S Not Necessary	1,395.60 FL	*697.80 FL
21	2		*EXHAUST MUFFLER (LH/RH)	Not Necessary	1,935.40 FL	*- FL
22	1		*EXHAUST PIPE CENTRE	Not Necessary	730.10 FL	*- FL
23	1		*REAR PANEL	Dented	526.70 FL	*526.70 FL
24	1		*REAR PANEL GARNISH	Broken	57.70 FL	*57.70 FL
25	1		*REAR PANEL LOWER PANEL	Dented	495.50 FL	*495.50 FL
26	1		*BOOTLID COMFORTDELGRO	Necessary	30.00 FS	*30.00 FS
27	1		*BOOTLID 65521111	Necessary	30.00 FS	*30.00 FS
28	1		*REVERSE SENSOR	Broken	135.70 FS	*135.70 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	11,692.20	6,375.90
- List Item Discount on L Items 20.00/20.00% (\$\$)	2,299.30	1,236.04
Total Parts (\$\$)	9,392.90	5,139.86

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	1,200.00	1,120.00
2	SPRAY PAINTING CHARGE	New	1,000.00	800.00
3	WIRING CHARGE	New	40.00	30.00
4	TUFF KOTE	New	100.00	30.00
5	REMOVE/REFIX REVERSE SENSOR	New	120.00	30.00
6	REMOVE/REFIX EXHAUST PIPE	New	120.00	0.00
7	TOWING FEE- KING DOLLY	New	150.00	150.00
Gross Labour Cost (\$\$)			2,730.00	2,160.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >