COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd 59 Loyang Drive Singapore 508969

Our Ref : ______

Date : 1910 2000

Time of Fax:_____

a Fax

Your Insured: SKR 50937

Date of Acc : 18 10 2620

Attn: Motor Claims Department

Dear Sirs

Aig Asia

SURVEY OF CLIENT'S DAMAGED VEHICLE REG NO. SH D 3044W

Our client has engaged us to repair the above vehicle and submit claims against the other party/parties-involved in the accident __

In accordance to the motor claims framework, we hereby request your presence at 59 Loyang Drive, Singapore 508969 to survey our client's damaged vehicle.

Enclosed, please find:

- i) Our initial estimate of repairs of the damaged vehicle;
- ii) Accident report made by our client.

I would appreciate it if you could call us to arrange for the survey of the vehicle:-

Lim Kwok Eng
Jumani Bin Masudin
Lim Tien Siong
Tel: 6214 8316 or HP: 9824 0811
Tel: 6214 8315 or HP: 9635 5305
Tel: 6214 8398 or HP: 9635 8546

Chiang Liat Choon
Tel: 6214 8314 or HP: 9296 6006
Tel: 6214 8314 or HP: 9296 6006

Larry Ng Nyuk Phin
Tel: 6214 8315 or HP: 9230 2824

Fax no. 6546 8156

If we do not hear from you within the next 48 hours, we shall deem that you have waived your rights to survey our client's vehicle and we shall proceed to engage independent surveyor without further reference to you. We henceforth reserve our rights to claim for Loss of Use and Loss of Rental during any delayed period of this survey arrangement.

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a Motor Surveyor appointed by the Insurance company.

Thank you.

Yours faithfully

Lim Tien Siong

for Vice President Crash Repairs & Claims Recovery

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

19.10.2020 3P INSURANCE: AIG ASIA

SURVEYOR: MODEL: HYUNDAI 140

DATE:

VEH NO.: SHD3044M MVA: LIM T S

PART NO.	DESCRIPTION	QTY	LIST PRICE	REMARKS
- ACT NO.	Bootlid	_	LIGITATIOE	
		1 2	£140.20	\$2,174.90
	Bootlid Hinge (LH/RH)		\$142.30	284.60
	Bootlid Lock Upper			\$114.90
	Bootlid Lock Lower			\$31.70
	Bootlid Hyundai Plate			\$21.10
	Bootlid 'H' Emblem	1 1		\$28.70
	Bootlid CRDI Plate	1		\$27.90
	Bootlid I40 Emblem	1		\$27.90
	Bootlid Lamp (LH/RH)	2	\$565.60	\$1,131.20
	Bootlid Moulding	1		\$85.00
	Bootlid Lower Outer Garnish	1		\$227.90
	Rear Bumper	1		\$1,106.00
	Rear Bumper Reinforcement	1 1		\$428.40
	Rear Bumper Stay (LH/RH)	2	\$80.30	\$160.60
	Rear Bumper Clip (10 pcs)	10	\$2.20	\$22.00
	Rear Bumper Side Bracket (LH/RH)	2	\$35.60	\$71.20
	Rear Bumper Sponge	1		\$119.50
	Rear Bumper Under Cover	1		\$228.00
	Rear Bumper Reflector (LH/RH)	2	\$32.00	\$64.00
	Tail Lamp (LH/RH)	2	\$697.80	\$1,395.60
	Exhaust Muffler (LH/RH)	2	\$967.70	\$1,935.40
	Exhaust Pipe Centre	1		\$730.10
	Rear Panel	1		\$526.70
	Rear Panel Garnish	1		\$57.70
	Rear Panel Lower Panel	1		\$495.50
	SPARE PARTS SUB TOTAL		İ	\$11,496.50
	LESS 20%			\$2,299.30
	DISCOUNTED SPARE PARTS TOTAL			\$9,197.20

P1/2

PART NO.	DESCRIPTION	QTY	LIST PRICE	REMARKS
			SHA3044M	P2/2
E	Bootlid ComfortDelGro	1		\$30.00
E	Bootlid 65521111	1		\$30.00
F	Reverse Sensor	1		\$135.70
	S/NETT TOTAL			\$195.70
	SPARE PARTS & OTHERS TOTAL		Ī	\$9,392.90
P	anel Beating			\$1,200.00
s	pray Painting Charge			\$1,000.00
M	/iring Charge			\$40.00
Τ.	uff Kote			\$100.00
R	emove/Refix Reverse Sensor		ł	\$120.00
R	emove/Refix Exhaust Pipe			\$120.00
Т	owing Fee – King Dolly			\$150.00
	LABOUR TOTAL			\$2,730.00
	ESTIMATE TOTAL			\$12,122.90

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.