COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

P1/2

DATE:

19.10.2020

3P INSURANCE: AIG ASIA

MODEL:

HYUNDAI 140

SURVEYOR: _

MVA: LIMTS

VEH NO.:	SHD3044M	MVA:	LIMTS	
PART NO.	DESCRIPTION	QTY	LIST PRICE	REMARKS
200	Bootlid / 00	1		\$2,174.90
	Bootlid Hinge (LH/RH) X	2	\$142.30	284.60
	Bootlid Lock Upper / BT	1		\$114.90
	Bootlid Lock Lower X	1		\$31.70
	Bootlid Hyundai Plate / Mc	1		\$21.10
	Bootlid 'H' Emblem	. 1		\$28.70
	Bootlid CRDI Plate / //	. 1		\$27.90
3 1	Bootlid I40 Emblem / //(1		\$27.90
	Bootlid Lamp (LH/RH) (LH) X (RH) X	2	\$565.60	\$1,131.20
	Bootlid Moulding 1	1		\$85.00
	Bootlid Lower Outer Garnish ?	1		\$227.90
	Rear Bumper / III	1		\$1,106.00
	Rear Bumper Reinforcement	1		\$428.40
	Rear Bumper Stay (LH/RH)	2	\$80.30	\$160.60
	Rear Bumper Clip (10 pcs)	10	\$2.20	\$22.00
	Rear Bumper Side Bracket (LH/RH)	2	\$35.60	\$71.20
	Rear Bumper Sponge / BR	1		\$119.50
	Rear Bumper Under Cover / (기	1		\$228.00
	Rear Bumper Reflector (LH/RH) (LH) - (R4)	12	\$32.00	\$64.00
	Tail Lamp (LH/RH) CLH) > OR CRH) X	2,	\$697.80	\$1,395.60
		2	\$967.70	\$1,935.40
	Exhaust Muffler (LH/RH)	1		\$730.10
	Exhaust Pipe Centre X	1		\$526.70
	Rear Panel / III	1		\$57.70
	AY)			\$495.50
	Rear Panel Lower Panel $\qquad hilde{01}$	1		\$ 430.33
	SPARE PARTS SUB TOTA	4		\$11,496.50
	LESS 20°			\$2,299.30
	DISCOUNTED SPARE PARTS TOTA			\$9,197.20

PART NO.	DESCRIPTION	QTY	LIST PRICE	REMARKS
			SHA3044M	P2/2
				Lim Tien Sion
	Bootlid ComfortDelGro / M	1	1 4 4	\$30.00
	Bootlid 65521111 — M	1		\$30.00
	Reverse Sensor / DR	1 -	re de la	\$135.70
	S/NETT TOTAL			\$195.70
	SPARE PARTS & OTHERS TOTAL			\$9,392.90
	David Bastine	- 24	1120	\$1,200.00
	Panel Beating		1120 800	\$1,000.00
	Spray Painting Charge Wiring Charge		000	\$40.00
	Tuff Kote		33	\$100.00
	Remove/Refix Reverse Sensor		3	J \$120.00
3 132 0 1 3	Remove/Refix Exhaust Pipe		7	\$120.00
	Towing Fee - King Dolly		•	\$150.00
	LABOUR TOTAL			\$2,730.00
	ESTIMATE TOTAL			\$12,122.90

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Stene (LKK) WL ML

19/10/20, 3.30 pm L/S

My AL SH 4 dys

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

IFORTDELGRO

ember of COMFORTDELGRO

ComfortDelGro Engineering Pte Ltd

205 Brappal Touris Surgapura \$79701

Mandrie 1 55 6283 5287 Farminish + 85 5287 9755

Work-shops
59 Logary Surgapura \$79499
38 536 blood Surgapura \$79499
38 506 blood Surgapura \$77477
45 Barde Surgapura \$77477
45 Barde Surgapura \$77477
45 Barde Surgapura \$77485 501 Farminish Surgapura \$7845 50

Date/Time 220 19 Gund Oncology \$77596

Date/Time 220 19 Gund Oncology \$77596

Date/Time 220 19 Gund Oncology \$77596

_{JC NO.:}305428776 Sales Order: JOB CARD ARC Repair TP(CLSO)1 eam: REGN NOHD3044M MILEAGE TOMER COMFORT TRANSPORTATION PTE LTD MAKE: HYUNDAI FUEL AS 7010045 £.....1/2 TOMER NG 83 SIN MING DRIVE MODEL I-40 18. 10. 2020 11:15 Singapore SINGAPORE 575717 65508755 YR OF MAN 06. 2016 TARGET DATE (R) (P) COMPLETION DATE/TIME. CHASSIS CONTEBA1UMGU091494 OUNT CARD NO.


JOB DESCRIPTION

Accident Date: 18.10.2020

WATURE: 3P 18.10.2020

3/NO

LABOR CODE



XED & PASSED OUT BY:			
SERVICE ADVISOR	3		CUSTOMER'S SIGNATURE
ledgement Slip	•	Exit Pass	
No.: SHD3044M	LIMTS	Vehicle No.: SHD3044M	
Service Advisor	Signature/Date	Name of Service Advisor	Date
urned to Service Reception upon collection		To be kept by Security Guard	