

Surveyor : TAUFIKH LKK
 Claim : AIG OD
 DOA : 18.10.2020
 Emailed : 10.11.2020, 11am
 Date Survey : 19.10.2020

VEHICLE NO : SMT 7593 A
 MODEL : MIT ATTRAGE 1.2
 WIP : 58607

Material	:	\$	<u>4,309.81</u>
Labour	:	\$	<u>3,720.00</u>
Sub-Total	:	\$	<u>8,029.81</u>
	:		<u>-</u>
Less Excess	:	\$	<u>300.00</u>
Total	:	\$	<u>7,729.81</u>
GST 7%	:	\$	<u>541.09</u>
Grand Total	:	\$	<u>8,270.90</u>
Finalise By/Date	:		<u>LOI / 10/11/2020</u>

☒ REVERT BACK WITHIN 7 DAYS,
 OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

☐ REPAIR TOOK 0 WORKING DAYS + 0 Days (0) Weekends
 + 0 Days (0) Public Holiday
 TOTAL DAYS REPAIR TOOK = 0

☐ TP claim _____

☐ Claim GIA / LTA fee _____

☐ Claim Loss of ☐ Use / ☐ Rental

☐ Claim Medical Fee / Others _____

☐ Third Party Report - _____

PRO-FORMA INVOICE

Co Reg No : 197701469G

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892 19/10/2020	Cust No/Name	KCV15712/LEONG MUN EE, GENEVIEVE
	Reg No/Reg Date	SMT7593A / 16/07/2020
	Date In/Mileage	19/10/2020/ 1708
	Chassis/Package	MMBSTA13AKH003596 /DC17PT
	Engine No	3A92UJC2069
	Make/Model	MIT/19MY ATTRAGE 1.2 CVT
	Colour/Trim	T06 MEDIUM BLUE MIC/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	17/11/2020/ 11:06	BLK	260 / AiTing	58607			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE DAMAGED PARTS, REPLACE BONNET, RH FRONT FENDER, FRONT BUMPER, FRONT H/LAMP SUPPORT PANEL, REPAIR LH FRONT FENDER, AND ALL OTHER AFFECTED AREAS, ADJUST AND ALIGN BODY GAPS ALIGNMENT TO THE SAME								✓ 1350.00
E PNT98000 RESPRAY ON FRONT BUMPER, BONNET, RH FRONT DOOR, BOTH FRONT FENDER, FRONT H/LAMP SUPPORT PANEL, AND ALL OTHER AFFECTED AREAS TO THE SAME								✓ 1750.00
A 54900099 CHECK WIRING & CHASSIS ELECTRICAL SYSTEM								✓ 30.00
A 10028901 CONDUCT DIAGNOSTIC CHECK USING MUT TESTER AND CLEAR TROUBLE CODE								✓ 120.00
M SUNDRY APPLY ZERTONA COATING ON AFFECTED AREAS								✓ 400.00
M SUNDRY SUNDRIES								✓ 20.00
S SPECIALISTJOB SUPPLY & REPLACE FRONT NUMBER PLATE WITH FRAME								✓ 50.00
X EXC INSURANCE EXCESS								-300.00
X	HEADLAMP ASSY,RH				1.00	✓ 660.00	23.00	508.20
X	LAMP ASSY,FOG,FR RH				1.00	✓ 303.00	23.00	233.31
X	FACE,FR BUMPER				1.00	✓ 703.00	23.00	541.31
X	COVER,HEADLAMP SUPT PANEL				1.00	✓ 62.00	23.00	47.74
X	GARNISH,FR BUMPER,RH				1.00	✓ 127.00	23.00	97.79
X	GRILLE,FR UNDER				1.00	✓ 165.00	23.00	127.05
X	BRACKET,FR BUMPER,RH				1.00	✓ 13.00	23.00	10.01
X	GRILLE,RADIATOR				1.00	✓ 554.00	23.00	426.58
X	HOOD				1.00	✓ 734.00	23.00	565.18
X	HINGE,HOOD,LH				1.00	✓ 56.00	23.00	43.12
X	HINGE,HOOD,RH				1.00	✓ 56.00	23.00	43.12
X	FENDER,FR RH				1.00	✓ 497.00	23.00	382.69
X	PANEL,HEADLAMP SUPPORT,UPR				1.00	✓ 65.00	23.00	50.05
X	PANEL ASSY,FR END				1.00	✓ 1055.00	23.00	812.35



Exceptional Journeys

INSURANCE CO. : **AIG**

Supplementary Parts For Registration No.: **SMT 7593 A**

<u>Materials</u>		<u>Cost (\$)</u>
1	Garnish, Fr deck	178.00
2	Motor, windshield washer	30.00
3	Tank, windshield washer	74.00
4	clip (x4)	12.00
5	Cover, Fr bumper	12.00
6	Emblem Eco (x2)	34.00
7	Mark, Three-Dia	69.00
8	Rivet, Fr bumper (x6)	30.00
Total		439.00
Less 23% discount		100.97
Total after discount		338.03
7% GST		23.66
Grand total		<u>\$ 361.69</u>

Thank You.

Yours faithfully

LOI AI TING
SENIOR OFFICER - ADMIN
MITSUBISHI SERVICE CENTRE
DID : 6568 4556 / 6568 4501
FAX : 6567 5258 / 6565 1240

SMT 7593A

WIP#: 58607

(ADDITIONAL PARTS CHANGE)

Signature

S/NO	PARTS NAME	? / SUPP	CSA SIGN	PHOTO TAKEN	REMARKS
1	Panel Headlamp Support UPR	? / SUPP			
2	Panel Assy Front End	? / SUPP			
3	Cowl Top Cover	? / SUPP			
4	Clip Cowl Top	? / SUPP			
5	Washer Tank	? / SUPP			
6	Washer Motor	? / SUPP			
7	Tow cover frp (Missing)	? / SUPP			
8	Logo Three Diamond	? / SUPP			
9	Emblem (ECO) 2x	? / SUPP			
10	Rivent Air Dam	? / SUPP			
11		? / SUPP			
12		? / SUPP			
13		? / SUPP			
14		? / SUPP			
15		? / SUPP			
16		? / SUPP			
17		? / SUPP			
18		? / SUPP			
19		? / SUPP			
20		? / SUPP			

	DATE	TAKEN BY
PHOTO BEFORE PAINT		
PHOTO AFTER PAINT		
PHOTO OF MOUNT TO CELLLETE BENCH		
REMOVE AND INSTALL ENGINE		
REMOVE AND INSTALL DASHBAORD		
REMOVE & INSTALL FUEL TANK		
PHOTO UNDERCARRIAGE PARTS		

MODEL: Atfrage

SURVEYOR: Wk - Tausikh

SMT 7593A

After using MUT-3x unit to Base all 3x Band

All DTCs

2020.10.26

Job Done

Setting	
Item	Information
M.U.T.-3 Version	SEW20011-00
V.C.I. Version	B177
Vehicle Information	A13A 2019MY

All DTCs

2020.10.26

	System Name	SCC or DVC or Diagnostic database ID	Diagnostic trouble code(s)	Name		Malfunction Condition	
	MPI/GDI/DIESEL	KOSS_99880010		No DTCs			
	AT/CVT/A-MT/TC-SST	KOSS_99880010		No DTCs			
	4WS/Electric Power Steering	KOSS_99880010		No DTCs			
	ABS/ASC/ASTC/WSS	KOSS_99880010		No DTCs			
	SRS-AIR BAG	KOSS_99880010		No DTCs			
	Air Conditioner	KOSS_99880010		No DTCs			
	ETACS	KOSS_99880010		No DTCs			
	Meter	KOSS_99880010		No DTCs			
	Steering Angle Sensor	KOSS_99880010		Non-target System			
	KOS/OSS/IMMO/Keyless (with KOS)	KOSS_99880010		No DTCs			