

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG20011296/T1SD3E2

Date: 30/11/2020

REFERENCE

Insured/Claimant: LEONG MUN EE, GENEVIEVE

Policy No: 2070106266

Date of Loss: 18/10/2020

Nature of Claim: OD

Claim No: 8238512670SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMT7593A**

Make & Model: MITSUBISHI ATTRAGE, 1.2 CVT (A)

Engine No: 3A92UJC2069

Reg. Date: 16/07/2020 (Man. Year: 2019)

Chassis No: MMBSTA13AKH003596

Colour: Blue

Odometer: 1708 km

Engine Capacity: 1193 cc

Market Value/New Car Price: S\$63,000.00

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/55 R15

Rear Tyre Size: 185/55 R15

Front Left Side: Bridgestone 6 mm

Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm

Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,391.56	4,379.81	1,011.75	18.77
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,960.00	3,650.00	3,310.00	47.56
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,351.56	8,029.81	4,321.75	34.99
- Excess (S\$)	300.00	300.00	0.00	0.00
(S\$)	12,051.56	7,729.81	4,321.75	35.86
+ GST 7.00/7.00% (S\$)	843.61	541.09	302.52	35.86
Nett Amount (S\$)	12,895.17	8,270.90	4,624.27	35.86

INSPECTION

Date of Assignment: 19/10/2020

Date Inspected: 19/10/2020 Inspected At:

Cycle & Carriage Automotive Pte Ltd
(Pandan Gardens)
209 Pandan Gardens
Singapore 609339

Estimated Period of Repair: 6.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HEADLAMP ASSY, LH	Not Necessary	660.00 FL	*- FL
2	1		*HEADLAMP ASSY, RH	Cracked	660.00 FL	*660.00 FL
3	1		*LAMP ASSY, FOG, FR LH	Cut	303.00 FL	*303.00 FL
4	1		*FACE, FR BUMPER	Deformed	703.00 FL	*703.00 FL
5	1		*COVER, HEADLAMP SUPT PANEL	Cracked	62.00 FL	*62.00 FL
6	1		*AIR DAM, SIDE, FR RH	Not Necessary	18.00 FL	*- FL
7	1		*AIR DAM, SIDE, FR LH	Not Necessary	18.00 FL	*- FL
8	1		*GARNISH, FR BUMPER, RH	Missing	127.00 FL	*127.00 FL
9	1		*GRILLE, FR UNDER	Deformed	165.00 FL	*165.00 FL
10	1		*BRACKET, FR BUMPER, LH	Not Necessary	13.00 FL	*- FL
11	1		*BRACKET, FR BUMPER, RH	Deformed	13.00 FL	*13.00 FL
12	1		*GRILLE, RADIATOR	Cut	554.00 FL	*554.00 FL
13	1		*HOOD	Bent	734.00 FL	*734.00 FL
14	1		*HINGE, HOOD, LH	Bent	56.00 FL	*56.00 FL
15	1		*HINGE, HOOD, RH	Bent	56.00 FL	*56.00 FL
16	1		*LATCH, HOOD	Not Necessary	69.00 FL	*- FL
17	1		*FENDER, FR LH	Repair	497.00 FL	*- FL
18	1		*FENDER, FR RH	Bent	497.00 FL	*497.00 FL
19	1		*PANEL, HEADLAMP SUPPORT, UPR	Bent	65.00 FL	*65.00 FL
20	1		*PANEL ASSY, FR END	Bent	1,055.00 FL	*1,055.00 FL
21	1		*SHIELD, FR WHEELHOUSE, RH	Deformed	98.00 FL	*98.00 FL
22	1		*FRONT NUMBER PLATE WITH FRAME	Cut	50.00 FS	*50.00 FS
23	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
24	1		*GARNISH, FR DECK	Deformed	178.00 FL	*178.00 FL
25	1		*MOTOR, WINDSHIELD WASHER	Deformed	30.00 FL	*30.00 FL
26	1		*TANK, WINDSHIELD WASHER	Deformed	74.00 FL	*74.00 FL
27	4		*CLIP	Necessary	12.00 FL	*12.00 FL
28	1		*COVER, FR BUMPER	Deformed	12.00 FL	*12.00 FL
29	1		*MARK, THREE-DIA	Necessary	69.00 FL	*69.00 FL
30	6		*RIVET, FR BUMPER	Necessary	30.00 FL	*30.00 FL
31	2		*EMBLEM	Necessary	34.00 FS	*34.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,962.00	5,657.00
- List Item Discount on L Items 23.00/23.00% (\$\$)	1,570.44	1,277.19
Total Parts (\$\$)	5,391.56	4,379.81

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REPL FRT BUMPER, BONNET, BOTH FRT FENDER, SUPPORT & AFFECTED AREA TO REPAIR ON FRT RH CHASSIS.	New	3,150.00	1,350.00
2	PAINT WORK FRT BUMPER, BONNET, SUPPORT, FRT RH DOOR, FRT RH CHASSIS & BOTH FRT FENDER.	New	2,450.00	1,750.00
3	TO REMOVE & INSTALL RADIATOR, CONDENSER FOR FACILITATE REPAIR.	New	120.00	0.00
4	TO TOP UP AIRCON GAS.	New	80.00	0.00
5	TO REMOVE & INSTALL ENGINE FOR FACILITATE REPAIR.	New	450.00	0.00
6	PERFORM RUST PREVENTION.	New	80.00	0.00
7	TO APPLY SEALANT ON AFFECTED AREA.	New	80.00	0.00
8	CHECK WIRING & CHASSIS ELECTRICAL SYSTEM.	New	30.00	30.00
9	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST.	New	120.00	120.00
10	TO APPLY ZERTONA COATING ON AFFECTED AREA.	New	400.00	400.00
Gross Labour Cost (S\$)			6,960.00	3,650.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >