Adjuster Report Page 1 of 3

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/TMI20011299/AQD3Q2

Date: 07/01/2021

REFERENCE

Handling Insurer: Tokio Marine Insurance Singapore Ltd Policy No: ML000125

Claimant St. 72637Y Insured Vehicle No: St. P7463A

Vehicle No : SLZ2637X Insured Vehicle No : SLP7463A

Date of Loss: 18/10/2020 Nature of Claim: TP Claim No: M2005131

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLZ2637X

Make & Model: HYUNDAI ELANTRA, 1.6 (A) Engine No: G4FGJU163305

Reg. Date: 27/04/2018 (Man. Year: 2018) Chassis No: KMHD841CMJU660826

Colour: Blue Odometer: 39687 km

Engine Capacity: 1591 cc
Market Value/New Car
N/A

Price:
Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
Front Left Side: Nexen 6 mm Rear Left Side: Nexen 6 mm
Front Right Side: Nexen 6 mm
Rear Right Side: Nexen 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,429.40	3,688.28	1,741.12	32.07
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,220.00	1,110.00	2,110.00	65.53
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,649.40	4,798.28	3,851.12	44.52
Approved Total (Overridden) (S\$)		3,800.00		
Nett Amount (S\$)	8,649.40	3,800.00	4,849.40	56.07

INSPECTION

Date of Assignment: 19/10/2020

Date Inspected: 19/10/2020 Inspected At: Advance Auto Garage

10 Kaki Bukit Road 2, #01-21 First

East Centre Singapore 417868

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 2 of 3

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 07 Jan 2021)

Parts: 143 HYUNDAI ELANTRA 1.6 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLZ2637X)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		*REAR BUMPER	Deformed	465.00 FL	-	*465.00 FL
2	2		*REAR BUMPER SIDE HOLDER	Necessary	70.80 FL	-	*70.80 FL
3	1		*REAR BUMPER REFLECTOR	O/s Cracked	225.20 FL	-	*112.60 FL
4	1		*REAR BUMPER LOWER GARNISH	Deformed	386.50 FL	-	*386.50 FL
5	1		*REAR BUMPER REINFORCEMENT	Bent	295.90 FL	-	*295.90 FL
6	2		*REAR BUMPER REINFORCEMENT TOP BRACKET	Not Necessary	36.00 FL	-	*-FL
7	1		*REAR END PANEL	Repair	454.60 FL	-	*- FL
8	1		*REAR END PANEL TOP GARNISH	Deformed	148.50 FL	-	*148.50 FL
9	1		*TAILLAMP	O/s Cracked	1,752.00 FL	-	*876.00 FL
10	1		*BOOTLID	Dented	1,782.00 FL	-	*1,782.00 FL
11	1		*BOOTLID LOCK	Not Necessary	116.20 FL	-	*- FL
12	1		*BOOTLID WEATHERSTRIPE	Not Necessary	151.00 FL	-	*- FL
13	1		*HYUNDAI LOGO	Necessary	45.90 FL	-	*45.90 FL
14	1		*ELANTRA EMBLEM	Necessary	43.90 FL	-	*43.90 FL
15	1		*S EMBLEM	Necessary	39.50 FL	-	*39.50 FL
16	1		*REAR NUMBER PLATE	Not Necessary	30.00 FS	-	*- FS
17	1		*REAR NUMBER PLATE WEEKEND CAR SEAL	Necessary	25.00 FS	-	*25.00 FS
18	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	-	*30.00 FS
19	1		*SET REVERSE SENSOR	Damaged	280.00 FS	-	*200.00 FS
20	1		*SET REAR END PANEL TOP GARNISH CLIPS	Necessary	20.00 FS	-	*20.00 FS
21	1		*SET REAR END PANEL SEALANT	Not Necessary	80.00 FS	-	*- FS
22	1		*REAR BUMPER REINFORCEMENT ANTENNA SENSOR	Not Necessary	167.50 FL	-	*-FL
F=Fra	nchise	part. S=	SpcNett. L=ListItemDisc.	-			
				Sub Total (S\$)		4,541.60	
	- List Item Discount on L Items 20.00/20.00% (S\$) 1,236.10 853.32						
Total Parts (S\$)5,429.40						3,688.28	

Report was unsubmitted during this print-out.

Adjuster Report Page 3 of 3

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount					
Lab	<u>Labour Items</u>								
1	PANEL BEATING, REMOVE AND REFIT PARTS	New	1,200.00	400.00					
2	SPRAY PAINTING TO AFFECTED AREA	New	1,200.00	400.00					
3	WIRING CHECK	New	50.00	30.00					
4	TO APPLY TUFF COAT	New	150.00	0.00					
5	TO REMOVE REVERSE SENSOR	New	100.00	50.00					
6	TO REMOVE AND REFIT REAR CAMERA	New	100.00	50.00					
7	TO REMOVE AND REFIT UPHOLSTERY	New	150.00	40.00					
8	TO TRANSFER BOOTLID FITTINGS	New	150.00	60.00					
9	TO SEND VEHICLE FOR LTA INSPECTION (WEEKEND CAR SEAL)	New	120.00	80.00					
	Gross Labour Cost (S\$)		3,220.00	1,110.00					
	Report was unsubmitted during this print-out.								

< END OF ESTIMATES >