

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:**

CC3/III20011305/QPA3Q2

Date:

17/05/2021

REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No:

D20MPC0003566

Claimant Vehicle No : GBF9635D**Insured Vehicle No :**

SGH5520H

Date of Loss: 16/10/2020

Nature of Claim:

TP

Claim No:

MPC2020D0002107

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **GBF9635D**

Make & Model: TOYOTA HIACE, 3.0 D TURBO 5 DR (M)

Engine No: 1KD2684425

Reg. Date: 03/05/2017 (Man. Year: 2016)

Chassis No: JTFHT02P000215907

Colour: White

Odometer: 0 km

Engine Capacity: 2982 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15

Rear Tyre Size: 195 R15

Front Left Side: LINAM 6 mm

Rear Left Side: LINAM 6 mm

Front Right Side: LINAM 6 mm

Rear Right Side: LINAM 6 mm

*The above values represent the remaining tyre treads depth***COST OF CLAIMS**

	Repairer's	Adjuster's	Difference	Diff %
Parts	9,698.17	3,311.87	6,386.30	65.85
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,260.00	1,600.00	1,660.00	50.92
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,958.17	4,911.87	8,046.30	62.09
Approved Total (Overridden) (S\$)		3,900.00		

(S\$)	12,958.17	3,900.00	9,058.17	69.90
+ GST 7.00/7.00% (S\$)	907.07	273.00	634.07	69.90
Nett Amount (S\$)	13,865.24	4,173.00	9,692.24	69.90
+ Loss of Use (4.0 x S\$100.00/day) (S\$)		400.00		
+ Doc/Search Fee (S\$)		7.49		
Nett Liability (S\$)		4,580.49		

INSPECTION

Date of Assignment: 19/10/2020

Date Inspected: 22/10/2020

Estimated Period of Repair: 4.0 days

Inspected At:

My Car Consultant Pte Ltd (Ubi)
 53 Ubi Ave 1, #01-33, Paya Ubi Industrial Park
 Singapore 408934

Adjuster: OI SUN PIN**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 07 Apr 2021)
Parts:	213	TOYOTA HIACE 3.0 D TURBO 5 DR (M) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBF9635D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	2,035.20 FL	*1,755.30 FL
2	1		*TAILGATE LOCK	Jammed	287.10 FL	*287.10 FL
3	1		*TAILGATE WEATHERSTRIP	Cut	448.00 FL	*159.00 FL
4	1		*TAILGATE OUTER GARNISH	Serviceable	448.60 FL	*- FL
5	1		*TAILGATE LOGO	Serviceable	45.00 FL	*- FL
6	1		*TAILGATE WINDSCREEN MOULDING	Necessary	157.00 FL	*157.00 FL
7	1		*TAILAMP	O/S Cracked	778.80 FL	*389.40 FL
8	1		*TAILAMP LOWER GARNISH	O/S Deformed	257.40 FL	*128.70 FL
9	1		*REAR BUMPER	Crumpled	651.00 FL	*590.00 FL
10	2		*REAR BUMPER SIDE RETAINER	Necessary	96.00 FL	*96.00 FL
11	2		*REAR BUMPER BRACKET	Serviceable	88.00 FL	*- FL
12	1		*REAR END PANEL OUTER	Repair	412.00 FL	*- FL
13	1		*REAR END PANEL INNER	Repair	1,104.70 FL	*- FL
14	1		*REAR FLOOR PANEL	Repair	1,940.50 FL	*- FL
15	1		*REAR SPARE TYRE BRACKET	Serviceable	312.00 FL	*- FL
16	1		*REAR EXHAUST PIPE	Serviceable	589.60 FL	*- FL
17	1		*SET REAR REVERSE SENSOR	Shorted	250.00 FS	*200.00 FS
18	1		*REAR FLOOR PANEL ALUMINIUM PLATE	Serviceable	800.00 FS	*- FS
19	1		*SET TAILGATE COMPANY STICKER	Necessary	500.00 FS	*180.00 FS
20	1		*TAILGATE STICKER 70KM	Necessary	20.00 FS	*20.00 FS
21	1		*TAILGATE ALUMINIUM TRIM	Dented	400.00 FS	*180.00 FS
22	1		*TAILGATE WINDSCREEN SEALANT	Necessary	80.00 FS	*30.00 FS
23	1		*SET REAR BUMPER CLIP	Necessary	80.00 FS	*30.00 FS
24	1		*SET REAR END PANEL GARNISH CLIP	Serviceable	30.00 FS	*- FS
25	1		*FLOOR PANEL SEALANT	Serviceable	50.00 FS	*- FS
26	1		*END PANEL SEALANT	Serviceable	50.00 FS	*- FS
27	1		*MISCELLANEOUS	Serviceable	200.00 FS	*- FS

Report was unsubmitted during this print-out.

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK ELECTRICAL WIRING	New	80.00	30.00
2	TO REMOVE AND REFIT REVERSE SENSOR	New	150.00	30.00
3	REMOVE AND REFIX TAILGATE MECHANISM	New	120.00	60.00
4	REMOVE AND REFIX EXHAUST SYSTEM	New	200.00	0.00
5	CHECK AND TEST FOR WATER LEAKAGE	New	50.00	0.00
6	REMOVE AND REFIX REAR WINDSCREEN GLASS	New	120.00	120.00
7	REMOVE AND REFIX FLOOR PANEL ALUMINIUM	New	120.00	0.00
8	TO RESPRAY UNDERCOATING	New	100.00	30.00
9	APPLY ANTI RUST ON AFFECTED AREAS	New	120.00	30.00
10	SPRAY PAINTING ON AFFECTED AREAS	New	1,000.00	600.00
11	PANEL BEATING ON AFFECTED AREAS	New	1,200.00	700.00
Gross Labour Cost (S\$)			3,260.00	1,600.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >