

ASS. REC. BY:

Steve

REF:

CS3/ASM20011319/ESF3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD ☒ TP ☒ WS ☒ IP RES ☒ OD RES ☒ EVA ☒ INV ☒ MY

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Cum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No:

SKO 4573K

Yr Regn: 1/12/11

Type: ☒ Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make:

Mercedes Benz C180

c.c 1597

Colour:

Silver

A/C: Insured / Std / NI /

Sp. Reading

147994

T/Radio: Insured / Std / NI /

Eng/No:

C/No:

W 002940452 A 629786

Gen. Cond: Good / ☒ Fair / ☐ Poor / ☐ BurntSteering: Inorder / ☒ Jammed / ☐ Leaked / ☐ Burnt orBrakes: Inorder / ☒ Jammed / ☐ Leaked / ☐ Burnt orModl: Nil / ☒ S/Rm / ☐ STD A/Rm or

Tyre Size:

F:

915/50R16

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / ☒ MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

5

mm

R/Bal.

5

L/Bal.

5

mm

L/Bal.

5

D.O.A.

17/12/20

D.O.I.

29/12/20

Survey held at

9.20am

Des. of Damages: Frt / ☒ Rear / ☐ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

MV-30K

Repair large TK-SK
: 5 hrs approx

Date/Time, File Pass to?

21/10/2020

TYPIST

Date/Time, File Return to?

☐

: Prelim. Report

☒

: Final Report

Days Of Repair: 5

Resurvey No. of Trip: -

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Insp (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

\$ + RS, SI

Photos

Others

TOTAL

Pop. Formed:

PRS

Lump Sum / L.B.I. /