

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20011321/ABA3Q2

Date: 09/02/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800033993

Claimant
Vehicle No : SKE4321R **Insured Vehicle No :** SLX7340D

Date of Loss: 15/10/2020 Nature of Claim: TP Claim No: 7765173391SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKE4321R**
 Make & Model: HYUNDAI ELANTRA, 1.6 ABS D/AB 2WD 4DR (A) Engine No: G4FGCU464899
 Reg. Date: 01/03/2012 (Man. Year: 2012) Chassis No: KMHDH41CMCU421170
 Colour: White Odometer: 231604 km
 Engine Capacity: 1591 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
 Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
 Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,935.70	5,344.16	6,591.54	55.23
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,480.00	2,790.00	2,690.00	49.09
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,415.70	8,134.16	9,281.54	53.29
Approved Total (Overridden) (S\$)		6,500.00		
Nett Amount (S\$)	17,415.70	6,500.00	10,915.70	62.68
+ Loss of Use (11.0 x S\$60.00/day) (S\$)		660.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		7,162.00		
Global Sum Settlement (S\$)		7,150.00		

INSPECTION

Date of Assignment: 16/10/2020

Date Inspected: 16/10/2020 Inspected At:

CN MOTORS PTE LTD
 1 Kaki Bukit Ave 6 Blk C #01-41
 Autobay
 Singapore 417883

Estimated Period of Repair: 9.0 days

Adjuster: ADRIAN LING**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Distorted	1,188.70 F	*1,188.70 FL
2	2		*REAR BOOT LID HINGE	Bent	168.00 F	*168.00 FL
3	1		*REAR BOOT LID EMBLEM LOGO	Necessary	38.00 F	*38.00 FL
4	1		*REAR BOOT LID ELANTRA LOGO	Necessary	40.00 F	*40.00 FL
5	1		*REAR BOOT LID ELITE LOGO	Necessary	41.90 F	*41.90 FL
6	1		*REAR BOOT LID SIDE REFLECTOR	N/S Cracked	597.00 F	*298.50 FL
7	1		*REAR BOOT LID NUMBER PLATE	Cut	50.00 F	*50.00 FL
8	1		*REAR BOOT LID INNER LOCK	Jammed	125.00 F	*125.00 FL
9	1		*REAR BOOT LID WEATHERSTRIP	Cut	115.80 F	*115.80 FL
10	1		*REAR BOOT LID INNER TRIM BOARD	Crumpled	285.00 F	*285.00 FL
11	8		*REAR BOOT LID INNER TRIM BOARD CLIP	Necessary	52.00 F	*30.00 FL
12	1		*REAR BOOT LID REVERSE CAMERA	Not Necessary	680.00 FS	*- FS
13	1		*REAR WINDSCREEN SEAL	Not Necessary	105.00 F	*- FL
14	2		*REAR TAIL LAMP	N/S Cracked / O/S Cut	709.60 F	*709.60 FL
15	4		*REAR TAIL LAMP CLIP	Necessary	32.00 F	*32.00 FL
16	1		*REAR TAIL LAMP PANEL	N/S Buckled	1,112.40 F	*145.00 FL
17	1		*REAR BUMPER	Distorted	454.80 F	*454.80 FL
18	8		*REAR BUMPER CLIP	Necessary	52.00 F	*30.00 FL
19	2		*REAR BUMPER SIDE RETAINER	Necessary	76.00 F	*76.00 FL
20	1		*REAR BUMPER SIDE REFLECTOR	N/S Cracked	116.00 F	*58.00 FL
21	1		*REAR BUMPER LOWER	Not Necessary	282.00 F	*- FL
22	1		*REAR BUMPER INNER FOAM	Not Necessary	162.80 F	*- FL
23	1		*REAR BUMPER REINFORCEMENT	Cracked	328.00 F	*328.00 FL
24	2		*REAR BUMPER REINFORCEMENT BRACKET	Bent	189.20 F	*189.20 FL
25	5		*REAR BUMPER REINFORCEMENT TOP & LOWER BRACKET	Damaged	99.00 F	*99.00 FL
26	1		*REAR BUMPER REINFORCEMENT ANTENNA SENSOR	Cracked	285.40 F	*285.40 FL
27	1		*REAR BUMPER REVERSE SENSOR	Damaged	350.00 FS	*200.00 FS
28	1		*REAR END PANEL	Distorted	593.80 F	*593.80 FL
29	1		*REAR END PANEL TOP GARNISH	Deformed	105.00 F	*105.00 FL
30	1		*REAR L/H FENDER	Repair	1,560.80 F	*- FL
31	1		*REAR L/H FENDER COWLING	Torn	58.50 F	*58.50 FL
32	8		*REAR L/H FENDER COWLING CLIP	Necessary	52.00 F	*20.00 FL
33	1		*REAR FENDER INNER TRIM BOARD	N/S Torn	535.00 F	*267.50 FL
34	1		*REAR FENDER INNER TRIM BOARD CLIP (16 PCS)	Necessary	104.00 F	*30.00 FL
35	1		*REAR SPARE TYRE PANEL	Repair	486.00 F	*- FL
36	1		*REAR SPARE TYRE PANEL TOP COVER	Deformed	255.00 F	*255.00 FL
37	1		*REAR SPARE TYRE PANEL & END PANEL SEALANT	Necessary	450.00 FS	*250.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	11,935.70	6,567.70
- List Item Discount on L Items 0.00/20.00% (S\$)	0.00	1,223.54
Total Parts (S\$)	11,935.70	5,344.16

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE & REFIT CUSHION & TRIM BOARD	New	280.00	80.00
2	TO REMOVE & REFIT REVERSE CAMERA	New	180.00	50.00
3	TO REMOVE & REFIT REVERSE SENSOR	New	100.00	50.00
4	TO REMOVE & REFIT REAR WINDSCREEN	New	120.00	0.00
5	GUM	New	50.00	0.00
6	TO CHECK WIRING	New	100.00	30.00
7	TOWING FEE	New	150.00	0.00
8	TUFF KOTE	New	150.00	100.00
9	PANEL BEATING	New	2,200.00	1,200.00
10	SPRAY PAINTING	New	2,000.00	1,200.00
11	TO TRANSFER BOOTLID FITTINGS	New	150.00	80.00
Gross Labour Cost (\$\$)			5,480.00	2,790.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >