

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG20011344/QYF3E2

Date: 11/11/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900141037
Claimant Vehicle No : SLN7434U	Insured Vehicle No :	SKG2322R
Date of Loss: 16/10/2020	Nature of Claim: TP	Claim No: 7196211019SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLN7434U	Engine No:	LEB5937013
Make & Model:	HONDA VEZEL, 1.5 HYBRID X (A)	Chassis No:	RUJ31237000
Reg. Date:	16/05/2017 (Man. Year: 2016)	Odometer:	0 km
Colour:	Gold		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Toyo 6 mm	Rear Left Side:	Toyo 6 mm
Front Right Side:	Toyo 6 mm	Rear Right Side:	Toyo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	20/10/2020	
Date Inspected:	27/10/2020 Inspected At:	Elite Automotive Pte Ltd (HQ) 280 Woodlands Industrial Park E5, #01-17, Harvest@Woodlands Singapore 757322
Estimated Period of Repair:	5.0 days	

Adjuster: OI SUN PIN

Manager: YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Crumpled	0.00 F	*- F
2	1		*FRT BUMPER CLIPS	Necessary	0.00 F	*- F
3	1		*FRT BUMPER SIDE RETAINER	Broken	0.00 F	*- F
4	1		*FRT BUMPER REINFORCEMENT	Bent	0.00 F	*- F
5	1		*FRT LH BUMPER FOG LAMP COVER	Deformed	0.00 F	*- F
6	1		*FRT LH BUMPER FOG LAMP	Crumpled	0.00 F	*- F
7	1		*FRT GRILLE	Cracked	0.00 F	*- F
8	1		*FRT GRILLE EMBLEM	Necessary	0.00 F	*- F
9	1		*FRT GRILLE CHROME MOULDING	Cracked	0.00 F	*- F
10	1		*FRT SUPPORT PANEL	Bent	0.00 F	*- F
11	1		*FRT SUPPORT PANEL TOP GARNISH COVER	Crumpled	0.00 F	*- F
12	1		*FRT LH HEADLAMP ASSY	Cracked	0.00 F	*- F
13	1		*BONNET	Dented	0.00 F	*- F
14	1		*BONNET RUBBER	Necessary	0.00 F	*- F
15	1		*FRT LH FENDER	Dented	0.00 F	*- F
16	2		*FRONT HEADLAMP BRACKET RH / LH	Broken	0.00 F	*- F
17	1		*BONNET LOCK COVER	Crumpled	0.00 F	*- F
F=Franchise part.						
					Total Parts (S\$)	0.00 0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >