

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933







| NTUC INCOME INSURANCE CO-OPERATIVE LTD | | | Ref: | NS/INC20011348/Eqf3e2 | |
|--|---|-------------------------------------|---------------|--------------------------|--------------------|
| 73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556 | | | Date: | 09-11-2020 INC4 | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | | | |
| | Insured Veh. | SJW 8439B | Veh. lı | Veh. Inspected SHC 8162C | |
| | Policy No. | 5117282297 | Coverage (\$) | | 0.00 |
| | Claim No. | MT/1106950-002 | Exces | s (\$) | 0.00 |
| | Assign From | | Assig | n Date | 19/10/2020 |
| 2. Vehicle Particulars & Condition | | | | | |
| | Make & Model | HYUNDAI 140 | c.c | | 1685 |
| | Engine No. | HIDDEN | Year o | f Reg. | 2016 |
| | Chassis No. | KMHLB41UMGU089784 | Colou | • | BLUE |
| | Odometer | 595305 | Steering | | IN ORDER |
| | Brakes | IN ORDER | Modifi | cation | STANDARD ALLOY RIM |
| | General | FAIR | | | |
| 3. Conditions of Tyres | | | | | |
| | | Size | Make | | Balance |
| | R/H Front Tyre | 205/60 R16 | GOOD' | YEAR | 4 mm |
| | L/H Front Tyre | 205/60 R16 | GOOD' | YEAR | 4 mm |
| | R/H Rear Tyre | 205/60 R16 | GOOD' | YEAR | 4 mm |
| | L/H Rear Tyre | 205/60 R16 | GOOD' | YEAR | 4 mm |
| 4. Description of Damages | | | | | |
| | THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. | | | | |
| | DAMAGES SEE DETAILS. | | | | |
| 5. | General Information | | | | |
| | Accident Date 17/10/2020 Inspection Date 19/10/2020 | | | | 19/10/2020 |
| | Survey held at | t COMFORTDELGRO ENGINEERING PTE LTD | | | |
| | 59 LOYANG DRIVE SINGAPORE 508969 | | | | |
| 5a. | a. Remarks | | | | |
| | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | |
| 5b. Estimate Days of Repair | | | | | |
| | ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days | | | | |