

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20011350/KPA3Q2

Date: 18/02/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800079341

Claimant
Vehicle No : SLP2579H **Insured Vehicle No :** SMC5278M

Date of Loss: 17/10/2020 Nature of Claim: TP Claim No: 0838652310SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLP2579H	Engine No:	J35Z21952592
Make & Model:	HONDA ACCORD, 3.5 3.5 V6 (A)	Chassis No:	MRHCP36308P040043
Reg. Date:	12/08/2008 (Man. Year: 2008)	Odometer:	228312 km
Colour:	Metallic Black		
Engine Capacity:	3471 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R18	Rear Tyre Size:	225/45 R18
Front Left Side:	Continental 9 mm	Rear Left Side:	Continental 9 mm
Front Right Side:	Continental 9 mm	Rear Right Side:	Continental 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,956.24	1,126.76	829.48	42.40
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,750.00	495.00	1,255.00	71.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,706.24	1,621.76	2,084.48	56.24
Approved Total (Overridden) (S\$)		1,250.00		
(S\$)	3,706.24	1,250.00	2,456.24	66.27
+ GST 7.00/7.00% (S\$)	259.44	87.50	171.94	66.27
Nett Amount (S\$)	3,965.68	1,337.50	2,628.18	66.27
+ Loss of Use (2.0 x S\$100.00/day) (S\$)		200.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		1,539.50		

INSPECTION

Date of Assignment: 20/10/2020

Date Inspected: 26/10/2020 Inspected At:

Accord Auto Services Pte Ltd (HQ)
10 Ang Mo Kio Ind Park 2A #03-11,
AMK Auto Point
Singapore 568047

Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled	709.10 FL	*709.10 FL
2	2		*REAR BUMPER SIDE RETAINER	Distorted	35.00 FL	*35.00 FL
3	2		*REAR LAMP LOWER BRACKET LH & RH	Serviceable	16.00 FL	*- FL
4	2		*REAR LAMP LH & RH	Serviceable	591.60 FL	*- FL
5	1		*REAR END PANEL	Repair	287.80 FL	*- FL
6	1		*REAR END PANEL GARNISH	Serviceable	97.70 FL	*- FL
7	1		*REAR REINFORCEMENT BAR	Distorted	145.60 FL	*145.60 FL
8	1		*SET REAR REVERSE SENSOR	Shorted	380.00 FS	*380.00 FS
9	1		*SET REAR BUMPER CLIPS	Necessary	35.00 FS	*35.00 FS
10	1		*SET REAR END PANEL GARNISH CLIPS	Not Necessary	35.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	2,332.80	1,304.70
- List Item Discount on L Items 20.00/20.00% (\$)	376.56	177.94
Total Parts (\$)	1,956.24	1,126.76

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	SPRAY PAINTING ON ALL AFFECTED AREA	New	600.00	220.00
2	LABOUR REMOVE /REFIX ACCIDENT DAMAGES PARTS TO KNOCK ,JACK ,CUT WELD AND REALIGN ACCIDENT AFFECTED AREA	New	800.00	200.00
3	TO APPLY ANTI RUST TREATMENT	New	100.00	0.00
4	TO CHECK WIRING SYSTEM & LIGHT	New	100.00	15.00
5	TO REMOVE /REFIT /REPLACE REAR REVERSE SENSOR	New	150.00	60.00
Gross Labour Cost (\$\$)			1,750.00	495.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >